

ADEQ

ARKANSAS
Department of Environmental Quality

December 20, 2002

The Honorable Lynn Moore, Mayor
City Hall
114 W. South Street
Benton, AR 72015

SWD# 20461
To: _____

REC'D JUL 22 2003

Pmt # 0195-S
AFIN: 63-0063

RE: CSN 63-0063 Permit Nbr. 0195-S

Dear Mayor Moore:

On December 19, 2002, I performed a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Reg. 22, and the above referenced permit. A copy of the inspection report is enclosed for your review.

Refer to the report to note any allegations of deficiencies that require corrective action. Please send a written response to the corrective action taken. **Failure to respond to this letter in writing shall be construed as an admission of any allegations contained therein. Any items noted that are neglected and persistent may warrant enforcement action.**

If I can be any further assistance, feel free to contact me at (501) 682-0581 or at the address below.

Sincerely,



Kenneth Burks, Inspector
Solid Waste Division

cc: Central Files
Enforcement Branch Files, SW

Arkansas Department of Environmental Quality - Facility Evaluation

Name of Site: City of Benton	County: Saline	CSN # 63-0063	Permit # 195-S
Location: City Hall 222 West South St. Benton, AR 72015	Address of Permittee: City Hall 114 W. South St. Benton, AR 72015		
Telephone Number: (501) 776-5902	Licensed Operator & No:		Date: 12/19/02 Entry Time: 1010 Exit Time: 1230
Closed landfill classification: <input checked="" type="checkbox"/> CLASS 1 <input type="checkbox"/> CLASS 2 <input type="checkbox"/> CLASS 3 <input type="checkbox"/> CLASS 4			

OPERATIONAL STANDARDS

CATEGORY 1 VIOLATIONS

COMMENTS

- 1 2 4
 _____ Ditches maintained §22.1302(b)(1)
 _____ Settling on completed areas §22.1302(b)(1)

CATEGORY 2 VIOLATIONS

- 2 4 8
 _____ ☒ Cover vegetation maintained §22.1302(b)(1)
 _____ Preventing run-on and run-off from damaging final cover §22.1302(b)(1)

CATEGORY 3 VIOLATIONS

- 3 6 12
 _____ Erosion or cracking of soil §22.1302(b)(1)
 _____ Maintaining and operating gas monitoring system §22.1302(b)(4)
 _____ Ground water monitoring maintained §22.1302(b)(3)
 _____ Maintaining and operating leachate collection system §22.1302(b)(2)

TOTAL POINTS 8

Point Scale 0-3 (S) 4-5 (M) ≥ 6 (U)

RECORDS / OTHER CRITERIA / COMMENTS

Date of last waste accepted 10/08/93
 Date of last ground water monitoring report N/A §22.1302(b)(3)
 Date of last quarterly methane monitoring N/A §22.1302(b)(4)
 Date of Owner Closure Certification §22.1301 (l)
 Date of ADEQ Certification of Closure 2/16/00 §22.1302 (m)
 Date of leachate disposal N/A method location §22.1302(b)(2)
 Date of Annual Report N/A §22.423 / 22.522 / 22.619

No one present at time of inspection.
 Signature of Person Interviewed: _____

Signature of Inspector: Kenneth Buchs

Arkansas Department of Environmental Quality - Facility Evaluation Page 2

Name of Site: City of Benton Closed Landfill	Date: 12/20/02	County: Saline	CSN# 63-0063	Permit# 195-S
---	----------------	----------------	--------------	---------------

Category 2

Comments: Reg. §22.1302(b)(1) - Cover vegetation maintained: Landfill is in need of mowing. Excessive length of vegetation makes a proper inspection very difficult.

Category ____

Comments: Noted methane gas bubbling up through water puddles over the entire landfill area. No violation.

Category ____

Comments:

Category ____

Comments:

Category ____

Comments:

Category ____

Comments: