



STATE OF ARKANSAS
DEPARTMENT OF POLLUTION CONTROL & ECOLOGY

925 E. FAULKNER • P.O. BOX 1644
EL DORADO, ARKANSAS 71731-1644
501-862-5941
FAX 501-862-3509



Document ID # - 39405

November 7, 1996

Ms. Torii Wehling
El Dorado Chemical
P.O. Box 231
El Dorado, AR 71730

RE: Permit No. 0177-S
CSN No. 70-0040

Dear Ms. Wehling:

On November 6, 1996, I performed a routine inspection of your closed facility pursuant to the Arkansas Solid Waste Management Regulation 22 and the above referenced permit. A copy of the inspection report is attached.

If I can be of further assistance, feel free to contact me at 925 East Faulkner, El Dorado, AR 71730 or 501-862-5941.

Sincerely,

Jean Floyd, Inspector
Solid Waste Division

JF:kds

cc: Central Files
Heidi Love, Inspector Supervisor SWD
Mike Hood, SWD
Terry Sherwood, Director, RSWMB
Charles Skinner, Union County Judge

Arkansas Department of Pollution Control and Ecology — Landfill Closure Inspection

Name of Site Eldorado Chemical Union	County Union	CSN: 70-0040	Permit Nbr. 0177-5	Log Nbr
Landfill Location and Mailing Address 4500 N.W. Av. Eldorado, AK 71730		Date Last Waste Accepted: 3/30/95		
Contact Telephone Nbr: 863-1482		Date Initial Closure Approved (Two-year Closure Started): 2/28/96		
Landfill Classification: ☐ Class I ☐ Class II ☒ Class III ☐ Class IV	Soil Conditions: ☐ Wet ☒ Dry	Date of Inspection (YY MM DD) 9/6/11/06	Entry Time (24 HR) 1000	Exit Time (24 HR) 1115

Y N

- ☒ ☐ Closure plans are available at site _____
☒ ☐ Groundwater monitoring reports as required — Date: _____
☐ ☒ Fill material properly stockpiled XII B.7(e) **work complete**
☒ ☐ Sedimentation pond functional XII A.4 **N/A**
☒ ☐ Satisfactory site access control XII A.9(b) _____
☒ ☐ Surface water control functional _____
☒ ☐ Groundwater monitoring wells secured XII A.3 _____
☒ ☐ Leachate collection and disposal method adequate XII A.3 **N/A**
☐ ☒ Leachate or evidence of leachate XII B.5 _____
☐ ☒ Sediment accumulation on/off site XII A.4 _____
☐ ☒ Vegetative cover maintained XII B.7(g)(h) _____
☐ ☒ Erosion or cracking of soil controlled XII A.10(i) _____
☐ ☒ Standing or ponding water XII A.10(h) _____
☐ ☒ Settling on completed areas XII A.10(h) _____
☒ ☐ Borrow area closed properly **N/A**
☐ ☒ Exposed waste _____

Comments:

Site is well maintain

Person Interviewed: Toni Wehling	Signature of Inspector: James Hoxby Insp. SCD
--	---