

ARKANSAS DEPARTMENT OF POLLUTION CONTROL AND ECOLOGY
LANDFILL INSPECTION AND EVALUATION

Log # 00692

01. Name of site <i>Eldorado Chemical</i>	02. Location (Town, City) <i>Eldorado</i>	03. County <i>Union</i>	04. Permit No. <i>0177-S</i>
05. Operator <i>Eldorado Chemical</i>	06. Address <i>P.O. Box 231</i>	07. CSN # <i>70-0040</i>	
08. Permittee <i>Eldorado Chemical</i>	09. Address <i>Eldorado, AR 71730</i>	10. Percent of Landfill Area Utilized ☐ .01 Less than 25% ☒ .03 50% - 75% ☐ .02 25% - 50% ☐ .04 More than 75% ☐ .05 Not Determinable	
11. Landfill classification .01 () Class I .02 () Class II .03 ☒ Class III .04 () Class IV .05 () Unclassified			

12. CLASS I VIOLATIONS

- ☐ .01 Operation of an unpermitted facility
- ☐ .02 Evidence of open burning
- ☐ .03 Unsatisfactory daily cover
- ☐ .04 Unsatisfactory final cover
- ☐ .05 Improper drainage
- ☐ .06 Dumping waste into water
- ☐ .07 Leachate observed leaving the site
- ☐ .08 Leachate entering water course
- ☐ .09 Improper handling of special materials waste
- ☐ .10 Accepting unapproved waste(s)
- ☒ .11 Operation does not correspond with engineering design and plans *Plans require a 7' trench depth at SE end of Area I. See below*

13. CLASS II VIOLATIONS

- ☐ .01 Access not limited to operating hours
- ☐ .02 Unsatisfactory access roads
- ☐ .03 Waste not confined to manageable area
- ☐ .04 Unsatisfactory litter control
- ☐ .05 Improper spreading of waste
- ☐ .06 Improper compacting of waste
- ☒ .07 Unsatisfactory intermediate cover *Waste on E side of Area I needs cover, also*
Waste at S end of Area I needs cover
- ☐ .08 Evidence of leachate leaving the site
- ☐ .09 Improper fire protection, emergency communications
- ☐ .10 Evidence of vectors
- ☐ .11 No provisions for backup equipment

14. CLASS III VIOLATIONS

- ☐ .01 Inadequate information sign
- ☐ .02 Inadequate employee facilities
- ☐ .03 Inadequate records
- ☐ .04 Permit not posted at site
- ☐ .05 Engineering design and plans not available at site
- ☐ .06 Unapproved salvaging of wastes
- ☐ .07 Scavenging of wastes
- ☐ .08 Leachate observed on site
- ☐ .09 Dust or mud not properly controlled
- ☐ .10 Accepting waste from inadequately covered vehicles
- ☐ .11 Operator not certified

15. GENERAL COMMENTS

Copy of Plans for Area I attached.
12.11 Side slopes not constructed as per design
No test results on side slopes

16. Type of waste disposed:							
☐ .01 () Residential		☐ .02 () Commercial		☒ .03 () Industrial (process)			
☐ .04 () Demolition		☐ .05 () Special materials		☐ .06 () Other (identify under general comments)			
17. Person Interviewed <i>J. M. Wainwright</i>		19. Address <i>P.O. Box 231</i> <i>Eldorado, AR 71730</i>		month <i>21.01</i>	day <i>22</i>	year <i>90</i>	time <i>1:05</i>
18. Title		20. Phone <i>863-1402</i>					
22. Inspected by (signature) <i>[Signature]</i>				24. Reinspect prior to (date)			
23. Title <i>Inspector, SWD</i>				25. Weather conditions <i>Wet</i>			