

Log 1564

**ARKANSAS DEPARTMENT OF POLLUTION CONTROL AND ECOLOGY**  
**LANDFILL INSPECTION AND EVALUATION**

01. Name of site <u>Eldorado Chemical</u>	02. Location (Town, City) <u>Eldorado</u>	03. County <u>Union</u>	04. Permit No. <u>0177-S</u>
05. Operator <u>Eldorado Chemical</u>	06. Address <u>P.O. Box 231</u>	07. CSN # <u>700040</u>	
08. Permittee <u>Eldorado Chemical</u>	09. Address <u>Eldorado, AR 71730</u>	10. Percent of Landfill Area Utilized <input type="checkbox"/> .01 Less than 25% <input checked="" type="checkbox"/> .03 50% - 75% <input type="checkbox"/> .02 25% - 50% <input type="checkbox"/> .04 More than 75% <input type="checkbox"/> .05 Not Determinable	
11. Landfill classification .01 ( ) Class I .02 ( ) Class II .03 ( ) Class III .04 ( ) Class IV .05 ( ) Unclassified			

**12. CLASS I VIOLATIONS**

- ☐ .01 Operation of an unpermitted facility \_\_\_\_\_
- ☐ .02 Evidence of open burning \_\_\_\_\_
- ☐ .03 Unsatisfactory daily cover \_\_\_\_\_
- ☐ .04 Unsatisfactory final cover \_\_\_\_\_
- ☐ .05 Improper drainage \_\_\_\_\_
- ☐ .06 Dumping waste into water \_\_\_\_\_
- ☐ .07 Leachate observed leaving the site \_\_\_\_\_
- ☐ .08 Leachate entering water course \_\_\_\_\_
- ☐ .09 Improper handling of special materials waste \_\_\_\_\_
- ☐ .10 Accepting unapproved waste(s) \_\_\_\_\_
- ☐ .11 Operation does not correspond with engineering design and plans \_\_\_\_\_

**13. CLASS II VIOLATIONS**

- ☐ .01 Access not limited to operating hours \_\_\_\_\_
- ☐ .02 Unsatisfactory access roads \_\_\_\_\_
- ☐ .03 Waste not confined to manageable area \_\_\_\_\_
- ☒ .04 Unsatisfactory litter control Litter in area adjacent to working face in Area I.
- ☐ .05 Improper spreading of waste \_\_\_\_\_
- ☐ .06 Improper compacting of waste \_\_\_\_\_
- ☒ .07 Unsatisfactory intermediate cover Monthly cover is required
- ☐ .08 Evidence of leachate leaving the site \_\_\_\_\_
- ☐ .09 Improper fire protection, emergency communications \_\_\_\_\_
- ☐ .10 Evidence of vectors \_\_\_\_\_
- ☐ .11 No provisions for backup equipment \_\_\_\_\_

**14. CLASS III VIOLATIONS**

- ☐ .01 Inadequate information sign \_\_\_\_\_
- ☐ .02 Inadequate employee facilities \_\_\_\_\_
- ☐ .03 Inadequate records \_\_\_\_\_
- ☐ .04 Permit not posted at site \_\_\_\_\_
- ☐ .05 Engineering design and plans not available at site \_\_\_\_\_
- ☐ .06 Unapproved salvaging of wastes \_\_\_\_\_
- ☐ .07 Scavenging of wastes \_\_\_\_\_
- ☐ .08 Leachate observed on site \_\_\_\_\_
- ☐ .09 Dust or mud not properly controlled \_\_\_\_\_
- ☐ .10 Accepting waste from inadequately covered vehicles \_\_\_\_\_
- ☐ .11 Operator not certified \_\_\_\_\_

**15. GENERAL COMMENTS**

Litter was blown in area adjacent to working face in Area I.  
Area I requires monthly cover.

16. Type of waste disposed:				
.01 ( ) Residential	.02 ( ) Commercial	.03 (X) Industrial (process)		
.04 ( ) Demolition	.05 ( ) Special materials	.06 ( ) Other (identify under general comments)		
17. Person Interviewed <u>Jim Wainock</u>	19. Address <u>P.O. Box 231</u> <u>Eldorado, AR 71730</u>	month 21.01 <u>8</u>	day 21.02 <u>31</u>	year 21.03 <u>90</u>
18. Title <u>Environmental Coord.</u>	20. Phone <u>863-1400</u>	time 21.04 <u>1:35</u>		
22. Inspected by (signature) <u>Jan Lloyd</u>		24. Reinspect prior to (date) <u>10/8/90</u>		
23. Title <u>Solid Waste Inspector</u>		25. Weather conditions <u>Hot + Dry</u>		