≎EPA

Form Approved OMB No. 2040-0003 Approval Expires 7-31-85

							U	JNITEI	D STATE					ECTIO	N AGE	NCY								Approval Expires 7 51 65						
	NPDES Compliance Inspection Report																													
	Section A: National Data System Coding																													
	Tran	sactio	n Co	de						NPDE	ES							yr	/mo/d	ay			Ins	pec. T	ype	Ins	pecto	r I	Fac T	Гуре
1	N 2 5 3 A R 0 0 3 3 9 8 7										7	11	11 12 0 7 0 2 2 6 17 1								18	8 H 19 S 20 1								
			ı		1	ı	1			1 1		ı			Remar	ks	1													i
L	A	F I N 2 1 - 0 0 0 4 5																												
	Inspection Work Days Facility Evaluation Rat										ting			BI I	ı	QA _ _						; I	Reserved							
	67 0 0 1 69 70 N 71 N 72 N 73 74 75																ļ		80											
													Sec	ction	B: Fac	cility	Data													
	Name and Location of Facility Inspected (For industrial users discharging to POTW, also Entry Time /Date																Permit Effective Date													
City	include POTW name and NPDES permit number) City of Dumas WWTP													~9:	~9:30 a.m. 2/26/07						November 1, 2006									
	Approximately ¼ mile North of Highway 165 Section 25, Township 9 South, Range 4 West													Exi	Exit Time/Date						Permit Expiration Date									
	Desha County, Arkansas ~1:00 p.m. 2/26/07																October 31, 2011													
	Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Patrick Fitzgerald, Operator (870) 382-2121															Oth	ther Facility Data													
Pat	гіск	Fuzg	erai	а, Ор	<i>yera</i> ic)r	(870	<i>J)</i> 30)Z-Z1Z	<i>1</i>							•													
									none an	ıd Fax l	Numbe	r																		
		Gill, Duma		yor	(87	(0) 38.	2-212	<i>:1</i>										Г		acted										
	P.O. Box 157 Yes No X															X														
2	Dumas, Arkansas 71639 Section C: Areas Evaluated During Inspection																													
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)																														
N	Per	Permit N Flow Measurement											N	Op	erations & Maintenance						N	N CSO/SSO								
N	Re	Records/Reports N Self-Monitoring								_						ıdge I	dge Handling/Disposal					N								
M	ĺ	Facility Site Review N Compliance Scho									Sched	ules			N	Pı	<u> </u>						N	– • •						
N	Ef	fluent	, v												orm Water M							Other: Storm Damage								
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)																														
On Monday, February 26, 2007, I conducted a reconnaissance assessment of damage resulting from the Dumas tornado and noted the following:														the																
jouowing: City of Dumas POTW																														
	 The influent bar screen structure was damaged. However, the bar screen was still intact. Chlorinators and de-chlorinators are working but are manually operated due to no power. 																													
	<i>3</i> .	The	pui	mp s	tatio	ns ar	re wo	rkin	ng on	gene	rator	рон	ver.																	
	<i>4</i> .				l Eng		rs is	on s	site an	ıd wil	l be c	onte	actin	g th	e De	parti	ment	or F	<i>EM</i>	A fo	r									
		jina	пси	u re	ques	<i>ı</i> s.																								
Name(s) and Signature(s) of Inspector(s) Steven L. Henderson Agency/Office/Telep ADEQ/ Stuttgart/													ne/Fax 70) 673-8846/ (870) 673-7236							Date March 2, 2007										
Stern J. Handercon												()								,										
Signature of Reviewer											Agency/Office/Phone and Fax Numbers										Date									
																								I						