


Arkansas Department of Environmental Quality (ADEQ) Official Photograph Sheet

Location:		Eureka Springs POTW						
Photographer:		Tony Morris			Witness:			
Photo #	1	Of	2		Date:	10/19/06	Time:	10:46
Description:		Debris in Leatherwood Creek typical of streams draining urban watersheds. No indicators of untreated municipal waste water were noted in the debris.						
								
Photographer:		Tony Morris			Witness:			
Photo #	2	Of	2		Date:	10/19/06	Time:	11:22
Description:		An overview looking upstream of the plant. Ground water, from new construction excavation is being discharged through the filter in the foreground.						
		