



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Washington, D.C. 20460

Form Approved  
OMB No. 2040-0003  
Approval Expires 7-31-85

# NPDES Compliance Inspection Report

## Section A: National Data System Coding

Transaction Code	NPDES	yr/mo/day	Inspec. Type	Inspector	Fac Type
1   N   2   5   3   A   R   0   0   3   3   8   8   0   11   12   0   6   0   9   2   9   17   18   V   19   S   20   1					
Remarks					
A   F   I   N   #   2   6   -   0   0   1   4   5       G   A   R   L   A   N   D       C   O   .					
Inspection Work Days	Facility Evaluation Rating	BI	QA	-----Reserved-----	
67       1   69	70   N	71   N	72   N	73	74   75                 80

## Section B: Facility Data

Name and Location of Facility Inspected ( <i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i> )	Entry Time /Date 8:35 A.M. 9/29/06	Permit Effective Date 1 Jan. 2002
<b>City of Hot Springs - Mazarn #3</b> 379 Marion Anderson Road Hot Springs, AR	Exit Time/Date 9:00 A.M. 9/29/06	Permit Expiration Date 31 Dec. 2007
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)	Other Facility Data	
Craig Stevens, Pump Station Supv., 501-262-1881, fax 501-262-0339		
Name, Address of Responsible Official/Title/Phone and Fax Number		
Kent Myers, City Manager, 501-321-6810 320 Davidson Drive Hot Springs, Arkansas 71901	Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	

## Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

-	Permit	-	Flow Measurement	-	Operations & Maintenance	-	Sampling
-	Records/Reports	-	Self-Monitoring Program	-	Sludge Handling/Disposal	-	Pollution Prevention
-	Facility Site Review	-	Compliance Schedules	-	Pretreatment	-	Multimedia
-	Effluent/Receiving Waters	-	Laboratory	-	Storm Water	S	CSO-SSO

## Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

An SSO inspection was performed on this pump station in response to citizen complaints. The Mazarn #3 Pump Station is a 30-35 hp, 450 GPM duplex pump station that is servicing an SID on Marion Anderson Road. The complainant was concerned that the station was overflowing because of the water in the ditch. The water flows in this ditch continuously. Sampling of this water has eliminated wastewater and drinking water as a possible source of this flow. Our conclusion is that this water is from a spring. Mr. Stevens and I agreed that since this spring, being so close to a pump station needed to be placed in a French drain and directed away from the pump station to prevent further confusion to the public.

Name(s) and Signature(s) of Inspector(s)	Agency/Office/Telephone/Fax	Date
Jim McSwain	ADEQ / Hot Springs, AR / 501-520-0541	10/2/06
Signature of Management QA Reviewer	Agency/Office/Phone and Fax Numbers	Date

# ADEQ

A R K A N S A S  
Department of Environmental Quality

October 3, 2006

Don Cochran, Utilities Director  
City of Hot Springs  
P.O. Box 700  
Hot Springs, Arkansas

Re: AFIN No.: 26-00145


NPDES Permit No.: AR0033880

Dear Mr. Cochran:

On September 29, 2006, I performed a routine SSO inspection of the city's wastewater collection system, specifically Mazarn #3, the duplex pump station on Marion Anderson Road, in accordance with the provisions of the federal Clean Water ACT, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. This inspection revealed that you were in compliance with the terms of your permit.

If I can be any assistance, please contact me at 501-520-0541.

Sincerely,



Jim McSwain  
District Field Inspector  
Water Division

cc: NPDES Branch