



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Washington, D.C. 20460

Form Approved
OMB No. 2040-0003

NPDES Compliance Inspection Report

Section A: National Data System Coding

Transaction Code	NPDES										Yr/Mo/Day						Inspec. Type	Inspector	Fac. Type											
1	N	2	5	3	A	R	0	0	4	8	8	3	6	11	12	0	8	0	2	0	6	17	18	R	19	S	20	1		
Remarks																														
7	1	-	0	0	0	1	8																							
Inspection Work Days						Facility Evaluation Rating						BI	QA	-----Reserved-----																
67						69	70	4																						

Section B: Facility Data

Name and Location of Facility Inspected (<i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i>) City of Clinton Water Waste Water System in Van Buren County.	Entry Time/Date 11:00 February 6, 2008	Permit Effective Date August 1, 2005
	Exit Time/Date 12:30 February 6, 2008	Permit Expiration Date July 31, 2010
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Zeke Keeling, Water and Waste Water Manager/ 501-745-4320	Other Facility Data 35.5286 92.4340	
Name, Address of Responsible Official/Title/Phone and Fax Number The Honorable Chip Ellis, Mayor City of Clinton P.O. Box 277 Clinton, AR 72301	Contacted Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	N	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	N	Other:

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

The purpose of this site visit was to assess the extent of damage following the February 5, 2008 tornado which struck Clinton. At this time The West Plant was shut down due to a loss of power. The Pilgrim's Pride poultry processing plant which is the largest contributor to this plant was shut down also and not generating waste water. The main water line to town was ruptured and as a result very little waste water was being generated. The tornado path crossed the access to the east plant and the numerous fallen trees and debris blocking the road had not yet been cleared. Damage to the east plant had not been assessed.

Name(s) and Signature(s) of Inspector(s) Tony L. Morris	Agency/Office/Telephone/Fax Arkansas Dept. of Environmental Quality/ Jasper Field Office/ 870-446-2770 (PHONE) / 870-446-2181 (Fax)	Date February 7, 2008
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date