

Water Division NPDES Photographic Evidence Sheet

Location:	City of Clinton, East WWTP						
Photographer:	Greg Kremers			Witness:	Susan Poe		
Photo #	1	Of	2	Date:	2-8-2008	Time:	1234
Description:	Some of the damage that was observed at the plant.						



Photographer:	Greg Kremers			Witness:	Susan Poe		
Photo #	2	Of	2	Date:	2-8-2008	Time:	1249
Description:	View across the aeration basin.						

