

April 8, 2008

Mr. James Henderson Water and Wastewater Director City of Mountain View P.O. Drawer 360 Mountain View, AR 72560

RE: AFIN: 69-00011 NPDES Permit No.: AR0020117

Dear Mr. Henderson:

On February 6, 2008, I performed a sanitary sewer overflow inspection of the waste water treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated there under. This inspection revealed that sewage overflows occurred at three lift stations due to area-wide power outages after a tornado hit the area. The overflows were reported in a timely manner. The Sewer Overflow Report for February 2008 was submitted to the Department. No further action regarding these overflows is required at this time.

If I can be of any assistance, please contact me at (870) 446-6170 or by e-mail at Kirkpatrick@adeq.state.ar.us.

Sincerely,

Care Helpihit

Bruce Kirkpatrick District 2 Field Inspector Water Division

cc: Water Division Enforcement Branch Water Division Permits Branch AFIN: 69-00011

€EPA									Form Approved OMB No. 2040-0003	
UNITED STATES ENVIRONMENTAL PROTECTION AGENCY										
Washington, D.C. 20460 NPDES Compliance Inspection Report										
Section A: National Data System Coding										
NPDES Yr/Mo/Day Inspector Fac. Type   1 N 2 5 3 A R 0 0 2 0 1 1 7 11 12 0 8 0 2 0 6 17 18 V 19 S 20 1										
A F I N 6 9 - 0 0 1 1 I I I										
Inspection Work Days Facility Evaluation Rating BI QA   67 69 70 N 71 N 72 N 73 74 75									Reserved 80	
Section B: Facility Data										
Name and Location of Facility Inspected (For industrial users discharging to POTW, include POTW name and NPDES permit number) City of Mountain View Wastewater Treatment Plant							Entry Time/Date 1400/ 08-02-06		Permit Effective Date August 1, 2003	
	Westwood Avenue ¼ mile north of H ion 10, T11W, R14N in Stone Count				Exit Time/Date 1615 / 08-02-06		Permit Expiration Date July 31, 2008			
Mr. Joe Thatcher / Wastewater Plant Manager / 870 269-3293 Sa								Sar	er Facility Data nple Point: itude N 35.8665	
Name, Address of Responsible Official/Title/Phone and Fax Number Mr. James Henderson Water and Wastewater Director City of Mountain View P.O. Drawer 360 Mountain View, AR 72560						Contacted Yes No 🗹		Loi	ngitude W 92.1482	
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)										
N Permit N Flow Measureme							Ν	Sampling		
Ν	Records/Reports	ords/Reports N Self-Monitoring P		Program	Ν	Sludge Handling/Disposal		Ν	Pollution Prevention	
S	Facility Site Review	Ν	Compliance Sche	dules	Ν	Pre	retreatment		Multimedia	
Ν	Effluent/Receiving Waters	Ν	Laboratory	N Stor			rm Water		Other: Collection system	
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)										
A sanitary sewer overflow inspection was performed at the direction of the ADEQ Administration to assess the damages from a large tornado which struck the area on February 5, 2008. The treatment facility was operating on power from its back-up generator at the time of inspection. Sewage overflows at three lift stations occurred due to loss of electrical power in the area. Lift Station #1 overflowed an estimated 36,000 gallons from 2/5/08 to 2/10/08. Lift Station #2 overflowed an estimated 36,000 gallons from 2/5/08 to 2/10/08. Lift Station #2 overflows were stopped as soon as time and resources allowed. Overflows were reported in a timely manner and included on the February 2008 Sanitary Sewer Overflow Monthly Report.										
	ne(s) and Signature(s) of Inspector(s	ce Kirkpatrick	Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Jasper PHONE# (870) 446-6`170 / FAX# (870) 446-2181					Date March 12, 2008		
Sig	nature of Reviewer		Agency/Office/Phone and Fax Numbers					Date		