

June 18, 2008

Northwest Arkansas Regional Solid Waste Management District Attn. Bill Lord, Program Director PO Box 190 Harrison, AR. 72601

RE: AFIN/CSN 03-00208 Permit Nbr. 0022-SWTP

Dear Mr. Lord:

On June 17, 2008, I performed a routine inspection of your facility pursuant to the Arkansas Waste Tire Program, Reg. 14, and the above referenced permit. A copy of the inspection report is enclosed for your review.

Refer to the report to note any allegations of deficiencies that require corrective action. Please send a written response to the corrective action taken. Failure to respond to this letter in writing shall be construed as an admission of any allegations contained therein. Any items noted that are neglected and persistent may warrant enforcement action.

If I can be any further assistance, feel free to contact me at (870) 424-3322 or P.O. Box 442, Mountain Home, AR., 72653-0442.

Sincerely,

Gary Meador, Inspector

Sau Meado

Solid Waste Management Division

Northwest Arkansas Regional Solid Waste Management

District

PO Box 190

Harrison, AR. 72601

Attn. Bill Lord, Program Director



Arkansas Department of Environmental Quality Solid Waste Management Division Waste Tire Processing Facility Inspection



· "anagen"															
Site Name			NWARSWMD			County		Baxt	Baxter		AFIN		03-00208		
Facility Address		s	Mtn. Home, Hwy. 201 N. to CR831 to CR 784 to the Damco Site Project.			Telephone Number		870-4	870-425-4783		Permit Number		0022-SWTP		
Permittee Address PO Box 190 Harrison, AR. 72601					E-Mail Addres	SS									
Date	6-17-08 Entr		Entry Time	ry Time 1245		Exit		ime 1400		Follow		Yes	No X		
Regulation 14 - Operat								tion							
							70. a								
First Violation: Score of 1 Second Violation: Score of 2 Third Violation: Score of 4 Sign posted with required information 14.1402(F) Waste tires stored separately from used tires 14.1402(B) Records maintained and available 14.1207								Comments Waste tire collection and processing is done by Dale Yarbrough of Tire Disposal Systems, Inc.							
	Category 2 First Violation: Score of 2 Second Violation: Score of 4 Third Violation: Score of 8 Emergency preparedness manual on site and updated 14.1402(N) Communication equipment maintained on site 14.1210; 14.1402(L) Site kept free of vegetation 14.1402(M) Residuals disposed or recycled 14.1901(C)(3)														
	Separation distances maintained 14.1402(D) Mosquito and rodent control 14.1209; 14.1402(E) Passable access roads at all times 14.1402(H) Site bermed for runoff control 14.1402(J) Waste tire pile within maximum dimensions 14.1402(C) Access to the site controlled 14.1402(I) Processed tires meet storage criteria 14.1204 Department notified of emergency 14.1402(O)														
	Category 3 First Violation: Sco Second Violation: Sco Second Violation: Sco Second Violation: Sco Third Violation: Sco Third Violation: Sco Second Violat					of 6 12 402(G)			0 - 8 Satisfactory 9 - 13 Marginal ≥14 Unsatisfactory				TOTAL SCORE 0		
Regulation 14 - Records															
14.1402(N) Date of last revision/update to emergency preparedness manual 14.1207 Quantity of waste tires/processed tires received															
	14.1207 Quantity of waste tires stored on site 14.1207 Quantity of waste tires shipped from site							4,,		! !				46 - 5	
							All processed tire bales are stored and used at the Dam Site Project.								
14.1215 Date of last annual report						2-8	-08								
Operator Name & Number Don Yarbrough 1774 Signature of Inspector															







