AFIN: 61-00055

Permit #: AR0034835

€EPA									Form Approved OMB No. 2040-0003				
	UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460												
	NPDES Compliance Inspection Report												
Section A: National Data System Coding													
	Fransaction Code		NPDES				Yr/Mo/Day	Insp	pec. Type Inspector Fac. Type				
1	N 2 5 3 A R	0	0 3 4 8	3 5 11 12 0			8 0 5 1 2 17	18 V 19 S 20 1					
		I			Remar	ks							
Inspection Work Days Facility Evaluation Rating BI QAReservedReserved													
	67 69		70 N	71	Ν	72	N 73 74 75		80				
Section B: Facility Data													
inclı	e and Location of Facility Inspected de POTW name and NPDES permi hontas Wastewater Treatment Pl	Permit Effective Date February 1, 2004											
Poca	les down Swan Cove Road off Old hontas, AR dolph Co.	l Cou	nty Rd. (South alon	g Black River)			Exit Time/Date 0735 5/12/2008		Permit Expiration Date January 31, 2009				
	Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Other Facility Data None Other Facility Data												
Will Poca 207	e, Address of Responsible Official/ iam G. Daniel / Manager/870-892 hontas Water and Sewer Highway 67 South hontas, AR 72455		Phone and Fax Numb		Contacted Yes 🗹 No 🗖								
							uring Inspection sfactory, N = Not Evaluated)						
S	Permit	Ν	Flow Measuremen	ent U C		Op	erations & Maintenance	Ν	N Sampling				
Ν	Records/Reports	Ν	Self-Monitoring I	ng Program		Slu	Sludge Handling/Disposal N		Pollution Prevention				
Ν	Facility Site Review	Ν	Compliance Sche	edules N Pr			treatment	Ν	Wultimedia				
Ν	Effluent/Receiving Waters	N	Laboratory	N Storm Water U					Other: SSO				
Section D: Summary of Findings/Comments (Attach additional sheets if necessary) This SSO inspection was conducted in response to a complaint alleging an overflowing manhole near Black River bridge. At the time of the inspection, the manhole was overflowing. Mr. Daniel was contacted via telephone after the City of Pocahontas Water and Sewer Department office opened that morning. He was advised of the overflow and stated he would have the service crew investigate and take corrective action.													
As of the date of this report, there was no information in the Department's database indicating the overflow had been reported to the department as required by Part III of the permit.													
No letter will be sent.													
Name(s) and Signature(s) of Inspector(s) Agency/Office/I AB Dept. of En Agency/Office/I									Date				
Brei	t L. Walker Bred & Wal		AR Dept. of Environmental Quality-Jonesboro (870) 935-7221 ext. 12/(870) 935-4715 (Fax)					July 23, 2008					
Sig	ature of Reviewer			Agency/Office/Phone and Fax Numbers				Date					

ADEQ Water NPDES Inspection

AFIN: 61-00055

Water Division NPDES Photographic Evidence Sheet										
Location:	Cit	y of Po	cahontas	Collection System near H	Black River B	Bridge				
Photograph	ner:	Brent V	Walker		Witness:	None				
Photo #	1	Of	2		Date:	5/12/2008	Time:	0731		
Description	i:	Overfl	owing ma	anhole						
					5/12/					
Dhotograph		Dront V	Walker	200 B	Witness:	None				
Photograph Photo #	1er: 2	Of	2		Date:	5/12/2008	Time:	0732		
Description				anhole; Note Bridge and I				0752		
					Sinn 7					