



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Washington, D.C. 20460

Form Approved  
OMB No. 2040-0003

## NPDES Compliance Inspection Report

### Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspection Type	Inspector	Fac. Type
1 [N] 2 [5] 3 [A] [R] [0] [0] [3] [3] [8] [8] [0]	11 12 [0] [8] [0] [9] [0] [5]	17 18 [R]	19 [S]	20 [1]	
Remarks					
Inspection Work Days	Facility Evaluation Rating	BI	QA	Reserved	
67 [ ] [ ] [ ] 69	70 [3]	71 [N]	72 [N]	73 [ ] [ ] [ ]	74 75 [ ] [ ] [ ] [ ] [ ] [ ] 80

### Section B: Facility Data

Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number)

**City of Hot Springs** (Gulpha Creek Pump Station)  
Catherine Heights Road near Malvern Road  
Hot Springs, AR

Entry Time/Date  
**9/5/08 1245**

Permit Effective Date  
**January 1, 2008**

Exit Time/Date  
**9/5/08**

Permit Expiration Date  
**December 31, 2013**

Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)  
**n/a**

Other Facility Data

Name, Address of Responsible Official/Title/Phone and Fax Number  
Kent Myers, City Manager, 501-321-6810  
320 Davidson Drive  
Hot Springs, Arkansas 71901

Contacted  
Yes ☐ No ☒

### Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

-	Permit	-	Flow Measurement	-	Operations & Maintenance	-	Sampling
-	Records/Reports	-	Self-Monitoring Program	-	Sludge Handling/Disposal	-	Pollution Prevention
-	Facility Site Review	-	Compliance Schedules	-	Pretreatment	-	Multimedia
-	Effluent/Receiving Waters	-	Laboratory	-	Storm Water	U	Other: (SSO)

### Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

In talking with Craig Stevens (City of Hot Springs), he stated that due to the hurricane/tropical storm Gustav, the pump station lost power. The backup power source (generator) failed to start. Once power was restored, I and I became a problem causing further overflows.

He has estimated that approximately 60,000 gallons overflowed at the station. He stated that he would report all of the overflows as required and disinfect and deodorize any areas needed.

Name(s) and Signature(s) of Inspector(s)  
**Jim McSwain**

Agency/Office/Telephone/Fax  
**AR Dept. of Environmental Quality – Hot Springs Field  
Office – 501-520-0541 – Fax 501-520-5978**

Date  
**9/9/08**

Signature of Reviewer

Agency/Office/Phone and Fax Numbers

Date