



Form Approved
OMB No. 2040-0003

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Washington, D.C. 20460

NPDES Compliance Inspection Report

Section A: National Data System Coding

Transaction Code			NPDES										Yr/Mo/Day					Inspec. Type		Inspector		Fac. Type							
1	N	2	5	3	A	R	0	0	2	1	9	7	1	11	12	0	8	1	0	0	6	17	18	V	19	S	20	1	
Remarks																													
Inspection Work Days						Facility Evaluation Rating						BI		QA		-----Reserved-----													
67						70	N	71	N	72	N	73			74	75													80

Section B: Facility Data

Name and Location of Facility Inspected (<i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i>) City of Sunset – Satellite of Marion AR0021971 Sunset, AR Crittenden Co.	Entry Time/Date 1100 10/6/2008	Permit Effective Date 3/1/2007
	Exit Time/Date 1145 10/6/2008	Permit Expiration Date 2/29/2012
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) None – City Hall was closed		Other Facility Data
Name, Address of Responsible Official/Title/Phone and Fax Number Kirby Massey/Mayor/870-739-3233 Cell-870-225-3452 City of Sunset 300 John H. Johnson Blvd. Sunset, AR 72364		Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	U	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	U	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	U	Other: SSO

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

This SSO inspection was conducted in response to a fourth complaint alleging repeated overflows of the sewer system.

The City of Sunset operates and maintains two pump stations. The City of Sunset pumps their sewage to the City of Marion (AR0021971) for treatment.

Multiple violations were noted. See the letter attached to the September 11, 2008 inspection for details.

Name(s) and Signature(s) of Inspector(s) Brent L. Walker <i>Brent L. Walker</i>	Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Jonesboro (870) 935-7221 ext. 12/(870) 935-4715 (Fax)	Date October 17, 2008
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date

Water Division NPDES Photographic Evidence Sheet

Location:	City of Sunset						
Photographer:	Brent Walker			Witness:	None		
Photo #	1	Of	6	Date:	10/6/2008	Time:	1115
Description:	Harvard St. pump station with extensive leakage and wet well full, with extensive accumulation of solids.						



Photographer:	Brent Walker			Witness:	None		
Photo #	2	Of	6	Date:	10/6/2008	Time:	1115
Description:	Leakage from pump in Harvard St. pump station.						



Water Division NPDES Photographic Evidence Sheet

Location: City of Sunset

Photographer: Brent Walker **Witness:** None

Photo # 3 **Of** 6 **Date:** 10/6/2008 **Time:** 1129

Description: Manhole behind Harvard One Apartments at capacity.



Photographer: Brent Walker **Witness:** None

Photo # 4 **Of** 6 **Date:** 10/6/2008 **Time:** 1129

Description: Manhole behind Harvard One Apartments at capacity with extensive accumulation of solids.



Water Division NPDES Photographic Evidence Sheet

Location:	City of Sunset						
Photographer:	Brent Walker			Witness:	None		
Photo #	5	Of	6	Date:	10/6/2008	Time:	1130
Description:	Sewage from overflowing manhole flowing along fence line.						



Photographer:	Brent Walker			Witness:	None		
Photo #	6	Of	6	Date:	10/6/2008	Time:	1130
Description:	Sewage from overflowing manhole.						

