

March 23, 2009

The Honorable Mary Jane Erwin Mayor, City of Flippin P.O. Box 40 Flippin, AR 72634

Re: AFIN: 45-00021; NPDES Permit No. AR0021717

Dear Mayor Erwin:

On February 4, 2009, I performed a reconnaissance inspection of the waste water treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. This inspection did not reveal evidence if any violations.

If I can be of any assistance, please contact me at (870) 446-6170 or by e-mail at Kirkpatrick@adeq.state.ar.us.

Sincerely,

Bruce Kirkpatrick

District 2 Field Inspector

Water Division

cc: Cindy Garner, Technical Assistance Manager, Water Division Enforcement Branch Water Division Permits Branch

	ADEQ Water NPDES In	spec	tion AF	FIN: 45-00021			Permit #: AR	00217	717
≎ EPA									Form Approved OMB No. 2040-0003
UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460									
NPDES Compliance Inspection Report									
Section A: National Data System Coding									
Transaction Code NPDES Yr/Mo/Day Inspec. Type 1 N 2 5 3 A R 0 0 2 1 7 1 7 11 12 0 9 0 2 0 4 17 18 R									
	A F I N 4 5 - 0 0 0 2 1 Remarks								
Inspection Work Days Facility Evaluation Rating BI QA									Reserved
Section B: Facility Data									
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Entry Time/Date 1508 / 2-4-09								Permit Effective Date	
City of Flippin Wastewater Treatment Plant							11/01/07		
NE1/4, NE1/4, Section 10, T19N, R15W, Marion County Exit Time/Date 1530 / 2-4-09								Permit Expiration Date 10/31/12	
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Mr. Robert Patterson, Plant Operator, 870 453-2566 Oth									er Facility Data
Name, Address of Responsible Official/Title/Phone and Fax Number Mary Jane Erwin / Mayor / (870) 453-8300 / Fax (870) 453-5722 City of Flippin P.O. Box 40, Flippin, AR 72634						Cont Yes 🔲	Contacted Yes □ No ☑		
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)									
S	Permit	N	Flow Measuremen	,, , , , ,	N	Operations & Main	,	N	Sampling
N	Records/Reports	N	Self-Monitoring Program		N	- ^			Pollution Prevention
S	Facility Site Review	N	Compliance Scheo	dules	iles N Pro		etreatment		Multimedia
S	Effluent/Receiving Waters	N	Laboratory		N	Storm Water			Other:
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)									
A reconnaissance level inspection was performed to assess the damages from a large ice storm which struck the area the previous week. This inspection revealed that prior to power being restored the POTW had to use its generator back-up power to run the treatment plant and its only lift station, which is on the treatment plant grounds. According to the Operator, Mr. Patterson, no sewage overflows occurred. Plant effluent appeared to be of good quality. This inspection did not reveal any evidence of permit violations. Name(s) and Signature(s) of Inspector(s) Bruce Kirkpatrick Agency/Office/Telephone/Fax Date									
	Bruce K		Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Jasper PHONE# (870) 446-6170 / FAX# (870) 446-2181				Date March 23, 2009		

Agency/Office/Phone and Fax Numbers

Signature of Reviewer

Date




Photo of plant effluent post-aeration unit showing clear effluent