

April 2, 2009

Northwest Arkansas Regional Solid Waste Management District Attn. Bill Lord, Program Director PO Box 190 Harrison, AR. 72601

RE: AFIN/CSN 03-00208

Permit Nbr. 0022-SWTP

Dear Mr. Lord:

On March 26, 2009, I performed a routine inspection of your facility pursuant to the Arkansas Waste Tire Program, Reg. 14, and the above referenced permit. A copy of the inspection report is enclosed for your review.

Refer to the report to note any allegations of deficiencies that require corrective action. Please send a written response to the corrective action taken. Failure to respond to this letter in writing shall be construed as an admission of any allegations contained therein. Any items noted that are neglected and persistent may warrant enforcement action.

If I can be any further assistance, feel free to contact me at (870) 424-3322 or P.O. Box 442, Mountain Home, AR., 72653-0442.

Sincerely,

milleado

Gary Meador, Inspector Solid Waste Management Division



Arkansas Department of Environmental Quality Solid Waste Management Division Waste Tire Processing Facility Inspection



	anagemer														
Site Name			NWARSWMD			County	/	Baxte	er	AFIN		03-002	03-00208		
Facility Address		6	Mtn. Home, Hwy. 201 N. to CR831 to CR 784 to the Damco Site Project.			Telephone Number		870-4	870-425-4783		Permit Number		0022-SWTP		
Permittee Address			PO Box 190 Harrison, AR. 72601			E-Mail Address									
Date	te 3-26-09		Entry Time 1330			Exit		Time 1445		Follow		w-Up	Yes	No	
								_						X	
Regulation 14 - Operational Standards															
Category 1 First Violation: Score of 1 Second Violation: Score of 2 Third Violation : Score of 4 Sign posted with required information 14.1402(F) Waste tires stored separately from used tires 14.1402(B) Records maintained and available 14.1207 First Violation: Score of 2 Second Violation: Score of 2 Second Violation: Score of 2 Second Violation: Score of 4 Third Violation : Score of 8 Emergency preparedness manual on site and updated 14.1402(N) Communication equipment maintained on site 14.1210; 14.1402(L) Site kept free of vegetation 14.1402(M) Residuals disposed or recycled 14.1901(C)(3)								Comments Waste tire collection and processing is done by Dale Yarbrough of Tire Disposal Systems, Inc.							
Separation distances maintained 14.1402(D) Mosquito and rodent control 14.1209; 14.1402(E) Passable access roads at all times 14.1402(H) Site bermed for runoff control 14.1402(J) Waste tire pile within maximum dimensions 14.1402(C) Access to the site controlled 14.1402(I) Processed tires meet storage criteria 14.1204 Department notified of emergency 14.1402(O)								- - - - -							
Category 3 First Violation : Score of 3 Second Violation : Score of 6 Third Violation : Score of 12 Fire protection services assured 14.1402(K) Operations involving use of open flames prohibited 14.1402(G) Facility operates in accordance with permit documents 14.1201 Fifty foot wide fire lanes and unobstructed 14.1402(D)							•	0 - 8 Satisfactory 9 - 13 Marginal ≥14 Unsatisfactory 0							
Regulation 14 - Records															
14.1402(N) Date of last revision/update to emergency preparedness manual 14.1207 Quantity of waste tires/processed tires received 14.1207 Quantity of waste tires stored on site															
	14.1207 Quantity of waste tires shipped from site 14.1215 Date of last annual report						All processed tire bales are stored and used at the Dam Site Project. 2-8-08								
14.1215	14.1215 Date of last annual report							2-8	-08						
Don Yarbrough 1774 Operator Name & Number Signature of Inspector										A	and	leads	_		

FOR ADEQ USE ONLY







