

ADEQ

ARKANSAS
Department of Environmental Quality

June 11, 2009

Mr. James Henderson
Water and Wastewater Director
City of Mountain View
P.O. Drawer 360
Mountain View, AR 72560

RE: AFIN: 69-00011 NPDES Permit No.: AR0020117

Dear Mr. Henderson:

On April 27, 2009, I performed a recon inspection of the waste water treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated there under in response to a complaint received on April 13, 2009. The complaint alleged that a manhole was overflowing at the PD Building Supply on Hwy 66 West on April 12. Mountain View Wastewater was notified on April 13 and stated they had already stopped the overflow. This inspection revealed the following violation: an overflow estimated to be 5000 gallons occurred on April 12, 2009, during heavy rain due to lift station pump failure. The area had been cleaned and disinfected. The overflow was reported in a timely manner. The Sewer Overflow Report for April 2009 was submitted to the Department. No further action regarding this overflow is required at this time.

If I can be of any assistance, please contact me at (870) 446-6170 or by e-mail at Kirkpatrick@adeq.state.ar.us.

Sincerely,



Bruce Kirkpatrick
District 2 Field Inspector
Water Division

cc: Water Division Enforcement Branch
Water Division Permits Branch



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Washington, D.C. 20460

NPDES Compliance Inspection Report

Form Approved
OMB No. 2040-0003

Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspec. Type	Inspector	Fac. Type
1 N 2 5 3 A R 0 0 2 0 1 1 7 11 12 0 9 0 4 2 7 17 18 R 19 S 20 1	Remarks				
A F I N 6 9 - 0 0 0 1 1					
Inspection Work Days	Facility Evaluation Rating	BI	QA	-----Reserved-----	
67 <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 69	70 N	71 N	72 N	73 <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	74 75 <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 80

Section B: Facility Data

Name and Location of Facility Inspected (<i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i>) City of Mountain View Wastewater Treatment Plant On Westwood Avenue ¼ mile north of Hwy 66 East Section 10, T11W, R14N in Stone County	Entry Time/Date 1315 / 4-27-09	Permit Effective Date 8-1-08
	Exit Time/Date 1345 / 4-27-09	Permit Expiration Date 7-31-13
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Mr. Jackey Craig, / Operator / 870 269-3293	Other Facility Data Sample Point: Latitude N 35.8665 Longitude W 92.1482	
Name, Address of Responsible Official/Title/Phone and Fax Number Mr. James Henderson Water and Wastewater Director City of Mountain View P.O. Drawer 360 Mountain View, AR 72560	Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	N	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	U	Other: Collection system

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

The complaint alleged that a manhole was overflowing at the PD Building Supply on Hwy 66 West on April 12. Mountain View Wastewater was notified on April 13 and stated they had already stopped the overflow. This inspection revealed the following violation: an overflow estimated to be 5000 gallons occurred on April 12, 2009, during heavy rain due to lift station pump failure. The area had been cleaned and disinfected. The overflow was reported in a timely manner. The Sewer Overflow Report for April 2009 was submitted to the Department. No further action regarding this overflow is required at this time. Attached are photos taken on 4-27-09 and a copy of the SSO Report Form submitted to the Department.

Name(s) and Signature(s) of Inspector(s) Bruce Kirkpatrick 	Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Jasper PHONE# (870) 446-6170 / FAX# (870) 446-2181	Date June 11, 2009
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date



Lift station which failed



Manhole which overflowed as result of lift station failure



Lift station which failed

ADEQ - Water Div - NPDES - Questions/Comments Confirmation Page

Page 1 of 1

CONFIRMATION

Your information has been sent.

SSO Report Form

Date Received: 4/15/2009
NPID: AR0020117
Date Started: 4/12/2009
Date Stopped: 4/12/2009
Volume: 5000
Stream: Hughes Creek
Description: Manhole #1 on West 66 and Maple St.
Cause: Rainfall
Measures Taken: EC
Environmental Damage: NEAH
Callers Name: Joe Thatcher
Telephone Number: 870-269-8284



4-15-09

NOTE: If the Permit requires a follow-up letter within five (5) days of verbally reporting the event, print this confirmation report, sign and date it with an original signature, and submit it to the Department.