

ADEQ

A R K A N S A S
Department of Environmental Quality

November 5, 2009

Mark Foshee, Owner
Kirby House Car Wash
20 Barentine Rd.
Amity, AR 71921

Re: AFIN No: 55-00134

Permit No: 4732-WG-CW

Dear Mr. Foshee:

On November 2, 2009, I performed a routine compliance inspection of your facility in accordance with the provisions of the Arkansas Water and Air Pollution Control Act and the regulations promulgated thereunder. This inspection revealed that you are in compliance with the terms of your permit.

If I can be of any assistance, please feel free to contact me at (870) 389-6970.

Sincerely,

Shan Lynch

Shan Lynch
District Field Inspector
Water Division

cc: Enforcement Branch

ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY

STATE INDUSTRIAL PERMIT INSPECTION FORM

AFIN: 55-00134 Log No.: _____

Permit No.: 4732-WG-CW Inspection Date: November 2, 2009

Media: Water Inspector: Shan Lynch

Compliance Status: **OUT**

1A. Name of Facility: Kirby House Car Wash

Address: 2897 Hwy 70 W; Kirby, AR

County: Pike Sec. 3, T6S, R25W

2A. Name of On-Site Representative: none

3A. Name of Responsible Official: Mark Foshee

Address: 20 Barentine Rd.; Amity, AR 71921 Telephone: _____

4A. Parent Company: NA

Address: _____ Telephone: _____

5A. Description of Process (including type of industry, materials produced, and major by-products):

2 bay car wash. Grit trap, oil and grease separator, septic tank, distribution box, field lines

6A. Any complaints registered against this permitted facility? Yes _____ No **X**
If yes, give date and description of complaint.

7A. Are there any additions, modifications, or corrections to the facility since the last inspection?
Yes _____ No **X**
If yes, explain:

1B. Furnish a simplified flow diagram of the treatment system and include main components, flow sequence through plant, and calculated or estimated flows.

2B. Nearest Stream: Unnamed tributary to Bear Creek

3B. Does wastewater from this facility cause adverse effect on the waters of the State:

Yes No

If yes, describe: _____

4B. Are operating records kept as required by permit? Yes No N/A

If no, explain: Operating records are required; however, no onsite representative was available to provide these records.

5B. Are maintenance records kept as required by permit? Yes No N/A

If no, explain: _____

6B. Are Samples routinely taken? Yes No N/A

7B. Does the sampling program meet the requirements of the permit?

Yes No N/A

If no, explain: _____

8B. What laboratory does the facility use? NA

Address: _____ Telephone: _____

1C. Does laboratory procedures and records meet the requirements of the permit?

If no, explain: _____

2C. Is contaminated runoff a problem?

3C. Is sludge disposal required?

Yes No N/A

If yes, describe (including final destination): No onsite representative available to provide this information.

4C. Is the treatment system being properly operated and maintained as required by permit?

Yes No N/A

If no, Explain See summary below _____

SUMMARY OF FINDINGS/COMMENTS

No violations of this permit were noted during this inspection.

Inspector Signature:

Ethan Lynch

Date of Report: November 2, 2009

Signature of Reviewer:

Ein m. fl.

Date of Review: November 2, 2009