

March 17, 2010

Larry Merriman – Utilities Operations Director City of Hot Springs 780 Adams Street Hot Springs National Park, AR 71901

Re: AFIN: No. 26-00145 NPDES Permit No. AR0033880

Dear Mr. Merriman:

On March 8, 2010, I performed a routine inspection of the city's wastewater collection system, specifically Mazarn #1 Pump Station, in accordance with the provisions of the federal Clean Water ACT, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated there under. This inspection revealed that the manhole just prior to the pump station had overflowed due to an Entergy power outage.

Since you have complied with the notification of noncompliance requirements of your permit, no further response is necessary.

If I can be of any assistance, please contact me at 501-520-0541.

Sincerely.

Jim McSwain

District 7 Field Inspector

Water Division

cc: Water Division Enforcement Branch

Water Division Permits Branch

																	Т						
-\$EPA										Form Approved OMB No. 2040-0003													
VETA																							
UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460																							
NPDES Compliance Inspection Report																							
					5	Section	ı A: N	Natio	nal Da	ata S	stem Co	ding											
1								Yr/Mo	1	8	3 17		ì	pec. Type Inspector Fac. Ty R 19 S 20 1									
								F	Remai	rks													
	Inspection Work Days Facility Evaluation Rating BI QA							 I	Reserved														
	67 69		7	0 N	J			71	N	72	N 73	3		7	4 75							80	
							Sec	tion I	B: Fa	cility	Data						1						
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Entry Time/Date 1355 3/8/10									Permit Effective Date January 1, 2008														
City of Hot Springs (Mazarn #1 Pump Station) Ridge Point Road, off of Marion Anderson Hot Springs, AR Exit Time/Date 1500 3/8/10									Permit Expiration Date December 31, 2013														
Nan	Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Other Facility Data																						
Sila	Shawn Davis, Collections Mgr. 501-623-6981																						
	ne, Address of Responsible Official/ ry Merriman, Utilities Operation					oer						C-											
320	Davidson Drive												ntacte	а П									
Hot Springs, Arkansas 71901 Yes ✓ No □																							
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)																							
-	Permit - Flow Measurement					- Operations & Maintenance -								Sampling									
-	Records/Reports - Self-Monitoring I				Program - S				Slu	ludge Handling/Disposal -						Pollution Prevention							
-	Facility Site Review	Site Review - Compliance Schedules				-	Pretreatment -						Multimedia										
-	- Effluent/Receiving Waters - Laboratory					- Storm Water U							Other: (SSO)										
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)																							
Shawn Davis – Collections Mgr. with the city contacted me to let me know that there had been an overflow at Mazarn 1 due to a																							
transformer blowing. His office was not notified until the overflow had occurred. Once Entergy restored power, the pump station																							
began working normal and the overflow ceased. His people began disinfecting the area and clean-up. Mr. Davis contacted me once the overflow was contained and remediated on 3/7/10.																							
Since the station is located so close to Lake Hamilton, a recon inspection was performed.																							
Mazarn #1 consist of two 30 horsepower pumps and is currently on a light alarm system.																							
						T																	
Name(s) and Signatule(s) of Inspectors) Jim McSwain						Agency/Office/Telephone/ AR Dept. of Environm					/Fax nental Quality – Hot Springs Field						Date						
					_					20-0541 – Fax 501-520-5978					3/16/10								
Signature of Reviewer						Agency/Office/Phone and Fax Numbers							Da	Date									

ADEQ Water NPDES Inspection	AFIN: 26-00145	Permit #: AR0033880