Form Approved OMB No. 2040-0003

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460										
NPDES Compliance Inspection Report										
Section A: National Data System Coding										
Transaction Code										
67 69 70 N 71 N 72 N 73 74 75 80									80	
Section B: Facility Data										
include POTW name and NPDES permit number) City of Bentonville Wastewater Treatment Plant							Entry Time/Date 1005 / 07-19-10		Permit Effective Date March 01, 2009	
1901 N.E. A Street Bentonville, Arkansas 72712 Exit Time/Date 1030 / 07-19-10									Permit Expiration Date February 28, 2014	
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) N/A									Other Facility Data 36.3146, -94.2745	
Name, Address of Responsible Official/Title/Phone and Fax Number Mike Roberts, Wastewater Utility Manager City of Bentonville 115 W. Central Bentonville, Arkansas 72712 479-271-3160, 479-271-3163 (fax)							Contacted Yes ✓ No □	Lift Station #22 and manhole west of lift station		
Section C: Areas Evaluated During Inspection $(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)$										
N	Permit	N	Flow Measuremen		N		erations & Maintenance	N	Sampling	
N	Records/Reports	N	Self-Monitoring F	Program	N	Slu	dge Handling/Disposal	N	Pollution Prevention	
N	Facility Site Review	N	Compliance Scheo		N		treatment	N	Multimedia	
N	Effluent/Receiving Waters N Laboratory			N Storm Water			S	Other: suspected SSO		
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)									Oner suspected asso	
A reconnaissance inspection was conducted to investigate a complaint of a possible sanitary sewer overflow. The complainant stated that he smelled a strong sewage odor from his property but could not identify the source. A lift station is located west of the complainant's home between his home and Little Osage Creek. A manhole along a gravity main is present west of Little Osage Creek. There was no physical evidence of an overflow from these locations nor was there evidence of wastewater surfacing in the area. Little Osage Creek did not appear to be impacted from an overflow. It is suspected that the odor detected by the complainant was coming from the vent pipe at the lift station.										
Name(s) and Signature(s) of Inspector(s)				Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Fayetteville					Date	
John	Fazio		479-267-0811, ext. 16; 479-267-0819 (fax)					08/05/10		
Sign	nature of Reviewer		Agency/Office/Phone and Fax Numbers					Date		

\$EPA