

May 24, 2011

Kirby Murray, Public Works Director City of Berryville P.O. Box 227 Berryville, Arkansas 72616

RE: AFIN: 08-00034

NPDES Permit No.: AR0021792

Dear: Mr. Murray:

On March 29, 2011, I performed a reconnaissance level inspection at the wastewater treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. The inspection did not reveal any evidence of any violations.

If I can be of any assistance, please contact me at 870-446-6170.

Sincerely,

Car Helpihit

Bruce Kirkpatrick District 2 Field Inspector Water Division

cc: Water Division Enforcement Branch Water Division Permits Branch

÷	PA																				Form Approved OMB No. 2040-0003		
		UNIT	ED ST	ΓATES	ENVI					TION	AGEN	NCY											
	NPDES	5 ([0]	mn		hington nnc				C	tio	n l	R	eno	rt								
				F										em Cod									
1	Transaction CodeN253AR)	0	2	NPDE 1	ES 7	9	2	1		12	1		Y 1 0	r/Mo	1	ay 2	9	17	Ins 18	spec. Type Inspector Fac. Type R 19 S 20		
L	A F I N 0 8 - 0 0 0 3 4 Image: Second secon												 	Reserved									
67 69 70 N 71 N 72 N 73 74 75															80								
Section B: Facility Data																							
inclu City	Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Entry Time/Date City of Berryville 1615 / 03-29-2011														Permit Effective Date December 01, 2007								
1000 W. CedarvaleExit Time/DateBerryville, Arkansas1638 / 03-29-2011													Permit Expiration Date November 30, 2012										
	Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Other Facility Data Darrell Backs, Chief Operator, 870-423-3749 Facility: 36 21' 25.95", -93 34' 43.51"																						
Name, Address of Responsible Official/Title/Phone and Fax Number Contacted Kirby Murray, Public Works Director Contacted P.O. Box 227 Pole Serryville, Arkansas 72616 Berryville, Arkansas 72616 Yes No I											• •												
				(S =	Satisf									i ng Insp actory, N			Eval	uated	l)				
S	Permit	Ν	Flo	ow M	leasu	reme	nt				N	Op	pera	ations 8	k Ma	aint	enar	ice		Ν	Sampling		
Ν	Records/Reports	Ν	Se	lf-Mo	onito	ring I	Progr	am			Ν	Slu	udg	e Hand	ling/	/Dis	posa	ıl		Ν	Pollution Prevention		
S	Facility Site Review	N	Co	ompli	iance	Sche	dules	5			N	Pro	retro	eatmen	t					N	N Multimedia		
Μ	Effluent/Receiving Waters	N So		bora	•	nory	ofFi	ndin	as/C	0	N			1 Water		l ch	oote	if no	005501	w)	Other:		
Section D: Summary of Findings/Comments (Attach additional sheets if necessary) A reconnaissance inspection was performed to assess the status of the "smoky" condition of the wastewater which was passing through the POTW and was attributed to the pre-treated wastewater for the Tyson Foods Processing Facility. This inspection revealed that the effluent had cleared considerably from its condition the day prior. While the "smoky" condition still existed, it was much improved. The receiving stream just below Outfall 001 appeared to have a low turbidity. Tyson had made improvements in their treatment. The inspection did not reveal any evidence of any violations. Also, attached to this report is a copy of an inspection report from the 3-29-2011 inspection which was sent by memo to the Water Division Enforcement Branch and not previously mailed to the City.																							
	ne(s) and Signature(s) of Inspector(s										Telep viro			x Quality	v. Ia	isne	•r				Date 3-17-2011		
Bruc	e Kirkpatrick Ruce Helpihi	Ł												B1 (fax)	у- ј а	she	.1				5-17-2011		
	ature of Reviewer						Ag	gency	y/Off	ice/	Phon	e and	d Fa	ax Numł	pers						Date		

Location:	Be	erryvil	le WW	TP							
Photograph	ner:	Bruce	Kirkpa	ıtrick	Witness	none	ne				
Photo #	1	of	4		Date:	3-29-2011	Time:	1620 hrs			
Descriptio	n:	Outfa	11 001								
Photograph	ner:	Bruce	Kirkpa	trick	Witness	none	1				
Photo #	2	of	4		Date:	3-29-2011	Time:	1620 hrs			
Descriptio	n:	Recei	ving str	eam at Berryville WV	VTP just b	elow Outfal	1 001				

Location:	De				1 apri 51					
		-	le WW							
Photograph	ner:	Bruce	Kirkpa	trick	Witness	none				
Photo #	3	of	4		Date:	3-29-2011	Time: 1621 hrs			
Descriptio	n:	Weir	overflo	w at Final Clarifier 1						
Photograp	ner:	Bruce	Kirkpa	ıtrick	Witness	none				
Photo #	4	of	4		Date:	3-29-2011	Time:	1621 hrs		
Descriptio	n:	UV u	nit		1 1		1	•		

ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY

WATER DIVISION

MEMORANDUM

TO:	CO: Cindy Garner, Technical Assistance Manager, Enforcement Bran					
THRU:	Eric Fleming, Field Services Branch Manager					
FROM:	Bruce Kirkpatrick, Inspector					
DATE:	3-29-2011					
RE:	Berryville POTW NPDES Permit No. AR0021792 / AFIN 08-00034					

Attached please find the NPDES Inspection Report of my investigation on March 28, 2011. I will stop by and look at the discharge today. Please call me if you have any questions.

									Form Approved OMB No. 2040-0003	
9	EPA									
		UNII	ED STATES ENVIRONM Washingtor	ENTAL PROTECTION 1, D.C. 20460	N AGEN	ICY				
	NPDES	5 (Complianc		tio	n F	Report			
			-	Section A: Nation	nal Da	ıta Sy	stem Coding			
1	Transaction Code N 2 5 3 A R	0	NPDES 0 2 1 7	9 2 11	12	1	Yr/Mo/Day 1 0 3 2 9 17	Inspec. TypeInspectorFac. Type18R19S201		
	A F I N 0	8	- 0 0 0	3 4	Remar	ks				
	Inspection Work Days 67 69		Reserved 80							
				Section I	B: Fac	ility l	Data		1	
inclı City	ne and Location of Facility Inspected ade POTW name and NPDES permit of Berryville 0 W. Cedarvale			,	Entry Time/Date 0855 / March 28, 2011		Permit Effective Date December 01, 2007			
	ryville, Arkansas			Exit Time/Date 1010 / March 28, 2011		Permit Expiration Date November 30, 2012				
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)Other Facility DataDarrell Backs, Chief Operator, 870-423-4074, 870-423-4501 (fax)Facility: 36 21' 25.95", -93 34' 43Mike Maynard, OperatorFacility: 36 21' 25.95", -93 34' 43										
Kir City P.O	ne, Address of Responsible Official/ by Murray, Public Works Director y of Berryville . Box 227 ryville, Arkansas 72616						Contacted Yes No 🗹			
				tion C: Areas Ev y, M = Marginal,			rring Inspection sfactory, N = Not Evaluated)			
Ν	Permit	Ν	Flow Measuremen	nt	Ν	Ope	erations & Maintenance	N	Sampling	
Ν	Records/Reports	Ν	Self-Monitoring F	Program	Ν	Slu	dge Handling/Disposal	Ν	Pollution Prevention	
Ν	Facility Site Review	Ν	Compliance Sche	dules	N	Pre	treatment	N	Multimedia	
Μ	Effluent/Receiving Waters	N	Laboratory	of Findings/Com	N		rm Water ach additional sheets if necessary	N v)	Other:	
Ty: Bra we: 24, pre hou tre the clea	son-Berryville and this ⁷ 'smoky col anch Manager, on March 25, 2011 re normal at the POTW. Mr. Bac 2011. Results from lab are as fol	s perf or" v . Se ks sta llows has c ould ime t tetreat le to a	ormed on March 28 vas passing through e attached photos ta tited that the conditi 	8, 2011, in respon the POTW. C aken on March 2 ion also existed o ia, 4.74 mg/l CB On several oc ory being discuss store its wastew. Plant. Mr. Maynout of the WWT. Agency/Office/	nse to onditi 28, 201 on Ma: OD ar ccasion ed as ater d nard s P. Telepl nviror	a rep on wa 1. 1 rch 2 nd 12 ns ove a fact uring stated	ort from the facility that they we as reported to Ms. Cindy Garner Except for the cloudy "smoky" a 4, 2011. Compliance sampling col/100 ml Fecal Coliform Bacter er the past few weeks, the City as or in the current problem was th g these ceases in discharge. Be by phone at 1240 hrs on 3/29/11 Fax tal Quality- Jasper	re re , AD ppear at Ou ria. 7 ked 7 ked 7 at Ty nch te	rance of the water, all parameters htfall 001 was performed on March The Tyson Plant began biological Tyson to stop discharging for several yson lost too much biomass in its ests were being performed to assess	
	nature of Reviewer			Agency/Office.	/Phon	e and	Fax Numbers		Date	

Location:	Be	erryvil	le WW	TP	<u> </u>			
Photograph	ner:	Bruce	Kirkpa	utrick	Witness	none		
Photo #	1	of	8		Time:	0914 hrs		
Descriptio	n:	Outfa	ll 001 e	ffluent: filtered on the	e left of ph	oto / unfilt	ered on the	e right
					mL 0 200 5% 200 100 100 150 50			
Photograph	ner:	Bruce	Kirkpa	atrick	Witness	none		
Photo #	2	of	8		Date:	3-28-11	Time:	0921 hrs
Descriptio	n:	Recei	ving str	eam at Berryville WV	WTP just b	elow Outfa	all 001	

	_			Official Photog	гарп бп				
Location:	Be	erryvil	le WW	ГР		_			
Photograph	ner:	Bruce	Kirkpa	utrick	Witness	none	;		
Photo #	3	of	8		3-28-1	1 7	Fime:	0923 hrs	
Descriptio	n:	Weir	overflo	w at Final Clarifier 1					
Photograph	ner:	Bruce	Kirkpa	utrick	Witness	none	;		
Photo #	4	of	8		Date:	3-28-1	1 7	Fime:	0923 hrs
Descriptio	n:	Final	Clarifie	er 1			•		

				Official Photog	apii Sii	eel		
Location:	Be	rryvil	le WW	ГР				
Photograph	ner:	Bruce	Kirkpa	ıtrick	Witness	none		
Photo #	5	of	8		Date:	3-28-11	Time:	0924 hrs
Descriptio	n:	Berry	ville 00	1				
Photograph Photo #	her:	Bruce of	Kirkpa 8	ıtrick	Witness: Date:	none 3-28-11	Time:	0927 hrs
Descriptio	n:	UV u	nit		<u> </u>			

Location:	Be	erryvil	le WW	TP / Tyson Foods - E		100			
Photograph	er:	Bruce	e Kirkpa	ıtrick	Witness	::	none		
Photo #	7	of	8		Date:	3-	-28-11	Time:	0927 hrs
Description	n:	Final	Clarifie	r 2 at Berryville WW	/TP				
Photograph	er:	Bruce	e Kirkpa	ıtrick	Witness	::	none		
Photo #	8	of	8		Date:	3-	-28-11	Time:	0955 hrs
Description	n:	Tysor	n efflue	nt					