

May 27, 2011

Mr. Catherine Yeager, Plant Superintendent City of Harrison Wastewater Treatment Facility P.O. Box 1715 Harrison, AR 72602

RE: AFIN: 05-00054; NPDES Permit No. AR0034321

Dear Ms. Yeager:

On March 29, 2011, I performed a reconnaissance level inspection of the waste water treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. The investigation was performed to assess the plant's condition after your report of an upset on March 25, 2011. This inspection did not reveal evidence of any violation not already reported to the Department.

If I can be of any assistance, please contact me at (870) 446-6170 or by e-mail at Kirkpatrick@adeq.state.ar.us.

Sincerely,

Bruce Kirkpatrick

District 2 Field Inspector

Water Division

cc: Water Division Enforcement Branch

Water Division Permits Branch

Name(s) and Signature(s) of Inspector(s) Bruce Kirkpatrick Our High	Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Jasper PHONE# (870) 446-6170 / FAX# (870) 446-2181	Date May 17, 2011
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date

Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet

				9 222 0 202 2 22 0 7 0 8	2 60 6 22 8 22					
Location:	ion: Harrison POTW									
Photograp	Bruce Kirkpatrick			Witness	Witness: None					
Photo #	1	1 of 4 Date: 3-29-2011 Time: 1502						1502		
Description: Photo of plant effluent										



Photograp	pher:	Bru	ce Kirk	patrick	Witness	none none		
Photo #	2	of	4		Date:	3-29-2011	Time:	1502
Description: Photo of			to of pl	ant effluent				



Arkansas Department of Environmental Quality (ADEQ) Official Photograph Sheet

Location: Harrison POTW										
Photograp	Bruce Kirkpatrick			Witness: None						
Photo #	3	3 of 4 Date: 3-29-2011 Time: 1502						1502		
Description: Photo of plant effluent										



Photograp	her:	Bru	ce Kirk	patrick	Witness	ss: none		
Photo #	4	of	4		Date:	3-29-2011	Time:	1503
Description: Photo of plant of				ant affluent				

Description: Photo of plant effluent





Google Earth image of the area showing locations of water quality monitoring stations and the POTW