AFIN: 61-00055

Permit #: AR0034835

€EPA									Form Approved OMB No. 2040-0003	
UNITED STATES ENVIRONMENTAL PROTECTION AGENCY										
NPDES Compliance Inspection Report										
Section A: National Data System Coding										
1 N 2 5 3 A R 0 0 3 4 8 3 5 11 12 1 1 0 8 1 7 17 18									Inspector Fac. Type   R 19 S 20	
Remarks       Inspection Work Days     Facility Evaluation Rating     BI     QA								-Reserved		
	67 69	-	70 <b>N</b>	71	1 1	72 <b>N</b> 73	1 1 1	74 75	80	
Section B: Facility Data										
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number)Entry Time/Date 0920 8/17/2011City of Pocahontas WWTP0920 8/17/2011								Permit Effective Date 4/1/2009		
~0.4 mi. south of Swan Cove intersection with Black River Pocahontas, AR Randolph Co.						Exit Time 1000 8/1			Permit Expiration Date 3/31/2014	
Bill Daniel/Manager/870-892-3222								her Facility Data		
									5.240997 0.97981	
Bill Daniel/Manager/870-892-3222 Pocahontas Water and Sewer System							Contacted Co		omp#: 012785	
207 1	Hwy. 67 South hontas, AR 72455					ısp#: 061770				
Section C: Areas Evaluated During Inspection (S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)										
S	Permit	N Flow Measurement		nt	M Operations & Maintenance		Ν	Sampling		
Ν	Records/Reports	Ν	Self-Monitoring P	Program	Ν	Sludge Handl	idge Handling/Disposal		Pollution Prevention	
Ν	Facility Site Review	Ν	Compliance Schee	dules	Ν	Pretreatment	etreatment		Multimedia	
Ν	Enluent/Receiving waters Laboratory							Μ	Other: SSO	
Section D: Summary of Findings/Comments (Attach additional sheets if necessary)										
This inspection was conducted in response to a complaint alleging an overflowing manhole at 1120 Hillcrest Cv., Pocahontas, AR. On the afternoon of 8/16/2011, I spoke with Pocahontas Water and Sewer System Manager – Bill Daniel regarding the complaint. Mr. Daniel advised he would investigate. On the morning of 8/17/2011, I met with Mr. Daniel and visited the location of the complaint. Mr. Daniel advised that the manhole was overflowing the previous day due to a blockage in the city's main and there had been some prior confusion regarding the responsibility for maintaining this manhole, but it was ultimately determined to be the city's responsibility. Mr. Daniel stated that they had removed the blockage and would report the overflow as required by the permit. At the time of my visit, the manhole appeared to be flowing properly and no further action was required.										
Nam Bren	e(s) and Signature(s) of Inspector(s t L. Walker Bud L Walk	Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Jonesboro (870) 935-7221 ext. 12/(870) 935-4715 (Fax)					Date September 19, 2011			
Sign	ature of Reviewer	Agency/Office/Phone and Fax Numbers					Date			