

June 1J, 2012

Northwest Arkansas Regional Solid Waste Management District C/o Melinda Caldwell **VIA Recyclables** 927 West Rush Street Harrison, AR 72601

RE: Quarterly Inspection; AFIN 03-00208 Permit Number 0022-SWTP

Dear Ms. Caldwell:

On June 18, 2012 I performed a routine inspection of your facility pursuant to the Arkansas Waste Tire Program, Reg. 14, and the above referenced permit. A copy of the inspection report is enclosed for your review.

Please refer to the attached inspection report to note the specific allegations. A written response for the noted allegations, describing the corrective action taken or to be taken, must be submitted to my attention at the address listed below within thirty (30) days from the date hereof. Failure to submit the written response shall be construed as an admission of any allegations. Any items noted that are neglected and/or persistent may warrant formal enforcement action.

If I can be of any further assistance, feel free to contact me at (870-424-3322).

Sincerely,

willer-

Gary Meador, Inspector Solid Waste Management Division

Ofccæ&@ ^} c А Ô& KÁU& [ ccÁT & Y á]| ãæ {•ÊÂU Y ÁO} - { | & ^} cÁO [ [ | å ð] æ [ | ÁXXXXXQEEÃAÖ[ | [ à accaÉAÓ] \* ā ^^ | ÁQÁ



## Arkansas Department of Environmental Quality Solid Waste Management Division Waste Tire Processing Facility Inspection



- 194	anagement													
Site Na	ame	NV	NWARSWMD			County		Baxter		AFIN		03-00208		
Facility Address		s CF	Mtn. Home, Hwy. 201 N. to CR831 to CR 782 to the Damco Site Project.		Telephone Number			870-741-7026		rmit 0022 mber		22-SWTP		
Permittee Address 1 927 West Rijsh Street				E-Mail Addres										
Date	6-18-12		Entry Time	1000		Exit	Exit Time 1120 Follow-Up					Yes	No X	
Regulation 14 - Operational Standards														
Category 1   First Violation: Score of 1     Second Violation: Score of 2   Third Violation: Score of 4     Sign posted with required information 14.1402(F)   Waste tires stored separately from used tires 14.1402(B)					the	<b>Comments</b> The Solid Waste District has ceased all operations at the waste tire processing facility. They have contracted								
	Records maintained and available   14.1207     Category 2   First Violation: Score of 2 Second Violation: Score of 4 Third Violation : Score of 8     Emergency preparedness manual on site and updated   14.1402(N)     Communication equipment maintained on site   14.1210; 14.1402(L)     Site kept free of vegetation   14.1402(M)     Residuals disposed or recycled   14.1402(R)     8   Mosquito and rodent control   14.1209; 14.1402(E)     Passable access roads at all times   14.1402(H)					with Champlain Tire Recycling out of Kansas, to pickup, transport, and recycle waste tires. Some of the processed tire bales are stored on the Damco Site Project.								
8						I called Melinda Caldwell and left a voice mail message covering the inspection report. I stated that the site conditions have not changed since the last inspection conducted on 1-19-12.								
8	Site bermed for runoff control   14.1402(J)     Waste tire pile within maximum dimensions   14.1402(C)     Access to the site controlled   14.1402(I)     Processed tires meet storage criteria   14.1204     Department notified of emergency   14.1402(O)					Conducted on 1-19-12. There was a malfunction of the camera therefore the pictures do not have a date stamp.								
12	Category 3   First Violation : Score of 3 Second Violation : Score of 6 Third Violation : Score of 12     Fire protection services assured   14.1402(K)     Operations involving use of open flames prohibited   14.1402(G)     12   Facility operates in accordance with permit documents   14.1201     Fifty foot wide fire lanes and unobstructed   14.1402(D)					0 - 8 Satisfactory 9 - 13 Marginal 214 Unsatisfactory 28					SCORE			
					lation	14 -	- Red	cords				20		
14.1402	(N)	Date of last	revision/update to e					rch 2005						
14.1207 Quantity of waste tires/processed tires received														
14.1207 Quantity of waste tires stored on site				4000 Bales x 100 tires per bale = 400,000 tires										
14.1207 Quantity of waste tires shipped from site														
14.1215	14.1215 Date of last annual report					3-1-10 for 2009								
Operator Name & Number Site Closed No Operator Available Signature of Inspector														

FOR ADEQ USE ONLY

Arkansas Department of Environmental Quality Solid Waste Management Division Comments Page



"Ste Managemen"									
Site Name	NWARSWMD	AFIN	03-00208	Permit Number	0022-SW	ГР			
Category 2 Comments       Mosquito and rodent control     14.1209 Vector Control; 14.1402(E) Outdoor Above -Ground Tire Storage       Vector Control: An approved vector control program must be operational at all times for tires stored outdoors.       The owner or operator shall develop and implement a program to control mosquitoes and rodents or request such control measures from the local mosquito and vector control office, so as to protect the public health and welfare.       Mosquito control measures may include covering containers and trailers used for the collection and storage of waste tires with a tarp or placing them under some type of constructed cover during inclement weather and/or when the business is closed.       Comments:     There were no evident signs of any mosquito or rodent control measures implemented at the site.									
Category 2CommentsProcessed tires meet storage criteria14.1204The storage limit for processing facilities is thirty (30) times the daily capacity of the processing equipment used. Comments: According to the Baling Contractor the daily capacity of the processing equipment was approximately 2000 tires a day. Based on the daily capacity of the processing equipment maximum storage capacity for the facility would be 									
	Cato	aory 3 Com	monte						
Category 3 Comments     Facility operates in accordance with permit documents 14.1201     Waste tire processing facilities shall obtain a permit and shall meet the requirements contained in this regulation for waste tire processing facilities (Waste Tire Processing Facility Requirements) or shall meet the general permit requirements contained in this regulation.     Reg.14.1215   Annual Reporting     Owners and operators of waste tire processing facilities shall submit to the Department an annual report by March 1 that summarizes information on facility activities. The report shall be submitted to the Department on Form TP5 (Waste Tire Processing Facility Annual Report).     Comments:   There has been no Annual Report submitted for 2010 or 2011.									
Signature of Inspec	ctor Jan Meado	Inspection	on Date	6-18-12	Page	2			

COMPLIANCE

Arkansas Department of Environmental Quality Solid Waste Management Division Comments Page										
Site Name	NWARSWMD	AFIN	03-00208	Permit Number	0022-SWTP					
Category 3 Comments     Facility operates in accordance with permit documents 14.1201     Site Specific Permit Conditions, Number 1: Financial Assurance     Financial assurance shall be provided and maintained based on Appendix B of Regulation Number 14. The amount of financial assurance is \$57,000 and shall be established and approved by the Department prior to the processing of the waste tires. This amount is subject to annual adjustment and may be increased at the discretion of the Department based on the cost for a third party to close the facility in accordance with an approved closure plan and with the guidelines set forth in Section 18 of Regulation Number 14. The amount of financial assurance is to be maintained and comply with the requirements of Regulation Number 14. Financial assurance amounts must be maintained at all times in order to cover the provisions of the Act and Regulation Number 14.     Comments:     No records found on file with ADEQ indicating financial assurance has been provided for the Facility.										
	Catego		nments	<u></u> .						
Category Comments										
Signature of Inspe	ctor Janmana	Inspecti	on Date 6-1	8-12	Page	3				







