

April 8, 2013

Lisa Bowling Graphic Flexible Packaging PO Box 20700 Pine Bluff, AR. 71612

RE: Quarterly Inspection; AFIN 35-00017 Permit Number 0243-S3N-R2

Dear: Mrs. Bowling,

On April 2, 2013, I conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, and the above-referenced permit. A copy of the inspection report is enclosed for your records. At the time of the inspection, there were no violations noted on the inspection report.

If I can be of any further assistance, feel free to contact me at (870) 247-5155.

Sincerely,

Addy Tentry

Bobby Gentry, ADEQ Inspector Solid Waste Management Division

Attachment



## Arkansas Department of Environmental Quality Solid Waste Management Division Class 3 Landfill Inspection



Site Name		Graphic Flexible Packaging	County	Jefferson	AFIN	35-00017						
Facility Address		North of Pine Bluff in the Industrial Park	Phone Number	870-541-5046	Permit Number	0243-S3N-R2						
Permittee Address		P.O. Box 20700, Pine Bluff, AR 71612	E-Mail Address	None	1 crime reamber	<b>PDS</b> # 070967						
Date		4-2-13	Entry Time	9:00 am	Exit Time	10:00 am						
<i>D</i> .	ite	Dogwlotion		nal Ctandanda	Latt Time							
Regulation 22 – Operational Standards												
X R	Depicts Violation Repeat Violation		Category 1	gory 1								
	Regulation	Item Description			Comments							
	510(l)	Adequate employee facilities										
	520(a)(b)	Record keeping meets requirements specified by regulations										
	516	Access requirements										
	510(j)	Adequate provisions for backup equipment										
	520(c)	Waste receipt records, ticket system maintained										
	510(k)	Telephone system & written emergency response plan on site										
	522(a)	Annual compliance inspection by register professional enginee	r									
	521	Facility implements operating plan and narrative										
	520(a)(4)	Leachate disposal/recirculation records										
	701, 520(a)(2)	Special waste disposal and procedures records										
X	Depicts Violation Repeat Violation	Category 2										
	Regulation	Item Description			Comments							
	510(a)	Operations in accordance with permit documents										
	516(c)	Adequate all weather operational roads										
	510(c)	Smallest practical area, unloading supervised, single working	face									
	510(e)	Salvage operations meet approved conditions										
	510(f)(l)	Scavenging of waste prohibited										
	510(o)	Proper wet weather repairs										
	510(b)	Operations by licensed on-site personnel at all times										
	510(d)	Waste spread and compacted as unloaded										
	510(g)	Litter control provisions maintained										
	513(a)	Disease vectors controlled										
			'									

				Categ	ory	2 (continued)			
	Regulation	Tt.	em Description					Comi	ments
	518	Surface water controls					Com		
	510(h)(l)	Contouring prevents surfa	Contouring prevents surface water flowing into or through w						
	517(a)(b)	= =	Run-on/off control system present and adequate						
	510(h)(2)	Surface water control prevents off-site sediment accumulation		ulation					
	510(h)(i)	Adequate maintenance of intermediate/final cover vegetation							
	514	Gas monitoring program							
	510(n)	Leachate leaks or evidence of leachate seepage							
	526	Survey controls							
	529	Leachate collection system	1						
	519	Liquid restrictions							
X	Depicts Violation	Elquia restrictions		<u> </u>		2			
R	(Repeat Violation)	Category 3							
	Regulation	Item Description						Comi	ments
	511	Implementation of hazardous/unauthorized waste exclusion plan							
	512(a)(c)	Satisfactory daily/alternat	tive cover						
	512(b)	Satisfactory intermediate cover							
	515(b),510(f)(4)	Open burning prohibited							
	518	Cause discharge/leachate discharge leaving landfill							
	510(f)(3).518(a)(4)	Depositing waste in standing water prohibited							
	510(n)	Erosion or other cover de	fects resulting in exposed refu	ulting in exposed refuse					
	309(c)	Overfill/off lined area							
			Re	gulation	22 -	Records			
520(a)(8), 204(b) Date of last groundwater monitoring report			12-31-12						
522				June 2012					
528				Notice of lin	er co			Third part CQ	A on-site during construction Yes/No No
511 514,520(a)(3)		Date of last random inspection for unauthorized waste  Date of last quarterly methane monitoring  None		Every load		Total # for month Detection level	March	514	Explosive gas records current? Yes/No
701, 520(a)(2)				none		Disposal location		514	Explosive gas records current:
520(c)		Previous quarter waste received 277.19				Tons	1st QTR 2	013	
		Surface water DMR records current? Yes/No Yes							
	erator Name &				Sig	nature of Inspector			Tentry
Ex	it Interview Con	ducted with Keith Swillin	ng	Method	On-	site	Date	4-2-13	<b>Time</b> 9:45 am

1&2



