



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Washington, D.C. 20460

NPDES Compliance Inspection Report

Form Approved
OMB No. 2040-0003

Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspec. Type	Inspector	Fac. Type
1 N 2 5 3 A R 0 0 3 3 7 6 6 11 12 1 3 0 4 1 5 17 18 R 19 S 20 1					
Remarks					
<div style="display: flex; justify-content: space-between;"> Inspection Work Days Facility Evaluation Rating BI QA -----Reserved----- </div>					
67		69	70 N	71 N 72 N 73	74 75

Section B: Facility Data

Name and Location of Facility Inspected (<i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i>) Paragould Light, Water and Cable WWTP 401 Grant Ln. Paragould, AR Greene Co.	Entry Time/Date 4/15/2013 1335	Permit Effective Date 2/1/2010
	Exit Time/Date 4/15/2013 1445	Permit Expiration Date 1/31/2015
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Lisa Ellington/Manager - Environmental Services/870-239-7795	Other Facility Data <u>MAJOR MUNICIPAL</u>	
Name, Address of Responsible Official/Title/Phone and Fax Number Darrell Phillips/Assistant General Manager/870-239-7700 Paragould Light, Water and Cable P.O. Box 9 Paragould, AR 72450	Contacted Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

S	Permit	N	Flow Measurement	S	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	S	Other: SSO

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

This reconnaissance inspection was conducted in conjunction with a complaint investigation at 915 Grayson St., Paragould, AR. Overflows from multiple cleanouts had resulted due to a blockage in the customer's line serving the apartments located at the aforementioned address. There was no malfunction in the PLWC system. At the time of the investigation/inspection, the cleanout caps were removed from the risers. This matter was referred to Lisa Ellington with PLWC, who immediately contacted the PLWC staff responsible for the operation and maintenance of the collection system to require corrective action by the property owner to prevent the introduction of foreign materials into the collection system and unnecessary inflow during rain events. No permit violations were noted and no further action is required. No letter will be sent.

Name(s) and Signature(s) of Inspector(s) Brent L. Walker <i>Brent L. Walker</i>	Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Jonesboro (870) 935-7221 ext. 12/(870) 935-4715 (Fax)	Date 4/15/2013
Signature of Reviewer J. Bolenbaugh <i>J. Bolenbaugh</i>	Agency/Office/Phone and Fax Numbers ADEQ	Date 4/19/2013

ADEQ Water NPDES Inspection

AFIN: **28-00470**

Permit #: **AR0033766**