

ADEQ

ARKANSAS
Department of Environmental Quality

September 13, 2013

Kirby Murray, Public Works Director
City of Berryville
P.O. Box 227
Berryville, Arkansas 72616

RE: Reconnaissance Inspection (Carroll Co)
AFIN: 08-00034 **NPDES Permit No.: AR0021792**

Dear Mr. Murray:

On September 10, 2013, I performed a reconnaissance inspection of the above referenced facility in response to a complaint in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. The complainant alleged that he periodically experienced bad odors at his home in the Paradise Heights Subdivision near the lift station. This inspection revealed that a sanitary sewer overflow occurred at the Paradise Heights Lift Station on the afternoon of September 9, 2013. The overflow was stopped, the lift station was repaired, the affected area was cleaned/disinfected and the overflow was reported to the Department prior to this inspection. No further action regarding this violation is required at this time. No offensive odors were observed at the time of the inspection.

If I can be of any assistance, please contact me at (870) 446-6170 or by e-mail at Kirkpatrick@adeq.state.ar.us.

Sincerely,



Bruce Kirkpatrick
District 2 Field Inspector
Water Division



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Washington, D.C. 20460

NPDES Compliance Inspection Report

Form Approved
OMB No. 2040-0003

Section A: National Data System Coding

Transaction Code	NPDES	Yr/Mo/Day	Inspec. Type	Inspector	Fac. Type
1 <input type="text" value="N"/> 2 <input type="text" value="5"/> 3 <input type="text" value="A"/> <input type="text" value="R"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="2"/> <input type="text" value="1"/> <input type="text" value="7"/> <input type="text" value="9"/> <input type="text" value="2"/>	11 <input type="text" value="1"/> 12 <input type="text" value="3"/> <input type="text" value="0"/> <input type="text" value="9"/> <input type="text" value="1"/> <input type="text" value="0"/>	17 <input type="text" value="R"/>	18 <input type="text" value="R"/>	19 <input type="text" value="S"/>	20 <input type="text" value="1"/>
Remarks					
<input type="text" value="A"/> <input type="text" value="F"/> <input type="text" value="I"/> <input type="text" value="N"/> <input type="text" value="0"/> <input type="text" value="8"/> <input type="text" value="-"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="3"/> <input type="text" value="4"/>					
Inspection Work Days	Facility Evaluation Rating	BI	QA	-----Reserved-----	
67 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> 69	70 <input type="text" value="N"/>	71 <input type="text" value="N"/>	72 <input type="text" value="N"/>	73 <input type="text" value=""/> <input type="text" value=""/>	74 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> 75 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> 80

Section B: Facility Data

Name and Location of Facility Inspected (<i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i>) City of Berryville 1000 W. Cedarvale Berryville, Arkansas	Entry Time/Date 1442 / 9-10-2013	Permit Effective Date December 1, 2007
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s) Kirby Murray, Public Works Director	Exit Time/Date 1536 / 9-10-2013	Permit Expiration Date November 30, 2012 (extended)
Name, Address of Responsible Official/Title/Phone and Fax Number Kirby Murray, Public Works Director City of Berryville P.O. Box 227 Berryville, Arkansas 72616 870-423-4074, 870-423-4501 (fax)	Contacted Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Other Facility Data PDS# 073558

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

N	Permit	N	Flow Measurement	N	Operations & Maintenance	N	Sampling
N	Records/Reports	N	Self-Monitoring Program	N	Sludge Handling/Disposal	N	Pollution Prevention
N	Facility Site Review	N	Compliance Schedules	N	Pretreatment	N	Multimedia
N	Effluent/Receiving Waters	N	Laboratory	N	Storm Water	U	Other: Collection System

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

A reconnaissance inspection was performed on 9-10-2013 in response to a complaint. Mr. Kirby Murray was present. The complainant alleged that he periodically experienced bad odors at his home in the Paradise Heights Subdivision near the lift station. This inspection revealed that a sanitary sewer overflow occurred at the Paradise Heights Lift Station on the afternoon of September 9, 2013. An estimated 300 gallons of wastewater overflowed the lift station before the overflow was stopped at 1630. The overflow was stopped, the lift station was repaired, the affected area was cleaned/disinfected and the overflow was reported to the Department in accordance with permit requirements prior to this inspection. No offensive odors were observed at the time of the inspection. No further action regarding this violation is required at this time.

Name(s) and Signature(s) of Inspector(s) Bruce Kirkpatrick <i>Bruce Kirkpatrick</i>	Agency/Office/Telephone/Fax AR Dept. of Environmental Quality-Jasper PHONE# (870) 446-6170 / FAX# (870) 446-2181	Date September 12, 2013
Signature of Reviewer Kerri McCabe <i>Kerri McCabe</i>	Agency/Office/Phone and Fax Numbers ADEQ / NLR / 501-682-0642	Date September 13, 2013

Water Division NPDES Photographic Evidence Sheet

Location:	City of Berryville						
------------------	--------------------	--	--	--	--	--	--

Photographer:	Bruce Kirkpatrick	Witness:	None		
----------------------	-------------------	-----------------	------	--	--

Photo #	1	of	2	Date:	9/10/2013	Time:	1513
----------------	---	-----------	---	--------------	-----------	--------------	------

Description:	Paradise Heights Lift Station.						
---------------------	--------------------------------	--	--	--	--	--	--



Photographer:	Bruce Kirkpatrick	Witness:	None		
----------------------	-------------------	-----------------	------	--	--

Photo #	2	of	2	Date:	9/10/2013	Time:	1514
----------------	---	-----------	---	--------------	-----------	--------------	------

Description:	Paradise Heights Lift Station.						
---------------------	--------------------------------	--	--	--	--	--	--

