

January 21, 2014

Amber Zajac Graphic Flexible Packaging PO Box 20700 Pine Bluff, AR. 71612

RE: Quarterly Inspection; AFIN 35-00017 Permit Number 0243-S3N-R2

Dear: Mrs. Zajac,

On January 16, 2014, I conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, and the above-referenced permit. A copy of the inspection report is enclosed for your records. At the time of the inspection, there were no violations noted on the inspection report.

If I can be of any further assistance, feel free to contact me at (870) 247-5155.

Sincerely,

Addy Tentry

Bobby Gentry, ADEQ Inspector Solid Waste Management Division

Attachment

www.adeq.state.ar.us



## Arkansas Department of Environmental Quality Solid Waste Management Division Class 3 Landfill Inspection



Sit	te Name	Graphic Flexible Packaging	County	Jefferson	AFIN	35-00017					
<b>Facility Address</b>		North of Pine Bluff in the Industrial Park	Phone Number	e Number 870-541-5046 Permit Num		0243-S3N-R2					
<b>Permittee Address</b>		P.O. Box 20700, Pine Bluff, AR 71612	E-Mail Address	None		<b>PDS</b> # 075637					
Date		1-16-14	Entry Time	9:45 am	Exit Time	11:00 am					
Regulation 22 – Operational Standards											
X	Depicts Violation	Category 1									
R	Repeat Violation Regulation	Item Description		Comments							
	510(1)	Adequate employee facilities			Comments						
	520(a)(b)	Record keeping meets requirements specified by regulations									
	516	Access requirements									
	510(j)	Adequate provisions for backup equipment									
	520(c)	Waste receipt records, ticket system maintained									
	510(k)	Telephone system & written emergency response plan on site									
	522(a)	Annual compliance inspection by register professional engineer	•								
	521	Facility implements operating plan and narrative									
	520(a)(4)	Leachate disposal/recirculation records									
	701, 520(a)(2)	Special waste disposal and procedures records									
X	Depicts Violation	Category 2									
R	Repeat Violation Regulation	Item Description			Comments						
	510(a)	Operations in accordance with permit documents			Comments						
	516(c)	Adequate all weather operational roads									
	510(c)	Smallest practical area, unloading supervised, single working f	ace								
	510(e)	Salvage operations meet approved conditions									
	510(f)(l)	Scavenging of waste prohibited									
	510(o)	Proper wet weather repairs									
	510(b)	Operations by licensed on-site personnel at all times									
	510(d)	Waste spread and compacted as unloaded									
	510(g) Litter control provisions maintained										
	513(a)	Disease vectors controlled									
	ı										

					Categ	ory	2 (continued)				
	Regulation		Item Description			Comments					
	518	Surface wat									
	510(h)(l)	Contouring	Contouring prevents surface water flowing into or through								
	517(a)(b)	Run-on/off	Run-on/off control system present and adequate								
	510(h)(2)	Surface wat	Surface water control prevents off-site sediment accumu		ulation						
	510(h)(i)	Adequate m	Adequate maintenance of intermediate/final cover vegetation		tation						
	514	Gas monito	Gas monitoring program								
	510(n)	Leachate lea	Leachate leaks or evidence of leachate seepage								
	526	Survey cont	rols								
	529	Leachate co	llection system								
	519	Liquid rest	rictions								
X	<b>Depicts Violation</b>	Category 3									
R	(Repeat Violation)					801.			Commo	omta	
	Regulation	T 1	Item Description			Comments					
	511	_	Implementation of hazardous/unauthorized waste exclusion plan								
	512(a)(c)		Satisfactory daily/alternative cover								
	512(b)	·	Satisfactory intermediate cover								
	515(b),510(f)(4)		Open burning prohibited								
	518		Cause discharge/leachate discharge leaving landfill								
	510(f)(3).518(a)(4)		Depositing waste in standing water prohibited								
	510(n)		er cover defects resulting in exposed refuse								
	309(c)	Overfill/off	lined area								
				Reg	gulation	22 -	Records				
52			Date of last groundwater monitoring report 12-19-13								
522			Date of last engineering report June 2013				X7 /NY	37 .		A. J. A. W. Di. M.	
528					ier co	er construction Yes/No No Third part CQA on-site during construction Yes/No No					
511 514,520(a)(3)			Date of last random inspection for unauthorized waste  Every load Date of last quarterly methane monitoring  None			Total # for month  Detection level	December 514 Explosive gas records current? Yes/No				
701, 520(a)(2)					none		Disposal location	514 Explosive gas records current? Yes/No			
520(c)		Previous quarter waste received 302.85				Tons	4th QTR 2013				
	527		Surface water DMR records current? Yes/No Yes				10115	2111	2010		
	perator Name &	Number	Keith Swilling Lic: #				nature of Inspector	_	Bdly.		
Exit Interview Conducted with Keith Swilling				Method	On-	site	Date	1-16-14	<b>Time</b> 10:45 am		



