ADEQ
ARKANSAS
Department of Environmental Quality

July 31, 2014

The Honorable Mike Jacobs
Johnson County Judge
P.O. Box 278
Clarksville, AR 72830

RE: Quarterly Inspection; AFIN 36-00089; Permit Number 0278-S4-R1

Dear Judge Jacobs:

On July 24, 2014, I conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, and the above-referenced permit. A copy of the inspection report is enclosed for your records.

Please refer to the attached inspection report to note the specific allegations. A written response for the noted allegations, describing the corrective action taken or to be taken, must be submitted to my attention at the address listed below within thirty (30) days from the date hereof. Failure to submit the written response shall be construed as an admission of any allegations. Any items noted that are neglected and/or persistent may warrant formal enforcement action.

If I can be of any further assistance, feel free to contact me at (479) 424-0326.

Sincerely,

Justin Sparrow, ADEQ Inspector
Solid Waste Management Division

Attachment

Arkansas Department of Environmental Quality
Solid Waste Management Division
Class 4 Landfill Inspection

Site Name	Johnson County Class IV	**County**	Johnson	**AFIN**	36-00089
Facility Address	3.5 Miles West of Clarksville on JCR 261	**Phone Number**	479-754-2175	**Permit Number**	0278-S4-R1
Permittee Address	P.O. Box 278, Clarksville, AR 72830	**E-Mail Address**		**PDS #**	079055
Date	7-24-14	**Entry Time**	1200	**Exit Time**	1330

Regulation 22 – Operational Standards

Category 1

X = Depicts Violation; R = Repeat Violation

	Regulation	Item Description	Comments
	607(l)	Adequate employee facilities	
	617(a)(b)	Record keeping meets requirements specified by regulations	
	613	Access requirements	
	607(j)	Adequate provisions for backup equipment	
	617(c)	Waste receipt records, ticket system maintained	
	607(k)	Telephone system & written emergency response plan on site	
	619(a)	Annual compliance inspection by registered professional engineer	
	618	Facility implements operating plan and narrative	
	701	Special waste disposal and procedures records	

Category 2

X = Depicts Violation; R = Repeat Violation

	Regulation	Item Description	Comments
	607(a)	Operations in accordance with permit documents	
	613(c)	Adequate all weather operational roads	
	607(c)(d)	Smallest practical area, single working face	
	607(e)	Salvage operations meet approved conditions	
	607(f)(1)	Scavenging of waste prohibited	
	613 (c)	Proper wet weather repairs	
	607(b)	Operations by licensed on-site personnel at all times	
	607(d)	Waste spread and compacted as unloaded	
	607(g)	Litter control provisions maintained	
	610(a)	Disease vectors controlled	
	611	Gas monitoring program	
	622	Survey controls	

Category 2 (continued)

	Regulation	Item Description	Comments
	623	Surface water controls	
	607(h)(1)	Contouring prevents surface water flowing into or through waste	
	614(a)	Run-on/off control system present and adequate	
X	607(h)(2)	Surface water control prevents off-site sediment accumulation	Lack of vegetation noted on Intermediate cover NE of the working face (See Photos 3 & 4)
	607(h)(i)(o)	Adequate maintenance of intermediate/final cover vegetation	
	607(o)	Leachate leaks or evidence of leachate seepage	
	616	Liquid restrictions	


X Depicts Violation
R (Repeat Violation)

Category 3

	Regulation	Item Description	Comments
	608	Implementation of hazardous waste exclusion plan	
	609(a)	Satisfactory weekly or more frequent cover	
	609(b)	Satisfactory intermediate cover	
	612(b),607(f)(4)	Open burning prohibited	
	615	Cause discharge/leachate discharge leaving landfill	
	607(f)(3),615(a)(4)	Depositing waste in standing water prohibited	
	607(o)	Erosion or other cover defects resulting in exposed refuse	
	309(c)	Overfill/off lined area	

Regulation 22 - Records

617(a)(4), 621(e)	Date of last groundwater monitoring report			Na							
619	Date of last engineering report	7-26-14									
617(a)(4)	Liner construction in progress	Yes/No	No	Notice of liner construction	Yes/No	Na	Third part CQA on-site during construction	Yes/No	Na		
608	Date of last random inspection for unauthorized waste			7-24-14	Total # for month	20					
611	Date of last quarterly methane monitoring			Na	Detection level	Na	611	Explosive gas records current?	Yes/No	Na	
701	Date of last special waste received			Na	Disposal location	Na					
617(c)	Previous quarter waste received				Tons	217					
623	Surface water DMR records current	Yes/No		unknown							

Operator Name & Number	Robert Hudspeth			Signature of Inspector			
Exit Interview Conducted with	Robert Hudspeth	Method		Date	7-24-14	Time	1330

Class 4 Form 7/1/2012

For ADEQ Use Only

Permit Number 0278-S4-R1
Photos 1 & 2





Permit Number 0278-S4-R1
Photos 3 & 4



