



Arkansas Department of Environmental Quality Solid Waste Management Division Other Report Form



Activity	Voided Facility Inspection	PDS ID	081068
Site Name	Arkansas Kraft Class 3	County	Conway
Location	35° 05' 11.69089", 92° 43' 43.79066" 338 Hwy 113 Morrilton, AR 72110	Date	11/20/2014

COMMENTS

Voided Permit # 0176-SR-2 AFIN 15-00001

On November 20, 2014, I inspected the closed and voided Arkansas Kraft Class 3 Landfill site. The property is shared by the currently operating Green Bay Packaging Class 3 Landfill (0284-S3N). This inspection was conducted in conjunction with the 4th Quarter 2014 inspection of the Green Bay Facility. Hay across the landfill surface had been recently mowed. Leachate risers & pumps are still in place and operating as needed. The majority of the landfill surface was viewable. No major areas of settling were noted. No exposed wastes or major cover defects were noted other than a small leachate seep on the northern slope (immediately south of the currently active cell). This leachate seep was also noted on the active facility's inspection to be addressed. An aerial photo, a site plan map, and photos taken during the inspection are included with this report.

Signature of Inspector		Date	11/20/2014
-------------------------------	---	-------------	------------

Voided AR Kraft Class 3 Landfill

Photo 1 & 2



Voided AR Kraft Class 3 Landfill

Photo 3 & 4



Voided AR Kraft Class 3 Landfill

Photo 5 & 6



Voided AR Kraft Class 3 Landfill

Photo 7 & 8



Voided AR Kraft Class 3 Landfill

Photo 9 & 10



Voided AR Kraft Class 3 Landfill

Photo 11 & 12



Voided AR Kraft Class 3 Landfill

Photo 13 & 14



Voided AR Kraft Class 3 Landfill


Photo 15 & 16



Voided AR Kraft Class 3 Landfill

Photo 17 & 18





EXISTING CLASS III LANDFILL

PROPOSED CLASS III LANDFILL

Depth To Bedrock

Scale 1 in = 1257 Ft

Contour interval = 2 Ft

CONWAY CO
PERRY CO

Candrill Creek

Gravel Pit X

Press Creek

