



Arkansas Department of Environmental Quality Solid Waste Management Division Other Report Form



Activity	Voided Facility Inspection	PDS ID	081994
Site Name	Entergy/Nuclear One Class 3	County	Pope
Location	35°18'58.70"N, 93°14'4.44"W Nuclear One 1448 SR 333; Russellville, AR	Date	1/21/2015

COMMENTS

Voided Permit # 0184-S AFIN 58-00002

On January 21, 2015, I inspected the voided Entergy Class 3 Landfill site on the grounds of Nuclear One in Russellville. I was accompanied to the site by Larry Cook of Nuclear One's environmental staff. The landfill area is located on the northern portion of the Nuclear One property. The site is primarily covered by grassy/weedy vegetation between 6 to 12 inches tall with some sporadic tree growth throughout. No exposed waste, erosion, or leachate leaks were noted. Slopes on the landfill area are minimal and no erosion was noted on the slopes. A few small areas of ponded water were noted, mostly at the base of the slopes. On the eastern ¼ of the landfill, signs noting the presence of buried asbestos containing materials are still posted. Two groundwater monitoring wells are located just outside of the western boundaries of the landfill area. According to Mr. Cook, these wells are still routinely sampled.

An aerial photo and photos taken during the inspection are included with this report.

Signature of Inspector		Date	1/21/2015
-------------------------------	---	-------------	-----------

Permit # 0184-S

Voided Entergy Class 3

Photo 1 & 2



Permit # 0184-S

Voided Entergy Class 3

Photo 3 & 4



Permit # 0184-S

Voided Entergy Class 3

Photo 5 & 6



Permit # 0184-S

Voided Entergy Class 3

Photo 7 & 8



Permit # 0184-S

Voided Entergy Class 3

Photo 9 & 10



Permit # 0184-S

Voided Entergy Class 3

Photo 11 & 12



Permit # 0184-S

Voided Entergy Class 3

Photo 13 & 14



Permit # 0184-S

Voided Entergy Class 3

Photo 15 & 16



Permit # 0184-S

Voided Entergy Class 3

Photo 17 & 18





Google earth

