

 A R K A N S A S Department of Environmental Quality		WATER DIVISION INSPECTION REPORT							
		AFIN: 36.00038		PERMIT #: AR0022187		DATE: 10/1/2015			
		COUNTY: 36 Johnson			PDS #: 087440		MEDIA: WN		
		GPS LAT:		LONG:		LOCATION: N/A			
FACILITY INFORMATION				INSPECTION INFORMATION					
NAME: Hanesbrand LOCATION: 1904 Clark Rd. CITY: Clarksville, AR				FACILITY TYPE: 2 - Industrial		INSPECTOR ID#: 26588 S - State			
RESPONSIBLE OFFICIAL NAME / TITLE: John Lester / General Manager COMPANY: Clarksville Light & Water Co MAILING ADDRESS: P.O. Box 1807 CITY, STATE, ZIP: Clarksville AR 72830 PHONE & EXT: / FAX: / EMAIL:				FACILITY EVALUATION RATING: N		INSPECTION TYPE: Industrial User			
				DATE(S): 10/1/2015		ENTRY TIME: 10:40		EXIT TIME: 11:50	
								PERMIT EFFECTIVE DATE: 10/1/2014 PERMIT EXPIRATION DATE: 9/30/2019	
CONTACTED DURING INSPECTION: ***				FAYETTEVILLE SHALE RELATED: N FAYETTEVILLE SHALE VIOLATIONS: N					
INSPECTION PARTICIPANTS									
NAME/TITLE/PHONE/FAX/EMAIL/ETC.: Gregg Rainey / Pollution Control Facility Superintendent / 479-979-5509 Pam Smith / Lab Superintendent & Pretreatment Coordinator / 479-754-7229 Cathey Stalcup / Hanesbrand / EH&S / 479-979-3419									
AREA EVALUATIONS									
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)									
N	PERMIT	N	FLOW MEASUREMENT	N	STORMWATER	N	RECORDS/REPORTS		
N	OPERATION & MAINTENANCE	N	LABORATORY	N	FACILITY SITE REVIEW	N	EFFLUENT/RECEIVING WATER		
N	SAMPLING	N	SLUDGE HANDLING/DISPOSAL	S	PRETREATMENT	N	OTHER:		
**									
SUMMARY OF FINDINGS									
No permit violations were noted during this inspection.									
GENERAL COMMENTS									
Clarksville Light & Water Company employees operate the pretreatment plant. The plant appeared to be in good operating order.									
INSPECTOR'S SIGNATURE: 				Tony L. Morris		DATE: 10/7/2015			
SUPERVISOR'S SIGNATURE: 				Kerri McCabe		DATE: 10/30/2015			

PRETREATMENT COMPLIANCE INSPECTION

IU SITE VISIT FORM

Name of Industry: **Hanesbrand**

POTW Name: **Clarksville POTW**

Industry Contacts: **Cathey Stalcup**

Date and Time of Visit: **10/1/2015, 10:40**

Description of Manufacturing Process:
Manufacture of nylon hosiery (weaving, washing, dyeing); 150,000 TO 200,000 gpd are discharged to POTW.

Sources of Process Wastewater:
Washing and dyeing

Categorical Industry? **NO**


Basis for Limits: **40CFR403.8 individual permits with effluent limits**

Point of Application: **NE**

Description of Pretreatment Equipment and Procedures:
Pretreatment plant onsite consists of activated sludge plant with aeration tank and clarifier. Sludge hauled to Clarksville POTW.

Spill Prevention and Solvent Management Procedures:
All operations are monitored for spills. No solvents are used at the plant.

Sampling Location and Equipment:
Sample collected at heat recovery pit; O&G sampled at effluent of pretreatment plant.

Water Division Photographic Evidence Sheet			
Location:	Hanesbrand		
Photographer:	Google Earth	Date:	10/24/2012
Witness:		Time:	
		Photo #:	1
Description:	The extended aeration activated sludge pretreatment plant.		
			
Photographer:	Tony Morris	Date:	10/1/2015
Witness:	Pam Smith	Time:	10:40
		Photo #:	2
Description:	Products manufactured by Hanesbrand at the Clarksville Plant.		
