

February 3, 2016

Mr. Lynn Shepherd Reynolds Metals Company Gum Springs Hwy 67 South 500 E. Reynolds Road Arkadelphia, AR 71923-8817

RE: Quarterly Inspection; AFIN10-00004; Permit Number 0262-S

Dear Mr. Shepherd:

On February 01, 2016, I conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, and the above-referenced permit. A copy of the inspection report is enclosed for your records. At the time of the inspection, no allegations of noncompliance were noted at your facility.

If I can be of any further assistance, feel free to contact me at 870-777-7585 Ext. 3 or greenwood@adeq.state.ar.us.

Sincerely,

Matt Greenwood ADEQ Inspector

Mattle II

Office of Land Resources

www.adeq.state.ar.us



Arkansas Department of Environmental Quality Solid Waste Management Division Class 3 Landfill Inspection



Site Name	Reynolds Metals, Inc. (Alcoa)	County	Clark	AFIN		10-00004	
Facility Address	2 miles east of I-30 on Hwy. 26 East.	Phone Number	870-245-2700 Permit Number		0262-S		
Permittee Address	500 E. Reynolds Rd. Arkadelphia, AR 71923	E-Mail Address	Kent.thomas@alcoa.com		PDS#	088897	
			Lyn.shepherd@alcoa.com				
Date	02/01/16	Entry Time	0900	Exit Time	0945		

Regulation 22 – Operational Standards

Category 1

Regulation	Item Description	Comments				
510(l)	Adequate employee facilities					
520(a)(b)	Record keeping meets requirements specified by regulations					
516	Access requirements					
510(j)	Adequate provisions for backup equipment					
520(c)	Waste receipt records, ticket system maintained					
510(k)	Telephone system & written emergency response plan on site					
522(a)	Annual compliance inspection by register professional engineer					
521	521 Facility implements operating plan and narrative					
520(a)(4)	520(a)(4) Leachate disposal/recirculation records					
701, 520(a)(2)	Special waste disposal and procedures records					

Category 2

Regulation Item Description		Comments				
510(a)	Operations in accordance with permit documents					
516(c)	Adequate all weather operational roads					
510(c)	Smallest practical area, unloading supervised, single working face					
510(e)	Salvage operations meet approved conditions					
510(f)(l)	Scavenging of waste prohibited					
510(o)	Proper wet weather repairs					
510(b)	Operations by licensed on-site personnel at all times					
510(d)	Waste spread and compacted as unloaded					
510(g)	Litter control provisions maintained					
513(a)	Disease vectors controlled					

	Category 2 (continued)									
	Regulation		Item Descri				Comments			
	518	Surface w	ater controls							
	510(h)(l)	Contourin	g prevents surface water f	lowing into or thi	rough waste					
	517(a)(b)	Run-on/of	f control system present ar	nd adequate						
	510(h)(2)	Surface w	ater control prevents off-si	te sediment accur	mulation					
	510(h)(i)	Adequate	maintenance of intermedia	ate/final cover veg	getation					
	514	Gas monit	oring program							
	510(n)	Leachate	eaks or evidence of leacha	te seepage						
	526	Survey co	ntrols							
	529	Leachate	collection system							
	519	Liquid res	trictions							
Category 3										
	Regulation		Item Descri				Comments			
	511	Implemen	tation of hazardous/unautl	lusion plan						
	512(a)(c)	Satisfactor	ry daily/alternative cover							
	512(b)	Satisfacto	ry intermediate cover							
	515(b), 510(f)(4	4) Open burn	ning prohibited							
	518	Cause disc	Cause discharge/leachate discharge leaving landfill							
	510(f)(3), 518(a)(4) Depositing	g waste in standing water p							
	510(n)	Erosion or	other cover defects result	fuse						
	309(c)	c) Overfill/off lined area								
	Regulation 22 - Records									
52	520(a)(8), 204(b) Date of last groundwater monitoring report Oct. 2015					Site Conditions Dry				
	522		ate of last engineering report		June 2015		Weather Conditions Sunny			
		528 Liner construction in progress Yes/No No			er construction Yes/No	No Third part CQA on-site during construction Yes/No No				
_	511 514, 520(a)(3)	511 Date of last random inspection for unauthorized waste 520(a)(3) Date of last quarterly methane monitoring		N/A N/A	Total # for month Detection level 514 Explosive gas records curr			anda arruna	nt? Yes/No No	
	701, 520(a)(2)			N/A	Detection level Disposal location	514 Explosive gas records current? Yes/No No				
	520(c)			None	Tons	0.0 Tons				
	527 Surface water DMR records current? Yes/No Yes									
Operator Name & Number Not in operation				Signature of Inspector	Mattle Themas					
Exit Interview Condu		nducted with	Kent Thomas		Method	On-Site	Date	02/01/16	Time	0940

Permit 0262-S Photo 1-2



