



April 8, 2016

Mondi Bag, USA
ATT: Randy Womack
PO Box 20700
Pine Bluff, AR. 71612

RE: Quarterly Inspection; AFIN 35-00017 Permit Number 0243-S3N-R2

Dear: Mr. Womack,

On April 1, 2016, I conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, and the above-referenced permit. A copy of the inspection report is enclosed for your records. At the time of the inspection, no allegations of noncompliance were noted at your facility.

If I can be of any further assistance, feel free to contact me at 870-247-5155 or gentry@adeq.state.ar.us.

Sincerely,

A handwritten signature in cursive script that reads "Bobby Gentry".

Bobby Gentry
ADEQ Inspector
Office of Land Resources



Arkansas Department of Environmental Quality

Solid Waste Management Division

Class 3 Landfill Inspection



| | | | | | |
|--------------------------|--|-----------------------|------------------------------|----------------------|-------------|
| Site Name | Mondi Bag USA | County | Jefferson | AFIN | 35-00017 |
| Facility Address | North of Pine Bluff in the Industrial Park | Phone Number | 870-541-5074 870-541-5000 | Permit Number | 0243-S3N-R2 |
| Permittee Address | P.O. Box 20700, Pine Bluff, AR 71612 | E-Mail Address | None | PDS # | 090162 |
| Date | 4-1-16 | Entry Time | 11:20 am | Exit Time | 12:30 pm |

Regulation 22 – Operational Standards

Category 1

| Regulation | Item Description | Comments |
|----------------|--|----------|
| 510(l) | Adequate employee facilities | |
| 520(a)(b) | Record keeping meets requirements specified by regulations | |
| 516 | Access requirements | |
| 510(j) | Adequate provisions for backup equipment | |
| 520(c) | Waste receipt records, ticket system maintained | |
| 510(k) | Telephone system & written emergency response plan on site | |
| 522(a) | Annual compliance inspection by register professional engineer | |
| 521 | Facility implements operating plan and narrative | |
| 520(a)(4) | Leachate disposal/recirculation records | |
| 701, 520(a)(2) | Special waste disposal and procedures records | |

Category 2

| Regulation | Item Description | Comments |
|------------|--|----------|
| 510(a) | Operations in accordance with permit documents | |
| 516(c) | Adequate all weather operational roads | |
| 510(c) | Smallest practical area, unloading supervised, single working face | |
| 510(e) | Salvage operations meet approved conditions | |
| 510(f)(l) | Scavenging of waste prohibited | |
| 510(o) | Proper wet weather repairs | |
| 510(b) | Operations by licensed on-site personnel at all times | |
| 510(d) | Waste spread and compacted as unloaded | |
| 510(g) | Litter control provisions maintained | |
| 513(a) | Disease vectors controlled | |

Category 2 (continued)


| Regulation | Item Description | Comments |
|------------|---|----------|
| 518 | Surface water controls | |
| 510(h)(l) | Contouring prevents surface water flowing into or through waste | |
| 517(a)(b) | Run-on/off control system present and adequate | |
| 510(h)(2) | Surface water control prevents off-site sediment accumulation | |
| 510(h)(i) | Adequate maintenance of intermediate/final cover vegetation | |
| 514 | Gas monitoring program | |
| 510(n) | Leachate leaks or evidence of leachate seepage | |
| 526 | Survey controls | |
| 529 | Leachate collection system | |
| 519 | Liquid restrictions | |

Category 3

| Regulation | Item Description | Comments |
|----------------------|---|----------|
| 511 | Implementation of hazardous/unauthorized waste exclusion plan | |
| 512(a)(c) | Satisfactory daily/alternative cover | |
| 512(b) | Satisfactory intermediate cover | |
| 515(b), 510(f)(4) | Open burning prohibited | |
| 518 | Cause discharge/leachate discharge leaving landfill | |
| 510(f)(3), 518(a)(4) | Depositing waste in standing water prohibited | |
| 510(n) | Erosion or other cover defects resulting in exposed refuse | |
| 309(c) | Overfill/off lined area | |

Regulation 22 - Records

| | | | | |
|-------------------|---|--|--|---|
| 520(a)(8), 204(b) | Date of last groundwater monitoring report | October 22, 2015 | Site Conditions | Dry |
| 522 | Date of last engineering report | June 2015 | Weather Conditions | Sunny |
| 528 | Liner construction in progress <input type="checkbox"/> Yes/No <input type="checkbox"/> No | Notice of liner construction <input type="checkbox"/> Yes/No <input type="checkbox"/> No | Third part CQA on-site during construction | <input type="checkbox"/> Yes/No <input type="checkbox"/> No |
| 511 | Date of last random inspection for unauthorized waste | Every load | Total # for month | March |
| 514, 520(a)(3) | Date of last quarterly methane monitoring | None | Detection level | 514 Explosive gas records current? <input type="checkbox"/> Yes/No <input type="checkbox"/> |
| 701, 520(a)(2) | Date of last special waste received | None | Disposal location | |
| 520(c) | Previous quarter waste received | 190.92 | Tons | 1 st QTR 2016 |
| 527 | Surface water DMR records current? <input type="checkbox"/> Yes/No <input type="checkbox"/> Yes | | | |

| | | | | | | | |
|-------------------------------|-----------------------|--------|------------------------|------|---|------|----------|
| Operator Name & Number | Keith Swilling Lic: # | | Signature of Inspector | |  | | |
| Exit Interview Conducted with | Keith Swilling | Method | Onsite | Date | 4-1-16 | Time | 12:15 pm |

0243-S3N-R2 Photos 1&2

