

April 27, 2016

The Honorable Jerry Holmes Cleburne County Judge 301 W. Main Street Heber Springs, AR 72543

RE: Quarterly Inspection AFIN; 12-00039 Permit Number; 0280-S4-R1

Dear Judge Holmes:

On April 19, 2016, I conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, and the above-referenced permit. A copy of the inspection report is enclosed for your records. At the time of the inspection, no allegations of noncompliance were noted at your facility.

If I can be of any further assistance, feel free to contact me at 501-682-0599 or by e-mail at stringer@adeq.state.ar.us.

Sincerely,

Charles Stringer ADEQ Inspector Office of Land Resources

Attachment

CC: Tammie Hynum, Senior Manager, Office of Land Resources, Regulated Waste Program



Arkansas Department of Environmental Quality Solid Waste Management Division Class 4 Landfill Inspection



Site Name	Cleburne Co SLF	County	Cleburne	AFIN	12-00039 0280-S4-R1							
Facility Address	Wilburne, Hwy. 110 W. to Harlin Road, 0.5 miles to Site.	Phone Number	501-206-9137 TS 501-362-8141	Permit Number								
Permittee Address	Judge Jerry Holmes, Cleburne Co. Courthouse, 300 W. Main, Heber Springs, AR. 72543	E-Mail Address	clebcojudge@yahoo.com	-	120	090463						
Date	4/19/2016	Entry Time	1320	Exit Time	1415							
	Regulation 22 – Operational Standards											
Category 1												
Regulation	Item Description		Comments									
607(l)	Adequate employee facilities											
617(a)(b)	Record keeping meets requirements specified by regulation	IS										
613	Access requirements											
607(j)	Adequate provisions for backup equipment											
617(c)	Waste receipt records, ticket system maintained											
607(k)	Telephone system & written emergency response plan on si	ite										
619(a)	Annual compliance inspection by registered professional er	ngineer										
618	Facility implements operating plan and narrative											
701	Special waste disposal and procedures records											
		Category 2										
Regulation	Item Description		Comments									
607(a)	Operations in accordance with permit documents											
613(c)	Adequate all weather operational roads											
607(c)(d)	Smallest practical area, single working face											
607(e)	Salvage operations meet approved conditions											
607(f)(1)	Scavenging of waste prohibited											
613 (c)	Proper wet weather repairs											
607(b)	Operations by licensed on-site personnel at all times											
607(d)	Waste spread and compacted as unloaded											
607(g)	Litter control provisions maintained											
610(a)	Disease vectors controlled											
611	Gas monitoring program											
622	Survey controls											

Category 2 (continued)													
Regulation	Item Description			Comments									
623	Surface water controls												
607(h)(1)	Contouring prevents surface wate	ough waste											
614(a)	Run-on/off control system present												
607(h)(2)	Surface water control prevents off-site sediment accumulation												
607(h)(i)(o)	Adequate maintenance of interme	etation											
607(o)	Leachate leaks or evidence of leachate seepage												
616	Liquid restrictions												
Category 3													
Regulation	Item Description			Comments									
608	Implementation of hazardous waste exclusion plan												
609(a)	Satisfactory weekly or more frequent cover												
609(b)	Satisfactory immediate cover												
612(b),607(f)(4)	Open burning prohibited												
615	Cause discharge/leachate discharge												
607(f)(3),615(a)(4)	Depositing waste in standing wate												
607(o)	Erosion or other cover defects resulting in exposed refuse												
309(c)	Overfill/off lined area												
Regulation 22 - Records													
617(a)(4), 621(e) D	ate of last groundwater monitoring	N/A	Site Conditions Cloudy										
619 Date of last engineering report			6/30/2015		Wea	Weather Conditions Damp							
617(a)(4) Liner construction in progress Yes/No NO			Notice of liner co		Third part CQA on-site during construction Yes/No								
			4/18/2016	Total # for month	9 – March 2010		-	X 7 / X 7	NT/ :				
			N/A	Detection level	-	511 Explosive gas rec	cords current?	Yes/No	N/A				
			N/A 1665	Disposal location N/A Cy 1st Qtr 2016									
- (-)	urface water DMR records current	Yes/No Yes	1005	Су	1st Qu 2010								
Operator Name & Nu		L	Signature of Inspector										
Exit Interview Condu	ucted with Mike Gadell		Method	On Site	Date	4/19/2016	Time	1410					

Class 4 Form 7/1/2012 (Revised and Implemented 10/21/2014)

For ADEQ Use Only







