

May 27, 2016

Mr. Tom Holte Green Bay Packaging, Inc. Arkansas Kraft Division PO Box 711 Morrilton, AR 72110

RE: Quarterly Inspection; AFIN 15-00001; Permit Number 0284-S3N

Dear Mr. Holte:

On May 18, 2016, I conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, and the above-referenced permit. A copy of the inspection report is enclosed for your records. At the time of the inspection, no allegations of noncompliance were noted at your facility.

If I can be of any further assistance, feel free to contact me at 501-682-0599 or stringer@adeq.state.ar.us.

Sincerely,

Charles Stringer ADEQ Inspector

Office of Land Resources

Attachment

cc: Tammie Hynum, Senior Manager, Office of Land Resources-Regulated Waste Programs



### Arkansas Department of Environmental Quality Solid Waste Management Division Class 3 Landfill Inspection



Site Name Green Ba	ay Packaging, Inc., Arkansas Kraft Division	County	Conway	AFIN	15-00001	
Facility Address Morrilton	n, Hwy 9 S. to Hwy 133 S. to the Facility	Phone Number	501-354-9289	Permit Number	0284-S3N	
Permittee Address PO Box 7	711, Morrilton, AR 72110	E-Mail Address			<b>PDS</b> # 090999	
<b>Date</b> 5/18/2010	6	Entry Time	1325 Exit Time		1430	

#### **Regulation 22 – Operational Standards**

## **Category 1**

Regulation	Item Description	Comments
510(l)	Adequate employee facilities	
520(a)(b)	Record keeping meets requirements specified by regulations	
516	Access requirements	
510(j)	Adequate provisions for backup equipment	
520(c)	Waste receipt records, ticket system maintained	
510(k)	Telephone system & written emergency response plan on site	
522(a)	Annual compliance inspection by register professional engineer	
521	Facility implements operating plan and narrative	
520(a)(4)	Leachate disposal/recirculation records	
701, 520(a)(2)	Special waste disposal and procedures records	

# Category 2

Regulation	Item Description	Comments
510(a)	Operations in accordance with permit documents	
516(c)	Adequate all weather operational roads	
510(c)	Smallest practical area, unloading supervised, single working face	
510(e)	Salvage operations meet approved conditions	
510(f)(l)	Scavenging of waste prohibited	
510(o)	Proper wet weather repairs	
510(b)	Operations by licensed on-site personnel at all times	
510(d)	Waste spread and compacted as unloaded	
510(g)	Litter control provisions maintained	
513(a)	Disease vectors controlled	

Category 2 (continued)														
	Regulation		Item Description							Cor	nments			
	518	Surface wa	Surface water controls											
	510(h)(l)	Contourin	Contouring prevents surface water flowing into or thro											
	517(a)(b)	Run-on/of	Run-on/off control system present and adequate											
	510(h)(2)	Surface wa	Surface water control prevents off-site sediment accum											
	510(h)(i)	Adequate	maintenance of inter	mediate/fi	nal cover vege	etation								
	514	Gas monit	oring program											
	510(n)	Leachate l	eaks or evidence of le	eachate se	epage									
	526	Survey con	ntrols											
	529	Leachate o	collection system											
	519	Liquid res	Liquid restrictions											
						Cat	egory 3							
	Regulation Item Description							Cor	nments					
	511	Implemen	Implementation of hazardous/unauthorized waste exclu			usion plan								
	512(a)(c)	Satisfactor	Satisfactory daily/alternative cover											
	512(b)	Satisfactor	Satisfactory intermediate cover											
	515(b), 510(f)(4	) Open burn	ning prohibited											
	518	Cause disc	harge/leachate disch	arge leavi	ng landfill									
	510(f)(3), 518(a)(4)	) Depositing	waste in standing wa	ater prohi	bited									
	510(n)		other cover defects i			ıse								
	309(c)	Overfill/of	f lined area											
	<u> </u>				Reg	ulation :	22 - Record	ds						
52	20(a)(8), 204(b)	Date of last gr	oundwater monitorir	ng report		2/5/2016			Site Condit	tions	Dry			
	522		gineering report	-8 - · F · - ·		6/23/15	/15 Weather Conditions Cloudy							
	528	Liner construc	ction in progress	Yes/No	completed	Notice of li		Yes/No	Third par		CQA on-site during	constructi	on Yes/No	
	511	Date of last ra	ndom inspection for	unauthori	zed waste	N/A	Total # for	r month						
514, 520(a)(3) Date of last quarterly methane monitoring		N/A	Detection	level		514	Explosive gas reco	ords curre	nt? Yes/No					
		N/A	Disposal le	ocation										
520(c) Previous quarter waste received		61,103.95	Cy		1 <sup>st</sup> Qtr 2016	j								
527 Surface water DMR records current? Yes/No														
Operator Name & Number Tom Holte-003513 Harrison Rae- 003821				Signature of 1	Inspector	r	6	112	_					
Exit Interview Conducted with		ducted with	Harrison Rae			Method	On Site		Date	5/18/2016		Time	1420	



Site Name

Green Bay Packaging, Inc., Arkansas Kraft Division

#### Arkansas Department of Environmental Quality Solid Waste Management Division Comments Page

15-00001

AFIN



0284-S3N

Permit Number

Site Main	Green Buy Fuenuging, Inc.,	THUMBUS THURS DIVISION	AFIII	15 00001	1 el mit Number	0201 8311				
Additional Comments										
Comment: The liner of Cell 5 has been fully constructed and the Department authorized the placement of waste into Cell 5 on May 11, 2016 (DOC ID#69373). See photos 1 through 3.										
Comment: Stan Chivers is no longer employed at the facility. Mr. Harrison Rae is now occupying Mr. Chivers' former position.										
		T		2. 0						
Date	5/18/2016	Signature of Inspector	Ch	12			Page	3		







Permit# 0284-S3N Photo 4 & 5



