



August 1, 2016

The Honorable Woody Wheelless
Crittenden County Judge
100 Court Street
Marion, AR 72364

RE: Quarterly Inspection; AFIN 18-00094; Permit Number 0245-S1-R1.

Dear Judge Wheelless:

On July 29, 2016, I conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, and the above-referenced permit. A copy of the inspection report is enclosed for your records.

Please refer to the attached inspection report to note the specific allegations. A written response for the noted allegations, describing the corrective action taken or to be taken, must be submitted to my attention at the address listed below within thirty (30) days from the date hereof. Failure to submit the written response shall be construed as an admission of any allegations. Any items noted that are neglected and/or persistent may warrant formal enforcement action.

If I can be of any further assistance, feel free to contact me at 870-935-7221 or bakert@adeq.state.ar.us.

Sincerely,

Tobin Baker
ADEQ Inspector
Office of Land Resources Division

Attachment

Cc: Tammie Hynum, Acting Sr. Operations Manager, Office of Land Resources



Arkansas Department of Environmental Quality

Office of Land Resources Division

Class 1 Landfill Inspection



Site Name	Crittenden County Class I	County	Crittenden	AFIN	18-00094
Facility Address	South off Hwy 70	Phone Number	LF: 870-732-4290 Off: 870-732-6580	Permit Number	0245-S1-R1
Permittee Address	Crittenden Co. Judge	E-Mail Address	arredllc@swb.net	PDS #	092043
Date	7/29/2016	Entry Time	10:30 AM	Exit Time	11:38 AM


Regulation 22 – Operational Standards

Category 1

Regulation	Item Description	Comments
411(l)	Adequate employee facilities	
421(a)(b)	Record keeping meets requirements specified by regulations	
417	Access requirements	
411(j)	Adequate provisions for backup equipment	
421(d)	Waste receipt records, ticket system maintained	
411(k)	Telephone system & written emergency response plan on site	
423(b)	Annual compliance inspection by registered professional engineer	
422	Facility implements operating plan and narrative	
421(f)	Leachate disposal/recirculation records	
421(g),701	Special waste disposal and procedures records	

Category 2

Regulation	Item Description	Comments
411(a)	Operations in accordance with permit documents	
417(c)	Adequate all weather operational roads	
411(c)	Smallest practical area, unloading supervised, single working face	
411(e)	Salvage operations meet approved conditions	
411(f)(1)	Scavenging of waste prohibited	
411(p)	Proper wet weather repairs	
411(b)	Operations by licensed on-site personnel at all times	
411(d)	Waste spread and compacted as unloaded	
411(g)	Litter control provisions maintained	
414(a)	Disease vectors controlled	

Category 2 (continued)														
	Regulation	Item Description						Comments						
	427	Surface Water Controls												
	411(h)(1)	Contouring prevents surface water flowing into or through waste												
	418(a)(b)	Run-on/off control system present and adequate												
	411(h)(2)	Surface water control prevents off-site sediment accumulation												
	411(i);427(f)	Adequate maintenance of intermediate/final cover vegetation												
	415	Gas monitoring program												
X	411(o)	Leachate leaks or evidence of leachate seepage						Leachate leaks were observed in the middle of the south and west slope of the landfill. See Photos 1-4.						
	426	Survey controls												
	429	Leachate collection system												
	420	Liquid Restrictions												
Category 3														
	Regulation	Item Description						Comments						
	412	Implementation of hazardous/unauthorized waste exclusion plan												
	413(a)(b)	Satisfactory daily/alternative cover												
	413(c)	Satisfactory intermediate cover												
	416(b),411(f)(4)	Open burning prohibited												
	419	Cause discharge/leachate discharge leaving landfill												
	411(f)(3),419(a)(4)	Depositing waste in standing water prohibited												
	411(o)	Erosion or other cover defects resulting in exposed refuse												
	309(c)	Overfill/Off lined area												
Regulation 22 - Records														
421(a)(8), 1203(k)		Date of last groundwater monitoring report				7/6/2016		Site Conditions		Dry				
423(b)		Date of last engineering report				3/23/ 2016		Weather Conditions		Sunny				
428		Liner construction in progress		Yes/No	No	Notice of liner construction		Yes/No	No	Third party CQA on-site during construction		Yes/No	No	
412(a)		Date of last random inspection for unauthorized waste				7/29/2016		Total # for month		23				
415, 421(e)		Date of last quarterly methane monitoring				6/8/2016		Detection level		0	415(a)	Explosive gas records current?	Yes/No	Yes
421(g),412(a)(2),701		Date of last special waste received				7/29/2016		Disposal location						
421(d)		Previous quarter waste received				31,520.41		Tons		2 nd Quarter 2016				
427(c)		Surface water DMR records current?				Yes/No	Yes							
Fayetteville Shale Related		Yes/No	No	Out of Compliance with Fayetteville Shale				Yes/No	No					
Operator Name & Number		Ed Jackson- 001217						Signature of Inspector						
Exit Interview Conducted with		John McDonald				Method	On-Site		Date	7/29/2016		Time	11:30	

0245-S1-R1 Photo 1 & 2



0245-S1-R1 Photo 3 & 4





Santek Waste Services of Arkansas
Crittenden County Landfill
1299 Kuhn Road
West Memphis, AR 72301
Phone (423) 716-4332
Fax (870) 735-2932

August 9, 2016

AFIN: 18-00094
PMT#: 0245-S1-R1 REC'D SCAN

AUG 09 2016

DOC ID: 70091
TO: TB 2 file SWMD

Attn: Mr. Tobin Baker
Arkansas Department of Environmental Quality
5301 North Shore Drive
North Little Rock, AR 72118-5317

Re: ADEQ Quarterly Inspection Performed on July 29, 2016
Crittenden County Landfill (Permit #0245-S1-R1)

Dear Mr. Baker:

On behalf of Santek Environmental of Arkansas, LLC, the enclosed information package provides updated information and corrective actions for deficiencies found during the July 29, 2016 ADEQ Quarterly Inspection. Please review the documentation and if you require further information, I can be contacted at (423) 716-4332.

Sincerely,

John McDonald
Landfill Manager

Cc: Hon. Woody Wheelless: County Judge, Crittenden County, AR
Mr. Matt Dillard, Executive V.P. of Operations, Santek

Category 1

No Violations

Category 2

Item Number

1. **Regulation 411 (0)** – Leachate leaks were observed in the middle of the south and west slope of the landfill
Corrective Action – Leachate leaks were repaired



Leachate leaks were corrected on 8/2/2016

1. **Regulation 411 (0)** – Leachate leaks were observed in the middle of the south and west slope of the landfill
Corrective Action – Leachate leaks were repaired



Leachate leaks were corrected on 8/2/2016

Category 3

No Violations

1. **Regulation 411 (0)** – Leachate leaks were observed in the middle of the south and west slope of the landfill
Corrective Action – Leachate leaks were repaired



Leachate leaks were corrected on 8/2/2016