

October 20, 2016

Mr. Fred Megginson Reynolds Metals Company Gum Springs Hwy 67 South 500 E. Reynolds Road Arkadelphia, AR 71923-8817

RE: Quarterly Inspection; AFIN10-00004; Permit Number 0262-S

Dear Mr. Megginson:

On October 17, 2016, I conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, and the above-referenced permit. A copy of the inspection report is enclosed for your records. At the time of the inspection, no allegations of noncompliance were noted at your facility.

If I can be of any further assistance, feel free to contact me at 870-777-7585 or greenwood@adeq.state.ar.us.

Sincerely,

Matt Greenwood

Mattle Grand

ADEQ Solid Waste Inspector

Office of Land Resources

cc: Tammie Hynum, Acting Sr. Operations Manager, Office of Land Resources



## Arkansas Department of Environmental Quality Office of Land Resources -Solid Waste Management Class 3 Landfill Inspection



Site Name	Reynolds Metals, Inc. (Alcoa)	County	Clark	AFIN	10-00004	
<b>Facility Address</b>	2 miles east of I-30 on Hwy. 26 East.	Phone Number	870-245-2700 <b>Permit Number</b>		0262-S	
<b>Permittee Address</b>	500 E. Reynolds Rd. Arkadelphia, AR 71923	E-Mail Address	Kent.thomas@alcoa.com	<u>1</u>	PDS#	093426
Date	10/17/16	<b>Entry Time</b>	0800 Exit Time		0930	

## **Regulation 22 – Operational Standards**

## **Category 1**

Regulation	Item Description	Comments							
510(l)	Adequate employee facilities								
520(a)(b)	Record keeping meets requirements specified by regulations								
516	Access requirements								
510(j)	Adequate provisions for backup equipment								
520(c)	Waste receipt records, ticket system maintained								
510(k)	Telephone system & written emergency response plan on site								
522(a)	Annual compliance inspection by register professional engineer								
521	Facility implements operating plan and narrative								
520(a)(4)	Leachate disposal/recirculation records								
701, 520(a)(2)	Special waste disposal and procedures records								

## **Category 2**

Regulation	Item Description	Comments
510(a)	Operations in accordance with permit documents	No waste is being placed in the landfill.
516(c)	Adequate all weather operational roads	
510(c)	Smallest practical area, unloading supervised, single working face	
510(e)	Salvage operations meet approved conditions	
510(f)(l)	Scavenging of waste prohibited	
510(o)	Proper wet weather repairs	
510(b)	Operations by licensed on-site personnel at all times	
510(d)	Waste spread and compacted as unloaded	
510(g)	Litter control provisions maintained	
513(a)	Disease vectors controlled	

	Category 2 (continued)												
	Regulation		Item Description				Comments						
	518		Surface water controls										
	510(h)(l)	Contourin	Contouring prevents surface water flowing into or through waste										
	517(a)(b)	Run-on/of	f control system present a	nd adequate									
	510(h)(2)	Surface wa	Surface water control prevents off-site sediment accumulation										
	510(h)(i)	Adequate	Adequate maintenance of intermediate/final cover vegeta										
	514	Gas monit	Gas monitoring program										
	510(n)	Leachate l	Leachate leaks or evidence of leachate seepage										
	526		Survey controls										
	529	·	Leachate collection system										
	519		Liquid restrictions										
Category 3													
	Regulation Item Description						v		Cor	nments			
	511	Implemen	Implementation of hazardous/unauthorized waste exc										
	512(a)(c)	-											
	512(a)(c) 512(b)		Satisfactory daily/alternative cover										
	515(b), 510(f)(4		Satisfactory intermediate cover										
	515(0), 510(1)(4	_	Open burning prohibited										
	518 510(f)(3), 518(a)(4)	Cause discharge/leachate discharge leaving landfill											
		1 6	Depositing waste in standing water prohibited										
	510(n)		Erosion or other cover defects resulting in exposed refus										
	309(c) Overfill/off lined area												
	Regulation 22 - Records												
52	520(a)(8), 204(b) Date of last groundwater monitoring report			Aug 2016			Site Condit		Dry				
	522		8 8 1		June 2016			Conditions   Sunny   Third part COA on-site during construction   Yes/No			Vog/No		
	528 511			110	Notice of liner construction Yes/No N/A Total # for month		No 7	Third part CQA on-site during construction Yes/No				No	
4	514, 520(a)(3)				N/A N/A		Detection level		514	Explosive gas records cur	rent?	Yes/No	No
	701, 520(a)(2)		ecial waste received	ug	N/A		Disposal location		314	Explosive gas records cur	icht.		110
	520(c)		ter waste received		None		Tons	0.0 Tons					
527 Surface water DMR records current? Yes/No Yes													
Operator Name & Number Not in operation				Sign	nature of Inspector	ŗ	Nett	Themas			_		
Exit Interview Condu		ducted with	Kent Thomas		Method	On-	Site	Date	10/17/16	Time	090	0	

Permit 0262-S Photo 1-2



