

December 5, 2016

John Lester Clarksville Light & Water PO Box 1807 Clarksville, AR 72830

RE: Pretreatment Industrial User - Bright Harvest Sweet Potato Co (Johnson Co)

AFIN: 36-00038 NPDES Permit No.: AR0022187

Dear Mr. Lester:

On November 17, 2016 I performed an Industrial User Inspection of the above-referenced facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. A copy of the inspection report is enclosed for your records.

Please refer to the "Summary of Findings" section of the attached inspection report and provide a written response for each finding that was noted. This response should be mailed to the attention of the Office of Water Quality, Inspection Branch at the address at the bottom of this letter or e-mailed to <a href="Water-Inspection-Report@adeq.state.ar.us">Water-Inspection-Report@adeq.state.ar.us</a>. This response should contain documentation describing the course of action taken to correct each item noted. This corrective action should be completed as soon as possible, and the written response with all necessary documentation (i.e., photos) is due by <a href="December 19, 2016">December 19, 2016</a>.

If I can be of any assistance, please contact me at <a href="mailto:grayd@adeq.state.ar.us">grayd@adeq.state.ar.us</a> or (479) 424-0333.

Sincerely,

Dannielle Gray

District 4 Field Inspector

Office of Water Quality

cc: Greg Rainey, Clarksville Light and Water Pollution Control Facility Superintendent,

Gregg.rainey@clarksvillelightwater.com

Pam smith, Clarksville Light and Water, Pretreatment Coordinator,

pam.smith@clarksvillelightwater.com

Misty Morehead, Bright Harvest Sweet Potato Co., R & D Manager,

mmorehead@brightharvest.com

	V DEO		OFFICE C	OF WATER	INS	PEC	TIO	N REPORT	
	ADLU	AFIN: <b>36-00038</b> PERMIT #: <b>AR0022187</b>					[	DATE: <b>11/16/2016</b>	
Α	RKANSAS	son	PDS	#: 0942	61	MEDIA: WN			
Dep	partment of Environmental Quality	GF	S LAT: L	ONG: LOC	OITAC	V: <b>N/A</b>		<u> </u>	
	FACILITY INFORMAT		IN	ISPEC	TION II	NFORI	MATION		
Bright Harvest Sweet Potato Co				FACILITY TYPE:  2 - Industrial	713	TOR ID#: 30 S - S			
	9 Taylor Road			facility evaluation ration <b>2 - Marginal</b>				on type: strial User	
-	arksville				NTRY TIME: 19:15	13:		PERMIT EFFECTIVE DATE: 10/1/2014	
RESPONSIBLE OFFICIAL								PERMIT EXPIRATION DATE:	
	en Lostor / Gonoral Managor	]				9/30/2019			
COM	hn Lester / General Manager	FAYETTEVILLE SHALE RELATED: N							
	arksville Light and Water			FAYETTEVILLE SHALE VIOLATIONS: N					
	NG ADDRESS:  D Box 1807				INSPECTION PARTICIPANTS				
CITY,	STATE, ZIP:			NAME/TITLE/PHONE/FAX/EMAIL/ETC.:					
	arksville AR 72830			Johnny Finn/Environmental Technician/479-754-6313 Doug Tate/Environmental Supervisor/479-754-6313					
PHON	ME & EXI: / FAX:			Greg Rainey/Clarksville POTW Facility					
EMAII				Superintendent/479-979-5509					
00	NITA OTED DUDING INODEOTION	N1 -		Pam Smith/Pretreatment Coordinator/479-754-6241					
CC	NTACTED DURING INSPECTION:	NO		ext304					
	(S=S:	atisfac		ALUATIONS htisfactory, N=Not Applicable	/Fvaluated	4)			
S	PERMIT	**	FLOW MEASU		**		RMWA	TER	
**	RECORDS/REPORTS	**	LABORATORY	,	U	FACI	LITY S	SITE REVIEW	
**	OPERATION & MAINTENANCE	**		CEIVING WATER				ITORING PROGRAM	
**	SAMPLING	**	SLUDGE HAND	DLING/DISPOSAL	**	PRE1	REAT	MENT	
**	OTHER:								
			SUMMARY	OF FINDINGS					

The following findings were noted during inspection:

1. Bright Harvest Sweet Potato is not properly operating its pretreatment clarifiers. Specifically, clarifiers are not being pumped of sludge in a manner, which allows for optimal operation of the pretreatment system. As such, both clarifiers are sludge laden and Pond #1 is septic and malfunctioning. The Permittee, Clarksville Light and Water, was investigating the Industrial User (IU) at the time of inspection. The Permittee will need to submit a statement to ADEQ indicating any non-compliance identified and actions taken to address them.

Inspection Report: Bright Harvest Sweet Potato Co, AFIN: 36-00038, Permit #: AR0022187

#### **GENERAL COMMENTS**

I inspected this IU on November 17, 2016. Mr. Finn and Mr. Tate accompanied my on my inspection. Following inspection, I met with Mr. Greg Rainey to discuss the findings of my inspection and obtain information regarding the City's response.

During inspection, it was noted that Bright Harvest Sweet Potato is not properly operating its pretreatment clarifiers. Specifically, clarifiers are not being pumped of sludge in a manner, which allows for optimal operation of the pretreatment system. As such, both clarifiers are sludge laden and Pond #1 is septic and malfunctioning. During inspection, I informed Mr. Finn that the facility needed to evaluate its operating procedures and implement a more stringent sludge pumping practice to improve functionality of the pretreatment facility.

Following inspection, I met with Mr. Greg Rainey and Ms. Pam Smith to discuss my findings. Mr. Rainey informed that the City was aware of the issue and had been out on Monday, November 14<sup>th</sup> to collect a sample. At the time of inspection, the City was awaiting the results of the sample. Mr. Rainey informed that the City would be conducting a follow-up IU inspection after obtaining the results. He further stated that the operational issues at Bright Harvest Sweet Potato Company were not causing Clarksville's POTW to experience any upsets at the time of the inspection.

·	
Dannielle & Lay-	
INSPECTOR'S SIGNATURE: Dannielle Gray	DATE: <b>12/2/2016</b>
Kerri McCale	
SUPERVISOR'S SIGNATURE:Kerri McCabe	DATE: <b>12/5/2016</b>

#### **POTW Pretreatment Program**

#### **Industrial Site Visit**

<u>Name</u>	of Industry:	Bright Harvest Sweet Potato Company									
Industry Contacts:		Johnny Finn 479-754-6313, Doug Tate 479-754-6313, & Misty Morehead 479-647-3898									
Type of Industry:		Food Processing and Preparation (Sweet Potatoes)									
Date (	of Visit:	11/17/2016									
1. :	Significant indu	strial user?	X	Yes		No		NA			
<b>2.</b>	Pretreatment eq	uipment or procedures?	X	Yes		No		NA			
	Pretreatment eq operational?	uipment maintained and		Yes	X	No		NA			
<b>4</b> .	Hazardous wast	e generated or stored?		Yes	X	No		NA			
<b>5.</b>	Proper solid was	ste disposal?		Yes	X	No		NA			
6. :	Solvent manage	ment/TTO control?		Yes		No	X	NA			
7. :	Suitable samplir	ng location?	X	Yes		No		NA			
	Appropriate self procedures/equi		x	Yes		No		NA			
9	Adequate spill p	revention?	<u> </u>	Yes		No		NA			
<b>10</b> .	Industry familiar	with limits and requirements?	X	Yes		No		NA			
	onal Comments REATMENT PLA	: SLUDGE BUILDUP OBSER NT WASN'T FUNCTIONING OPTIM									

OR WAS NOTED.

Visit Conducted By: Dannielle Gray

Date of Report: 12/2/2016

# Cocation: Bright Harvest Sweet Potato Co Photographer: Dannielle Gray Witness: Johnny Finn & Doug Tate Office of Water Photographic Evidence Sheet Date: 11/17/2016 Time: 1208 Photo #: 1



Photographer:Dannielle GrayDate:11/17/2016Time:1212Witness:Johnny Finn & Doug TatePhoto #:2



Figure 1. Google Earth image dated October 13, 2016 showing pretreatment plant overview and components.





December 27, 2016

Greg Rainey, Superintendent Clarksville Light and Water POTW P.O. Box 1807 Clarksville, AR 72830

**RE:** Response to Inspection (Johnson Co)

AFIN: 36-00038 NPDES Permit No.: AR00022187

Dear Mr. Rainey:

I have reviewed the response pertaining to my November 16, 2016 Industrial User inspection of the Bright Harvest Sweet Potato Company facility. The information provided sufficiently addresses the violations referenced in my inspection report. At this time, the Department has no further comment concerning this particular inspection. Acceptance of this response by the Department does not preclude any future enforcement action deemed necessary at this site or any other site.

If we need further information concerning this matter, we will contact you. Thank you for your attention to this matter. Should you have any questions, feel free to contact me at (479) 424-0333 or you may e-mail me at grayd@adeq.state.ar.us.

Sincerely,

Dannielle Gray

District 4 Field Inspector Office of Water Quality

cc: Gregg Rainey, Clarksville Light and Water, Pollution Control Facility Superintendent, Gregg.rainey@clarksvillelightwater.com

 From:
 Gray, Dannielle

 To:
 McConnell, Melissa

 Cc:
 McCabe, Kerri

 Subject:
 WID 21245

**Date:** Wednesday, January 04, 2017 10:33:20 AM

Attachments: <u>B00010NDG[1].pdf</u>

Please attach this pdf to WID 21245. I pulled this response off of zylab, and it is dated December 6, 2016. Please attach it to the file BEFORE the adequate response letter that is already attached to the electronic file, in order to maintain the timeline. Thank you.

Dannielle Gray ADEQ Water Inspector, District 4 (479) 424-0333



December 6, 2016

Arkansas Department of Environmental Quality
Office of Water Quality
5301 Northshore Drive
North Little Rock, AR 72118-5317

Re: Pre-Treatment Industrial User - Bright Harvest Sweet Potato, Co (Johnson Co)
AFIN: 36-00038 NPDES Permit No.: AR0022187

To whom it may concern:

Drew Ray

On December 5, 2016, Clarksville Light and Water received a letter from ADEQ, Office of Water Quality regarding their inspection of Bright Harvest Sweet Potato, Co. Enclosed you will find the requested material stated in fore mentioned letter. This includes a letter of findings of our inspection, pictures, and a copy of the field log where Nebo Services hauled off contents of Bright Harvest's clarifiers. If any more information is needed you can contact me at (479) 774-1270.

Sincerely,

Gregg Rainey, Wastewater Superintendent

**Enclosures** 



December 6, 2016

Rex King, President 509 Taylor Rd Clarksville, AR 72830

Dear Mr. King:

On November 30, 2016, Clarksville Light and Water performed their annual industrial inspection for Bright Harvest Sweet Potato, Co. The following findings were observed:

- 1. The grease separator in the grease trap was turned off.
- 2. The valves in all outside vats were open.
- 3. Visual inspection of clarifier showed poor cleanup of product inside of plant. There were chunks and slices of product continuing straight to clarifier.
- 4. Areas were covered in trash and in need of cleanup.

After our inspection, we received a letter from ADEQ of their inspection findings and our obligations to address this matter. Enclosed is a copy of this letter. Your immediate attention to these areas of non-compliance is required. If you have any questions, you can contact me at (479) 754-6241 Ext. 302.


Sincerely,

Gregg Rainey, Wastewater Superintendent


Cc: Reg Johnson

Trepolar

**Enclosure** 



12-6-2016



P	1	E		ľ	3		
S	E	R	V	Ì	C	E	S

## FIELD LOG

Field No.: HEQ Field Acreage:	Crop Type:	Allowable PAN:	(Acreage x Crop Uptake Rate
-------------------------------	------------	----------------	-----------------------------

DATE	TIME	DRIVER NAME	TICKET#	SOURCE FACILITY	WASTE TYPE	LOAD VOLUME	PAN/ LOAD	TOTAL PAN REMAINING	NOTES
11-21-16	10:30	Ricky		Н					
	10:50	Elton					ļ		
	11:00	Ricky					<u> </u>		
	12:20	Elfon			Ricky	1 10Ab	At	3,400 GAILON	= 3,400
6	12:50	RICKY					<u> </u>		
	1:45	Elton			Elton	6 lOADS	AY	6,500 GAHOUS	= 39,000
	2:02	Bicky							
	2:27	Elton		· · · · · · · · · · · · · · · · · · ·	Bicky	6 10005	At	6,500 GAILONS	= 39,000
	9:09	RICKY						,	
10	3:30	FITON							
	4:10	Bicky				-,,			
	4:40	Elton							
	5:10	Rick V.				· · · · · · · · · · · · · · · · · · ·			'\
									total
15		· · · · · · · · · · · · · · · · · · ·					<u> </u>	//	
_							<u> </u>		81,400
									/ /
20	L						<u></u>		

Carry over to next field log page



# Clarifier Cleaning 2016

### **FIELD LOG**

Field No.:	Field	Acreage:	Cro	op Type:		/	Allowable PAN:	(Acreage x Crop Uptake Rate)
	DRIVER		SOURCE	WASTE	LOAD	PAN/	TOTAL PAN	

DATE	TIME	DRIVER NAME	TICKET#	SOURCE FACILITY	WASTE. TYPE	LOAD VOLUME	PAN/ LOAD	TOTAL PAN REMAINING	NOTES
1	12:34	Eltan							
	12:45	Ronnie			GRAJU	9 10/18	At	4,000 GAILON	1=36,000
	1:05	Grady		·					
-	1:30	Ricky			CHARLEY	2 10/05	At	3,700 GAIL	= 7,400
5	1:50	Elton		<del></del>					
	2:07	Grady		: 	Elton	710205	A+	6,500 6B110NS	= 45,500.
	2:17	Rossie							
	2:40	Ricky			RONNITE	5 1BADS	AY	b, soo GANONS	= 32.500
	2:09	Grady							
10	5:03	EHOO		· .	Ricky	710105	st	6,500 GAllons	= 45,500
		, , , , , , , , , , , , , , , , , , ,						,	
				· · · · · · · · · · · · · · · · · · ·					
15	,			V - PA - AA- WY					totA)
									166,900
								\\	
				<del></del>					
20									
<u>=</u>		<u> </u>							

perator Signature: <u>Le Air Gellarl</u> Date: \_\_\_\_\_

Carry over to next field log page



7012 2210 0001 7782 0367



# CLARKSVILLE LIGHT & WATER CO.

400 WEST MAIN • P.O. BOX 1807 CLARKSVILLE, AR 72830 PHONE (479) 754-3148

Torkansas Dept. of Environmental Quality
Office of Water Quality
5301 Northshore Drive
North Little Rock, AR 72118-5317