



ARKANSAS
Department of Environmental Quality

WATER DIVISION INSPECTION REPORT

AFIN: 70-00473 PERMIT #: ARG550540 DATE: 2/6/2017
 COUNTY: 70 Union PDS #: 095667 MEDIA: WN
 GPS LAT: 33.159614 LONG: -92.443849 LOCATION: Entrance

FACILITY INFORMATION

NAME:
Anthony Forest Products Company – Urbana Sawmill
 LOCATION:
1236 Urbana Road
 CITY:
EI Dorado, AR 71730

RESPONSIBLE OFFICIAL

NAME / TITLE:
Derek Ratchford / Area Manager
 COMPANY:
Anthony Forest Products Company, LLC
 MAILING ADDRESS:
P.O. Box 724
 CITY, STATE, ZIP:
Strong AR 71765
 PHONE & EXT. / FAX:
870-962-3206 / 870-962-3320
 EMAIL:
Derek.Ratchford@canfor.com

CONTACTED DURING INSPECTION: Yes

INSPECTION INFORMATION

FACILITY TYPE: **2 - Industrial** INSPECTOR ID#: **101531 S - State**
 FACILITY EVALUATION RATING: **5 - Satisfactory** INSPECTION TYPE: **Compliance Evaluation**
 DATE(S): **2/6/2017** ENTRY TIME: **09:30** EXIT TIME: **14:00** PERMIT EFFECTIVE DATE: **7/1/2014**
 PERMIT EXPIRATION DATE: **6/30/2019**

FAYETTEVILLE SHALE RELATED: **N**

FAYETTEVILLE SHALE VIOLATIONS: **N**

INSPECTION PARTICIPANTS

NAME/TITLE/PHONE/FAX/EMAIL/ETC.:
Randy Evans/EHS Manager/870-962-3206/Randy.Evans@canfor.com
Amanda Gallagher/GBMc Environmental Engineer/501-847-7077/agallagher@gbmcassoc.com
Tobin Fulmer/ADEQ D8 Water Inspector

AREA EVALUATIONS

(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)

S	PERMIT	N	FLOW MEASUREMENT	N	STORMWATER
N	RECORDS/REPORTS	N	LABORATORY	N	FACILITY SITE REVIEW
N	OPERATION & MAINTENANCE	N	EFFLUENT/RECEIVING WATER	N	SELF-MONITORING PROGRAM
N	SAMPLING	N	SLUDGE HANDLING/DISPOSAL	N	PRETREATMENT
**	OTHER:				

SUMMARY OF FINDINGS

No violations noted during inspection.

GENERAL COMMENTS

On February 6, 2017, I completed an inspection on the permit ARG550540. In attendance for the inspection was Randy Evans, HSE Manager, and Amanda Gallagher, Environmental Engineer with GBMc. The system design is planned to be a Norweco Singular 960 Aerobic Treatment Unit with chlorination. The system has not been installed yet. See Figure 1 for the location of installation.

The system is being installed as a corrective action to Fecal Coliform Bacteria (FCB) violations reported at Outfall 001 (for permit AR0047384) that discharges wet deck water runoff, stormwater runoff, kiln condensate, make-up water, and treated domestic wastewater. The treated domestic wastewater is from several septic systems on the facility property. After a site evaluation, it was determined that the septic systems may not be operating efficiently and producing FCB violations at Outfall 001. During the inspection, Ms. Gallagher stated that the discharge location for the Norweco unit would be discharged upstream of the sample point for Outfall 007, which is a permitted Industrial Stormwater outfall under permit ARR000977. Ms. Gallagher stated that the sample location for Outfall 007 would be moved to a location that is upstream of the discharge from the Norweco system so that the IGP is not violated by commingling sources of sampled stormwater.

INSPECTOR'S SIGNATURE:  Michael Young

DATE: 2/7/2017

SUPERVISOR'S SIGNATURE:  Kerri McCabe

DATE: 3/3/2017

Figure 1. Overview of the anticipated location of the treatment unit and associated discharge.

