



July 27, 2017

Mr. Fred Megginson
Reynolds Metals Company
Gum Springs Hwy 67 South
500 E. Reynolds Road
Arkadelphia, AR 71923-8817

RE: Quarterly Inspection conducted on July 11, 2017
AFIN 10-00004
Permit Number 0262-S

Dear Mr. Megginson:

The Arkansas Department of Environmental Quality – Office of Land Resources (ADEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were noted at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or greenwood@adeq.state.ar.us.

Sincerely,

A handwritten signature in black ink that reads "Matt Greenwood".

Matt Greenwood
Solid Waste Inspector
Office of Land Resources

Attachment

cc: Tammie J. Hynum, Acting Sr. Operations Manager, Office of Land Resources



Arkansas Department of Environmental Quality

Office of Land Resources -Solid Waste Management

Class 3 Landfill Inspection



Site Name	Reynolds Metals, Inc. (Alcoa)	County	Clark	AFIN	10-00004
Facility Address	2 miles east of I-30 on Hwy. 26 East.	Phone Number	870-245-2700	Permit Number	0262-S
Permittee Address	500 E. Reynolds Rd. Arkadelphia, AR 71923	E-Mail Address	Kent.thomas@alcoa.com	PDS #	098292
Date	07/11/17	Entry Time	0745	Exit Time	0845

Regulation 22 – Operational Standards

Category 1

	Regulation	Item Description	Comments
	510(l)	Adequate employee facilities	
	520(a)(b)	Record keeping meets requirements specified by regulations	
	516	Access requirements	
	510(j)	Adequate provisions for backup equipment	
	520(c)	Waste receipt records, ticket system maintained	
	510(k)	Telephone system & written emergency response plan on site	
	522(a)	Annual compliance inspection by register professional engineer	
	521	Facility implements operating plan and narrative	
	520(a)(4)	Leachate disposal/recirculation records	
	701, 520(a)(2)	Special waste disposal and procedures records	

Category 2

	Regulation	Item Description	Comments
	510(a)	Operations in accordance with permit documents	No waste is being placed in the landfill.
	516(c)	Adequate all weather operational roads	
	510(c)	Smallest practical area, unloading supervised, single working face	
	510(e)	Salvage operations meet approved conditions	
	510(f)(l)	Scavenging of waste prohibited	
	510(o)	Proper wet weather repairs	
	510(b)	Operations by licensed on-site personnel at all times	
	510(d)	Waste spread and compacted as unloaded	
	510(g)	Litter control provisions maintained	
	513(a)	Disease vectors controlled	

Category 2 (continued)


Regulation	Item Description	Comments
518	Surface water controls	
510(h)(l)	Contouring prevents surface water flowing into or through waste	
517(a)(b)	Run-on/off control system present and adequate	
510(h)(2)	Surface water control prevents off-site sediment accumulation	
510(h)(i)	Adequate maintenance of intermediate/final cover vegetation	
514	Gas monitoring program	
510(n)	Leachate leaks or evidence of leachate seepage	
526	Survey controls	
529	Leachate collection system	
519	Liquid restrictions	

Category 3

Regulation	Item Description	Comments
511	Implementation of hazardous/unauthorized waste exclusion plan	
512(a)(c)	Satisfactory daily/alternative cover	
512(b)	Satisfactory intermediate cover	
515(b), 510(f)(4)	Open burning prohibited	
518	Cause discharge/leachate discharge leaving landfill	
510(f)(3), 518(a)(4)	Depositing waste in standing water prohibited	
510(n)	Erosion or other cover defects resulting in exposed refuse	
309(c)	Overfill/off lined area	

Regulation 22 - Records

520(a)(8), 204(b)	Date of last groundwater monitoring report	May 2017	Site Conditions	Dry
522	Date of last engineering report	July 2017	Weather Conditions	Sunny
528	Liner construction in progress <input type="checkbox"/> Yes/No <input type="checkbox"/> No	Notice of liner construction <input type="checkbox"/> Yes/No <input type="checkbox"/> No	Third part CQA on-site during construction	<input type="checkbox"/> Yes/No <input type="checkbox"/> No
511	Date of last random inspection for unauthorized waste	N/A	Total # for month	
514, 520(a)(3)	Date of last quarterly methane monitoring	N/A	Detection level	514 Explosive gas records current? <input type="checkbox"/> Yes/No <input type="checkbox"/> No
701, 520(a)(2)	Date of last special waste received	N/A	Disposal location	
520(c)	Previous quarter waste received	None	Tons	0.0 Tons
527	Surface water DMR records current? <input type="checkbox"/> Yes/No <input type="checkbox"/> Yes			

Operator Name & Number	Not in operation		Signature of Inspector				
Exit Interview Conducted with	Kent Thomas	Method	On-Site	Date	07/11/17	Time	0830

Arkansas Department of Environmental Quality (ADEQ)
Official Photograph Sheet

Location	Reynolds (Alcoa)				Permit	0262-S	AFIN	10-00004
Photographer	Matt Greenwood			<i>MG</i>	Witness	Kent Thomas		
Photo #	1	Of	2		Date	07/11/17	Time	0832
Description	North Slope looking southwest							
								
Location	Reynolds (Alcoa)				Permit	0262-S	AFIN	10-00004
Photographer	Matt Greenwood			<i>MG</i>	Witness	Kent Thomas		
Photo #	2	Of	2		Date	07/11/17	Time	0830
Description	South slope looking west							
								

Inspector Signature:

Matt Greenwood