Inspection Report: Bekaert Steel Corporation, AFIN: 04-00155, Permit #: AR0043397

	V DEO	WATER DIVISION INSPECTION REPORT								
ADEQ		AFIN: 04-00155 PE		ERMIT #: AR0043397			DATE: 9/7/2017			
A R K A N S A S Department of Environmental Quality			DUNTY: 04 Bento	n PDS #: 099		#: 099508		MEDIA: WN		
			S LAT: 36.35519	1 LONG: -94.161933 LOCATION:			Gener	General Area		
	FACILITY INFORMAT	INSPECTION INFORMATION								
Bekaert Steel Corporation			FACILITY TYPE: INSPECTOR ID#: 2 - Industrial 83321 S - State							
LOCATION:			FACILITY EVALUATION RATING: INSPECTION TYPE:							
1 Bekaert Drive			5 - Satisfactory Industrial User							
Rogers				DATE(S): ENTRY TIME: EXIT TIME: PERMIT EFFECTIVE DATE: 9/7/2017 09:20 10:02 2/4/2006						
	RESPONSIBLE OFFIC	3/1/2006 PERMIT EXPIRATION DATE:								
	:: / TITLE					2/28/2011				
Mr. Earl Rausch / Utility Superintendent				FAYETTEVILLE SHALE RELATED: N						
City of Rogers				FAYETTEVILLE SHALE VIOLATIONS: N						
	NG ADDRESS: D. Box 338			INSPECTION PARTICIPANTS						
CITY, STATE, ZIP:				NAME/TITLE/PHONE/FAX/EMAIL/ETC.:						
Rogers AR 72757 PHONE & EXT: / FAX:				Paul Burns, Pretreatment Coordinator, RWU Garrett Grimes, ADEQ District Field Inspector						
	9-936-3425 /			Ankush Nautiyal, ADEQ District Field Inspector						
EMAI				7						
	rIrausch@rwu.org ONTACTED DURING INSPECTION:	No								
	DIVIACIED DOINING INSPECTIONS	140	AREA EVA	LUATIONS						
		atisfac	tory, M=Marginal, U=Unsati	isfactory, N=Not Applicable						
**	PERMIT	**	FLOW MEASUR	REMENT	*	STORMWATER STORMWATER				
**	RECORDS/REPORTS OPERATION & MAINTENANCE	**	LABORATORY	CEIVING WATER	** FACILITY SITE REVIEW					
**	SAMPLING	**		LING/DISPOSAL	*	SELI -IVIC	SELF-MONITORING PROGRAM PRETREATMENT			
**	OTHER:		SLODGE HAND	ANDLINO, DIOF COAL FIVE I NEATIVIENT						
	<u> </u>		SUMMARY C	F FINDINGS						
Mr	. Bland was very knowledgeable o	of th	e processes and	treatment plant	. We	were not ab	le to v	isit the inside of		
the production facility but he did offer for us to revisit the facility at our earliest convenience.										
GENERAL COMMENTS										
Photographs of the facility's treatment system is included in the Pretreatment Compliance Inspection report.										
INS	SPECTOR'S SIGNATURE: Click te	xt to l	eft to add signature	-Inspector Name			DA	DATE:		
SUPERVISOR'S SIGNATURE: Jason Bolenbaugh DATE: 10/9/2017										
SU	PERVISOR'S SIGNATURE:	DA	TE: 10/9/2017							

Inspection Report: **Bekaert Steel Corporation**, AFIN: **04-00155**, Permit #: **AR0043397 POTW Pretreatment Program**

Industrial Site Visit

Name	of Industry:	Bekaert Steel Corporation				
Indust	ry Contacts:	Rodney Bland				
Туре	of Industry:	Metal Finisher				
Date o	of Visit: Septen	nber 7, 2017				
1.	Significant in	dustrial user:	X	Yes	No	N/A
2.	Pretreatment	equipment or procedures?	X	Yes	No	N/A
3.	Pretreatment and operation	equipment maintained nal?	х	Yes	No	N/A
4.	Hazardous wa	aste generated or stored?	X	Yes	No	N/A
5.	Proper solid	waste disposal?	X	Yes	No	N/A
6.	Solvent mana	gement/TTO control?	X	Yes	No	N/A
7.	Suitable sam	pling location?	X	Yes	No	N/A
8.	Appropriate s procedures/e	self-monitoring quipment?	X	Yes	No	N/A
9.	Adequate spi	II prevention?	X	Yes	No	N/A
10.	Industry fami and requirem	liar with limits ents?	x	Yes	No	N/A