

 A R K A N S A S Department of Environmental Quality		WATER DIVISION INSPECTION REPORT				
		AFIN: 05-00054		PERMIT #: AR0034321		DATE: 9/10/2018
		COUNTY: 05 Boone		PDS #: 104987		MEDIA: WN
		GPS LAT: 36.240879 LONG: -93.080843 LOCATION: Entrance				
FACILITY INFORMATION			INSPECTION INFORMATION			
NAME: Anchor Die Cast LOCATION: 300 N. Industrial Park Road CITY: Harrison			FACILITY TYPE: 2 - Industrial		INSPECTOR ID#: 36537 S - State	
RESPONSIBLE OFFICIAL NAME / TITLE: Katheryn Yeager / Wastewater Manager COMPANY: City of Harrison MAILING ADDRESS: P.O. Box 1715 Spring St. CITY, STATE, ZIP: Harrison AR 72601 PHONE & EXT. / FAX: 870-741-5022 / EMAIL: katheryn.yeager@cityofharrison.com CONTACTED DURING INSPECTION: No			FACILITY EVALUATION RATING: 3 - Satisfactory		INSPECTION TYPE: Industrial User	
			DATE(S): 9/10/2018	ENTRY TIME: 13:00	EXIT TIME: 13:30	PERMIT EFFECTIVE DATE: 10/1/2007 PERMIT EXPIRATION DATE: 9/30/2012
			FAYETTEVILLE SHALE RELATED: N			
			FAYETTEVILLE SHALE VIOLATIONS: N			
			INSPECTION PARTICIPANTS			
			NAME/TITLE/PHONE/FAX/EMAIL/ETC.: Randy Reese, City of Harrison Pretreatment Coordinator, randy.reese@cityofharrison.com; Skyler Schlick, ADEQ Inspector, Schlicks@adeq.state.ar.us; Scott Lusk, Anchor Die Cast			
AREA EVALUATIONS						
(S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)						
**	PERMIT	**	FLOW MEASUREMENT	**	STORMWATER	
**	RECORDS/REPORTS	**	LABORATORY	**	FACILITY SITE REVIEW	
**	OPERATION & MAINTENANCE	**	EFFLUENT/RECEIVING WATER	**	SELF-MONITORING PROGRAM	
**	SAMPLING	**	SLUDGE HANDLING/DISPOSAL	**	PRETREATMENT	
S	OTHER: IU					
SUMMARY OF FINDINGS						
No violations were noted relative to City of Harrison's Pretreatment Program during the inspection.						
GENERAL COMMENTS						
Anchor Die Cast is classified as both Significant Industrial User (SIU) and categorical industry discharging to City of Harrison's POTW. The facility produces and paints aluminum and galvanized steel hardware for chain link fence. Pretreatment of wastewater involves holding tank, pH adjustment, flocculation, clarifier, and sludge press. Water is discharged to the POTW collection system; solids are disposed to dumpster as needed.						
INSPECTOR'S SIGNATURE: 				DATE: 9/24/2018		
SUPERVISOR'S SIGNATURE: 				DATE: 10/18/2018		

POTW Pretreatment Program

Industrial Site Visit

Name of Industry: Anchor Die Cast

Industry Contacts: Scott Lusk/Plant Manager, Todd Allen, Operator

Type of Industry: Aluminum Die Casting

Date of Visit: September 10, 2018

- | | | | | |
|-----|--|---|-----------------------------|------------------------------|
| 1. | Significant industrial user: | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 2. | Pretreatment equipment or procedures? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 3. | Pretreatment equipment maintained and operational? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 4. | Hazardous waste generated or stored? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 5. | Proper solid waste disposal? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 6. | Solvent management/TTO control? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 7. | Suitable sampling location? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 8. | Appropriate self-monitoring procedures/equipment? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 9. | Adequate spill prevention? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |
| 10. | Industry familiar with limits and requirements? | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No | <input type="checkbox"/> N/A |

Additional Comments: Facility representatives were helpful and aware of permit requirements. The operator was knowledgeable on the workings of the pretreatment components.

Visit Conducted By: Amy Beck, Skylar Schlick, Randy Reese

Date of Report: September 24, 2018

Water Division Photographic Evidence Sheet

Location:	Anchor Die Cast				
Photographer:	Amy Beck	Date:	September 10, 2018	Time:	1308
Witness:	Skylar Schlick	Photo #:	1		
Description:	Water in holding tank.				



Photographer:	Amy Beck	Date:	September 10, 2018	Time:	1320
Witness:	Skylar Schlick	Photo #:	2		
Description:	Mixing tank				



Water Division Photographic Evidence Sheet

Location:	Anchor Die Cast				
Photographer:	Amy Beck	Date:	September 10, 2018	Time:	1321
Witness:	Skylar Schlick			Photo #:	3
Description:	Clarifier				



Photographer:	Amy Beck	Date:	September 10, 2018	Time:	1319
Witness:	Skylar Schlick			Photo #:	4
Description:	Sludge press				

