

August 12, 2019

Mr. Fred Megginson Reynolds Metals Company Gum Springs Hwy 67 South 500 E. Reynolds Road Arkadelphia, AR 71923-8817

RE: Quarterly Inspection conducted on July 23, 2019

**AFIN 10-00004** 

Permit Number 0262-S

Dear Mr. Megginson:

The Arkansas Department of Environmental Quality Office of Land Resources (ADEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 <u>et seq.</u>), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 777-7585 or <a href="mailto:greenwood@adeq.state.ar.us">greenwood@adeq.state.ar.us</a>.

Sincerely,

Matt Greenwood Solid Waste Inspector

Mattle Lucas

Office of Land Resources

Enclosure

cc: David Witherow P.E., Senior Manager, Office of Land Resources



## Arkansas Department of Environmental Quality Office of Land Resources -Solid Waste Management Class 3 Landfill Inspection



Site Name	Reynolds Metals, Inc. (Alcoa)	County	Clark	AFIN	10-00004	
<b>Facility Address</b>	2 miles east of I-30 on Hwy. 26 East.	Phone Number	870-245-2700	Permit Number	0262-S	
<b>Permittee Address</b>	500 E. Reynolds Rd. Arkadelphia, AR 71923	E-Mail Address	Kent.thomas@alcoa.com		PDS#	108852
Date	07/23/19	<b>Entry Time</b>	0830	Exit Time	0945	

## **Regulation 22 – Operational Standards**

## **Category 1**

Regulation	Item Description	Comments
510(l)	Adequate employee facilities	
520(a)(b)	Record keeping meets requirements specified by regulations	
516	Access requirements	
510(j)	Adequate provisions for backup equipment	
520(c)	Waste receipt records, ticket system maintained	
510(k)	Telephone system & written emergency response plan on site	
522(a)	Annual compliance inspection by register professional engineer	
521	Facility implements operating plan and narrative	
520(a)(4)	Leachate disposal/recirculation records	
701, 520(a)(2)	Special waste disposal and procedures records	

## **Category 2**

Regulation	Item Description	Comments
510(a)	Operations in accordance with permit documents	No waste is being placed in the landfill.
516(c)	Adequate all weather operational roads	
510(c)	Smallest practical area, unloading supervised, single working face	
510(e)	Salvage operations meet approved conditions	
510(f)(l)	Scavenging of waste prohibited	
510(o)	Proper wet weather repairs	
510(b)	Operations by licensed on-site personnel at all times	
510(d)	Waste spread and compacted as unloaded	
510(g)	Litter control provisions maintained	
513(a)	Disease vectors controlled	

	Category 2 (continued)												
	Regulation		Item Description				Comments						
	518		Surface water controls										
	510(h)(l)	Contourin	g prevents surface water fl	owing into or thr	ough waste								
	517(a)(b)	Run-on/of	f control system present an	d adequate									
	510(h)(2)	Surface wa	ater control prevents off-sit	te sediment accun	nulation								
	510(h)(i)	Adequate	Adequate maintenance of intermediate/final cover vegeta									_	
	514	Gas monit	Gas monitoring program									_	
	510(n)	Leachate l	eaks or evidence of leachat	e seepage									
	526	Survey con	ntrols										
	529	Leachate of	Leachate collection system										
	519	Liquid res	Liquid restrictions										
	Category 3												
	Regulation		Item Description						Cor	nments		_	
	511	Implemen	Implementation of hazardous/unauthorized waste exc									_	
	512(a)(c)	Satisfactor	Satisfactory daily/alternative cover										
	512(b)	Satisfactor	Satisfactory intermediate cover										
	515(b), 510(f)(4	Open burn	Open burning prohibited									_	
	518	Cause disc	Cause discharge/leachate discharge leaving landfill										
	510(f)(3), 518(a)(4)	) Depositing	Depositing waste in standing water prohibited										
	510(n)	Erosion or	Erosion or other cover defects resulting in exposed refuse										
	309(c)	Overfill/of	Overfill/off lined area										
	Regulation 22 - Records												
520(a)(8), 204(b) Date of last groundwater monitoring report			Feb 2019			Site Conditions		wet					
	522		ate of last engineering report		June 2019		Weather C		Sunny				
	528		ction in progress Yes/N	110	Notice of lin	er coi		No 7	Third part (	CQA on-site during construc	tion Yes/No No		
-	511 514, 520(a)(3)		ndom inspection for unaut arterly methane monitorin		N/A N/A		Total # for month Detection level		514	Explosive gas records curr	rent? Yes/No No		
			ecial waste received	ig .	N/A N/A		Disposal location		314	Explosive gas records curr	ent: res/10 No		
			ter waste received		None		Tons	0.0 Tons					
527 Surface water DMR records current? Yes/No Yes			- 1,022	L	10115								
Operator Name & Number Not in operation				Sign	nature of Inspector	•	Nett	Thereno 1	-				
Exit Interview Condu		ducted with	Kent Thomas		Method	On-s	site	Date	07/23/19	Time	0935		