Blue, Karen

From: Sent: To: Cc: Subject: Patterson, Slade <SPatterson2@republicservices.com> Friday, January 24, 2020 9:51 AM Davenport, Kimberly Lockley, Heath AFIN 60-00565 Permit 0151-S1-R4

Kimberly,

Regarding your recent inspection at Model Fill:

Due to weather, I have had the south slope partially seeded and hayed to correct the bare areas on the landfill as seen in photos #3 and #5. Once the weather clears, we will continue with the rest to prevent further erosion and settling on Phase 3.

Please let me know if you have any questions,

Slade Patterson Environmental Manager

7111 Old Millington Rd, Millington, TN 38053 e <u>spatterson2@republicservices.com</u> o 901-873-8334 c 901-619-0162





Rec'd Digitally	
AFIN: 60-00565	
PMT#: 0151-S1-R4	
RECEIVED By Karen Blue at 1:09 pm, Jan 27, 2020	S W
DOC ID#: 77594	M N
TO:_RH>FILE <kmb< td=""><td>D</td></kmb<>	D

We'll handle it from here."