

# ARKANSAS

## ENERGY & ENVIRONMENT

## ENVIRONMENTAL QUALITY

March 6, 2020

Mr. Alan Thomas  
Green Bay Packaging, Inc.  
338 Highway 113  
Morrilton, AR 72110

**RE: Quarterly Inspection conducted on February 28, 2020**  
**AFIN 15-00001**  
**Permit Number 0284-S3N**

Dear Mr. Thomas:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 682-0586 or [davenport@adeq.state.ar.us](mailto:davenport@adeq.state.ar.us)

Sincerely,



Kim Davenport  
Solid Waste Inspector  
Office of Land Resources

Enclosure

cc: David Witherow P.E., Senior Manager, Office of Land Resources

**Division of Environmental Quality**  
**Office of Land Resources - Solid Waste Management**  
**Class 3 Landfill Inspection**



<b>Site Name</b>	Green Bay Packaging, Inc.	<b>County</b>	Conway	<b>AFIN</b>	15-00001
<b>Facility Address</b>	338 Highway 113, Morrilton, AR 72110	<b>Phone Number</b>	501-334-9289	<b>Permit Number</b>	0284-S3N
<b>Permittee Address</b>	338 Highway 113, Morrilton, AR 72110	<b>E-Mail Address</b>	hvae@gbp.com	<b>PDS #</b>	111297
<b>Date</b>	2/28/2020	<b>Entry Time</b>	1335	<b>Exit Time</b>	1413

**Regulation 22 – Operational Standards**

**Category 1**

	<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
	510(l)	Adequate employee facilities	
	520(a)(b)	Record keeping meets requirements specified by regulations	
	516	Access requirements	
	510(j)	Adequate provisions for backup equipment	
	520(c)	Waste receipt records, ticket system maintained	
	510(k)	Telephone system & written emergency response plan on site	
	522(a)	Annual compliance inspection by register professional engineer	
	521	Facility implements operating plan and narrative	
	520(a)(4)	Leachate disposal/recirculation records	
	701, 520(a)(2)	Special waste disposal and procedures records	

**Category 2**

	<b>Regulation</b>	<b>Item Description</b>	<b>Comments</b>
	510(a)	Operations in accordance with permit documents	
	516(c)	Adequate all weather operational roads	
	510(c)	Smallest practical area, unloading supervised, single working face	
	510(e)	Salvage operations meet approved conditions	
	510(f)(l)	Scavenging of waste prohibited	
	510(o)	Proper wet weather repairs	
	510(b)	Operations by licensed on-site personnel at all times	
	510(d)	Waste spread and compacted as unloaded	
	510(g)	Litter control provisions maintained	
	513(a)	Disease vectors controlled	

## Category 2 (continued)


Regulation	Item Description	Comments
518	Surface water controls	
510(h)(l)	Contouring prevents surface water flowing into or through waste	
517(a)(b)	Run-on/off control system present and adequate	
510(h)(2)	Surface water control prevents off-site sediment accumulation	
510(h)(i)	Adequate maintenance of intermediate/final cover vegetation	
514	Gas monitoring program	
510(n)	Leachate leaks or evidence of leachate seepage	
526	Survey controls	
529	Leachate collection system	
519	Liquid restrictions	

## Category 3

Regulation	Item Description	Comments
511	Implementation of hazardous/unauthorized waste exclusion plan	
512(a)(c)	Satisfactory daily/alternative cover	
512(b)	Satisfactory intermediate cover	
515(b), 510(f)(4)	Open burning prohibited	
518	Cause discharge/leachate discharge leaving landfill	
510(f)(3), 518(a)(4)	Depositing waste in standing water prohibited	
510(n)	Erosion or other cover defects resulting in exposed refuse	
309(c )	Overflow/off lined area	

## Regulation 22 - Records

520(a)(8), 204(b)	Date of last groundwater monitoring report			2/12/2020		Site Conditions		Dry		
522	Date of last engineering report			6/28/2020		Weather Conditions		Sunny		
528	Liner construction in progress	Yes/No	No	Notice of liner construction	Yes/No	No	Third part CQA on-site during construction		Yes/No	N/A
511	Date of last random inspection for unauthorized waste			N/A	Total # for month					
514, 520(a)(3)	Date of last quarterly methane monitoring			N/A	Detection level		514	Explosive gas records current?	Yes/No	
701, 520(a)(2)	Date of last special waste received			N/A	Disposal location					
520(c)	Previous quarter waste received			60,485.90	Tons					
527	Surface water DMR records current?	Yes/No								

Operator Name & Number	Harrison Rae003821		Signature of Inspector				
Exit Interview Conducted with	H. Rae	Method	In-person	Date	2/28/2020	Time	1400

# Division of Environmental Quality Official Photograph Sheet

<b>Location</b>	Green Bay Packaging, Inc.				<b>Permit</b>	0284-S3N	<b>AFIN</b>	15-00001
<b>Photographer</b>	Kim Davenport, Inspector				<b>Witness</b>	N/A		
<b>Photo #</b>	1	<b>Of</b>	1		<b>Date</b>	2/28/2020	<b>Time</b>	1354
<b>Description</b>	An overview of the landfill at Cell 4 and Cell 5 observed, looking north.							
		