

	<b>OFFICE OF WATER QUALITY INSPECTION REPORT</b>		
	AFIN: <b>61-00055</b>	PERMIT #: <b>AR0034835</b>	DATE: <b>4/20/2020</b>
	COUNTY: <b>61 Randolph</b>	PDS #: <b>112106</b>	MEDIA: <b>WN</b>
	GPS LAT: <b>36.25771</b> LONG: <b>-90.971666</b> LOCATION: <b>General Area</b>		
<b>FACILITY INFORMATION</b>		<b>INSPECTION INFORMATION</b>	
NAME: <b>City of Pocahontas</b> LOCATION: <b>Marr Creek aerial sewage line crossing</b> CITY: <b>Pocahontas</b>		FACILITY TYPE: <b>1 - Municipal</b> INSPECTOR ID#: <b>93162 S - State</b> FACILITY EVALUATION RATING: <b>2 - Marginal</b> INSPECTION TYPE: <b>Reconnaissance</b>	
<b>RESPONSIBLE OFFICIAL</b>		DATE(S): <b>4/20/2020</b> ENTRY TIME: <b>14:40</b> EXIT TIME: <b>15:00</b>	PERMIT EFFECTIVE DATE: <b>5/1/2019</b> PERMIT EXPIRATION DATE: <b>4/30/2024</b>
NAME: / TITLE <b>Bruce Brodell / Manager</b> COMPANY: <b>City of Pocahontas</b> MAILING ADDRESS: <b>207 Highway 67 South</b> CITY, STATE, ZIP: <b>Pocahontas AR 72455</b> PHONE & EXT: / FAX: <b>870-892-3222 /</b> EMAIL: <b>bbrodell@suddenlinkmail.com</b>		FAYETTEVILLE SHALE RELATED: <b>N</b> FAYETTEVILLE SHALE VIOLATIONS: <b>N</b>	
CONTACTED DURING INSPECTION: <b>No</b>		<b>INSPECTION PARTICIPANTS</b>	
		NAME/TITLE/PHONE/FAX/EMAIL/ETC.: <b>None</b>	
<b>AREA EVALUATIONS</b> (S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)			
<b>N</b>	PERMIT	<b>N</b>	FLOW MEASUREMENT
<b>N</b>	RECORDS/REPORTS	<b>N</b>	LABORATORY
<b>N</b>	OPERATION & MAINTENANCE	<b>N</b>	EFFLUENT/RECEIVING WATER
<b>N</b>	SAMPLING	<b>N</b>	SLUDGE HANDLING/DISPOSAL
<b>N</b>	OTHER:	<b>N</b>	STORMWATER
			FACILITY SITE REVIEW
			SELF-MONITORING PROGRAM
			PRETREATMENT
<b>SUMMARY OF FINDINGS</b>			
No violations were noted at the time of this inspection. The leakage noted during the previous inspection had ceased.			
<b>GENERAL COMMENTS</b>			
INSPECTOR'S SIGNATURE: 		DATE: <b>4/22/2020</b>	
SUPERVISOR'S SIGNATURE: 		DATE: <b>6/4/2020</b>	

**Office of Water Quality Photographic Evidence Sheet**

Location:	<b>City of Pocahontas</b>		
Photographer:	<b>Wes Klasky</b>	Date:	<b>4/20/2020</b>
Witness:	<b>None</b>	Time:	<b>14:49</b>
		Photo #:	<b>1</b>
Description:	<b>View of sewer line no longer leaking, taken from the North side of Marr Creek.</b>		



Photographer:	<b>Wes Klasky</b>	Date:	<b>4/20/2020</b>
Witness:	<b>None</b>	Time:	<b>14:49</b>
		Photo #:	<b>2</b>
Description:	<b>View from North side of Marr Creek of aerial crossing, seepage is not occurring at the time of this visit.</b>		





Figure 1. Google Earth map showing location of sewer line aerial crossing.

