

	OFFICE OF WATER QUALITY INSPECTION REPORT				
	AFIN: 61-00055	PERMIT #: AR0034835	DATE: 4/17/2020		
	COUNTY: 61 Randolph	PDS #: 112107	MEDIA: WN		
	GPS LAT: 36.25771 LONG: -90.971666 LOCATION: General Area				
FACILITY INFORMATION		INSPECTION INFORMATION			
NAME: City of Pocahontas LOCATION: Marr Creek aerial sewage line crossing CITY: Pocahontas		FACILITY TYPE: 1 - Municipal INSPECTOR ID#: 93162 S - State FACILITY EVALUATION RATING: 2 - Marginal INSPECTION TYPE: Reconnaissance			
RESPONSIBLE OFFICIAL		DATE(S): 4/17/2020 ENTRY TIME: 11:30 EXIT TIME: 12:00 PERMIT EFFECTIVE DATE: 5/1/2019 PERMIT EXPIRATION DATE: 4/30/2024			
NAME: / TITLE Bruce Brodell / Manager COMPANY: City of Pocahontas MAILING ADDRESS: 207 Highway 67 South CITY, STATE, ZIP: Pocahontas AR 72455 PHONE & EXT: / FAX: 870-892-3222 / EMAIL: bbrodell@suddenlinkmail.com		FAYETTEVILLE SHALE RELATED: N FAYETTEVILLE SHALE VIOLATIONS: N			
CONTACTED DURING INSPECTION: No		INSPECTION PARTICIPANTS			
		NAME/TITLE/PHONE/FAX/EMAIL/ETC.: None			
AREA EVALUATIONS (S=Satisfactory, M=Marginal, U=Unsatisfactory, N=Not Applicable/Evaluated)					
N	PERMIT	N	FLOW MEASUREMENT	N	STORMWATER
N	RECORDS/REPORTS	N	LABORATORY	N	FACILITY SITE REVIEW
M	OPERATION & MAINTENANCE	N	EFFLUENT/RECEIVING WATER	N	SELF-MONITORING PROGRAM
N	SAMPLING	N	SLUDGE HANDLING/DISPOSAL	N	PRETREATMENT
N	OTHER:				
SUMMARY OF FINDINGS					
Visited this area to investigate and observed a large trickle of wastewater leaking into Marr Creek from cracks on top of the aerial sewer main crossing. The city was contacted by Inspector Sarah Frasher and Supervisor Brent Walker who informed them of the need to take correct action and report the SSO as required by the permit.					
GENERAL COMMENTS					
This reconnaissance inspection was triggered by complaint of a continuous release of sewage emanating from a cracked aerial sewer main crossing Marr Creek immediately downstream (east) of the Hwy. 67 bridge across Marr Creek (south end of Black River Overlook Park).					
INSPECTOR'S SIGNATURE: 				DATE: 4/22/2020	
SUPERVISOR'S SIGNATURE: 				DATE: 6/4/2020	

Office of Water Quality Photographic Evidence Sheet

Location:	City of Pocahontas		
Photographer:	Wes Klasky	Date:	4/17/2020
Witness:	None	Time:	11:35
		Photo #:	1
Description:	View of sewer line leak from the South side of Marr Creek.		



Photographer:	Wes Klasky	Date:	4/17/2020
Witness:	None	Time:	11:44
		Photo #:	2
Description:	View from North side of Marr Creek of aerial crossing and the seepage.		



Office of Water Quality Photographic Evidence Sheet

Location:	City of Pocahontas				
Photographer:	Wes Klasky	Date:	4/17/2020	Time:	11:45
Witness:	None	Photo #:	3		
Description:	Close up view of one of the seepage spots.				



Photographer:	Wes Klasky	Date:	4/17/2020	Time:	11:54
Witness:	None	Photo #:	4		
Description:	View from the side of the structure showing active release of sewage to Marr Creek.				



Figure 1. Google Earth map showing location of leaking sewer line.

