

ARKANSAS

ENERGY & ENVIRONMENT

ENVIRONMENTAL QUALITY

June 22, 2020

The Honorable Woody Wheelless
Crittenden County Judge
100 Court Street
Marion, AR 72364


RE: Quarterly Inspection conducted on June 15, 2020
AFIN 18-00094
Permit Number 0245-S1-R2

Dear Judge Wheelless:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (870) 935-7221 or bakert@adeq.state.ar.us.

Sincerely,



Tobin Baker
Solid Waste Inspector
Office of Land Resources

Enclosure

cc: David Witherow P.E., Senior Manager, Office of Land Resources

Division of Environmental Quality
Office of Land Resources - Solid Waste Management
Class 1 Landfill Inspection



Site Name	Crittenden County Class 1	County	Crittenden	AFIN	18-00094
Facility Address	1299 Khun Rd. West Memphis, AR 72301	Phone Number	LF: 870-732-4290 Off: 870-732-6580	Permit Number	0245-S1-R2
Permittee Address	100 Court Street Marion, AR 72364	E-Mail Address	judgewheeless@crittco.com		PDS # 112305
Date	6/15/2020	Entry Time	1020	Exit Time	1152


Regulation 22 – Operational Standards

Category 1

Regulation	Item Description	Comments
411(l)	Adequate employee facilities	
421(a)(b)	Record keeping meets requirements specified by regulations	
417	Access requirements	
411(j)	Adequate provisions for backup equipment	
421(d)	Waste receipt records, ticket system maintained	
411(k)	Telephone system & written emergency response plan on site	
423(b)	Annual compliance inspection by registered professional engineer	
422	Facility implements operating plan and narrative	
421(f)	Leachate disposal/recirculation records	
421(g),701	Special waste disposal and procedures records	

Category 2

Regulation	Item Description	Comments
411(a)	Operations in accordance with permit documents	
417(c)	Adequate all weather operational roads	
411(c)	Smallest practical area, unloading supervised, single working face	
411(e)	Salvage operations meet approved conditions	
411(f)(1)	Scavenging of waste prohibited	
411(p)	Proper wet weather repairs	
411(b)	Operations by licensed on-site personnel at all times	
411(d)	Waste spread and compacted as unloaded	
411(g)	Litter control provisions maintained	
414(a)	Disease vectors controlled	

Category 2 (continued)														
Regulation	Item Description					Comments								
427	Surface Water Controls													
411(h)(1)	Contouring prevents surface water flowing into or through waste													
418(a)(b)	Run-on/off control system present and adequate													
411(h)(2)	Surface water control prevents off-site sediment accumulation													
411(i);427(f)	Adequate maintenance of intermediate/final cover vegetation													
415	Gas monitoring program													
411(o)	Leachate leaks or evidence of leachate seepage													
426	Survey controls													
429	Leachate collection system													
420	Liquid Restrictions													
Category 3														
Regulation	Item Description					Comments								
412	Implementation of hazardous/unauthorized waste exclusion plan													
413(a)(b)	Satisfactory daily/alternative cover													
413(c)	Satisfactory intermediate cover													
416(b),411(f)(4)	Open burning prohibited													
419	Cause discharge/leachate discharge leaving landfill													
411(f)(3),419(a)(4)	Depositing waste in standing water prohibited													
411(o)	Erosion or other cover defects resulting in exposed refuse													
309(c)	Overfill/Off lined area													
Regulation 22 - Records														
421(a)(8), 1203(k)	Date of last groundwater monitoring report			2/19/2020		Site Conditions		Dry						
423(b)	Date of last engineering report			2/7/2020		Weather Conditions		Sunny						
428	Liner construction in progress			Yes/No	No	Notice of liner construction		Yes/No	No	Third party CQA on-site during construction			Yes/No	No
412(a)	Date of last random inspection for unauthorized waste			6/12/2020		Total # for month		19						
415, 421(e)	Date of last quarterly methane monitoring			3/18/2020		Detection level		0	415(a)	Explosive gas records current?		Yes/No	Yes	
421(g),412(a)(2),701	Date of last special waste received			4/30/2020		Disposal location		Cell 4						
421(d)	Previous quarter waste received			17,965.31		Tons								
427(c)	Surface water DMR records current?			Yes/No	Yes									
Fayetteville Shale Related		Yes/No	No	Out of Compliance with Fayetteville Shale			Yes/No	No						
Operator Name & Number		Ed Jackson- 001217				Signature of Inspector								
Exit Interview Conducted with		Dallis Bugg		Method	On-site		Date	6/15/2020		Time	1145			

Division of Environmental Quality Official Photograph Sheet

Location	Crittenden County Class 1 Landfill				Permit	0245-S1-R2	AFIN	18-00094
Photographer	Tobin Baker, Inspector				Witness	N/A		
Photo #	1	Of	1		Date	6/15/2020	Time	1118
Description	Crittenden County Class 1 Landfill.							
								