



ARKANSAS

ENERGY & ENVIRONMENT

10/1/2021

Brandon Bradberry
Plant Manager
Entergy Independence SES
555 Point Ferry Road
Newark, AR 72562

RE: Inspection conducted on September 27, 2021
AFIN 32-00042
Permit Number 0200-S3N-R2

Dear Mr. Bradberry:

The Arkansas Division of Environmental Quality Office of Land Resources (DEQ) conducted a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Act (Arkansas Code, Annotated, § 8-6-201 *et seq.*), of 1971, as amended, the Arkansas Pollution Control & Ecology Commission Regulation 22 (Solid Waste Management), and the above-referenced permit. At the time of the inspection, no allegations of noncompliance were observed at your facility. A copy of the inspection report is attached.

If I can be of any further assistance, please do not hesitate to contact me at (501) 837-6909 or nortond@adeq.state.ar.us.

Sincerely,

A handwritten signature in cursive script that reads 'Darrell Norton'.

Darrell Norton
Solid Waste Inspector
5301 Northshore Drive, North Little Rock, AR 72118-5317

Enclosure

cc: Scott McWilliams, Senior Compliance Manager, Regulated Waste Operations



ARKANSAS
ENERGY & ENVIRONMENT

Division of Environmental Quality
Office of Land Resources - Solid Waste Management
Class 3 Landfill Inspection

Site Name	Entergy- Independence Plant	County	Independence	AFIN	32-00042
Facility Address	555 Point Ferry , Newark, AR 72562	Phone Number	870-799-8761 Entergy 870-799-3565	Permit Number	0200-S3N-R2
Permittee Address	555 Point Ferry , Newark, AR 72562	E-Mail Address	Awilso1@entergy.com	PDS #	117659
Date	9/27/2021	Entry Time	1044	Exit Time	1145

Regulation 22 – Operational Standards

Category 1

Regulation	Item Description	Comments
510(i)	Adequate employee facilities	
520(a)(b)	Record keeping meets requirements specified by regulations	
516	Access requirements	
510(j)	Adequate provisions for backup equipment	
520(c)	Waste receipt records, ticket system maintained	
510(k)	Telephone system & written emergency response plan on site	
522(a)	Annual compliance inspection by register professional engineer	
521	Facility implements operating plan and narrative	
520(a)(4)	Leachate disposal/recirculation records	
701, 520(a)(2)	Special waste disposal and procedures records	

Category 2

Regulation	Item Description	Comments
510(a)	Operations in accordance with permit documents	
516(c)	Adequate all weather operational roads	
510(c)	Smallest practical area, unloading supervised, single working face	
510(e)	Salvage operations meet approved conditions	
510(f)(l)	Scavenging of waste prohibited	
510(o)	Proper wet weather repairs	
510(b)	Operations by licensed on-site personnel at all times	
510(d)	Waste spread and compacted as unloaded	
510(g)	Litter control provisions maintained	
513(a)	Disease vectors controlled	

Category 2 (continued)


Regulation	Item Description	Comments
518	Surface water controls	
510(h)(1)	Contouring prevents surface water flowing into or through waste	
517(a)(b)	Run-on/off control system present and adequate	
510(h)(2)	Surface water control prevents off-site sediment accumulation	
510(h)(i)	Adequate maintenance of intermediate/final cover vegetation	
514	Gas monitoring program	
510(n)	Leachate leaks or evidence of leachate seepage	
526	Survey controls	
529	Leachate collection system	Leachate pump #2 controlled by west leachate panel observed in off position. Work request ordered in August 2021. Back-up provisions observed on-site if needed.
519	Liquid restrictions	

Category 3

Regulation	Item Description	Comments
511	Implementation of hazardous/unauthorized waste exclusion plan	
512(a)(c)	Satisfactory daily/alternative cover	
512(b)	Satisfactory intermediate cover	
515(b), 510(f)(4)	Open burning prohibited	
518	Cause discharge/leachate discharge leaving landfill	
510(f)(3), 518(a)(4)	Depositing waste in standing water prohibited	
510(n)	Erosion or other cover defects resulting in exposed refuse	
309(c)	Overfill/off lined area	

Regulation 22 - Records

520(a)(8), 204(b)	Date of last groundwater monitoring report	6/18/2021	Site Conditions	Dry
522	Date of last engineering report	6/15/2021 Revised 8/6/2021	Weather Conditions	sunny
528	Liner construction in progress <input type="checkbox"/> Yes/No <input type="checkbox"/> No	Notice of liner construction <input type="checkbox"/> Yes/No <input type="checkbox"/>	n/a	Third part CQA on-site during construction <input type="checkbox"/> Yes/No <input type="checkbox"/> n/a
511	Date of last random inspection for unauthorized waste	Daily	Total # for month	n/a
514, 520(a)(3)	Date of last quarterly methane monitoring	n/a	Detection level	n/a
701, 520(a)(2)	Date of last special waste received	n/a	Disposal location	n/a
520(c)	Previous quarter waste received	4801.04	Tons Q2 2021	
527	Surface water DMR records current? <input type="checkbox"/> Yes/No <input type="checkbox"/>			

Operator Name & Number	Anthony Wilson 001442	Signature of Inspector			
Exit Interview Conducted with	Anthony Wilson	Method	In person	Date	9/27/2021
				Time	1137

Division of Environmental Quality Official Photograph Sheet

Location	Entergy-Independence Plant			Permit	0200-S3N-R2	AFIN	32-00042
Photographer	Darrell Norton , Inspector		<i>DW</i>	Witness	Anthony Wilson, Entergy		
Photo #	1	Of	2	Date	9/27/2021	Time	1102
Description	A view of slope stabilization recently performed on Cells 12 & 14..						
							
Location	Entergy-Independence Plant			Permit	0200-S3N-R2	AFIN	32-00042
Photographer	Darrell Norton, Inspector		<i>DW</i>	Witness	Anthony Wilson, Entergy		
Photo #	2	Of	2	Date	9/27/2021	Time	1103
Description	A view of stockpiled material near the working face.						
							